

INS. CASE OWNER:

CC 4, ASM

1900

5161

Aga39

LKK:
IDAC:

105378

Surveyor:

DOI:

Date / Time:

21/3/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

Admin.

Email ☒ Call ☐

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS 7100.00

(6 days) Reduction: 61615.65% 70

FINAL SETTLEMENT

Date/Time:

Confirm with:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.: 27

Repair Cost:

SS 7,597

Loss of Rental (LOR):

SS

(6 days)

Loss of Use (LOU):

SS 180.00

(\$ 80 x 6 days)

Loss of Income (LOI):

SS

(\$ x 6 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS 8084.49

Global Sum SS: 8000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒ Call ☐

Payee 1:

SS 8000.00

Name 1:

Chew motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$350.00

COPY SENT
26/3/19

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SK2792E Yr Regn: 2016, Jan.Type: M.CAR / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier cc 1986Colour: White A/C: Insured / Std / NI / NASp. Reading: 43348 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 254600065708Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 235/55R18R: 235/55R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 25/03/19Survey held at NHTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AXA(Red = \$16,375.65 / 70%)MV: 90kPV: 61.51kNett: 28.51k2-4-19 4/5 167.100

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

22/03/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 10/06/2018

Estimated repair cost for vehicle no: SKZ792E TOYOTA HARRIER 2.0 A '16

CHASSIS: ZSU600065708

TPAXA

Joy.

ZSU600065708

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented.</i>		\$1,718.45 ✓
2	2	Rear Boot Lid Hinge <i>3 NH</i>	\$182.10	\$364.20 ✗
3	2	Rear Boot Lid Shock Absorber <i>new</i>	\$374.45	\$748.90 ✗
4	1	Rear Boot Lid Harrier Logo <i>New</i>		\$79.80 ✓
5	1	Rear Boot Lid Inner Lock Assy <i>3 NH</i>		\$963.10 ✗
6	1	Rear Boot Lid Inner Rubber <i>3 NH</i>		\$390.90 ✗
7	1	Rear Boot Lid Inner Trim Board <i>cracked.</i>		\$673.60 ✓
8	1	Rear Boot Lid Windscreen Seal <i>3 NH</i>		\$227.00 ✓
9	2	Rear Boot Lid Windscreen Moulding	\$182.00	\$364.00 ✓
10	1	Rear Bumper <i>Defound</i>		\$1,381.50 ✓
11	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 <i>30</i>
12	1	Rear Bumper Lower <i>Defound</i>		\$461.60 ✓
13	2	Rear Bumper Side Retainer <i>LH Dmg</i>	\$131.35	\$262.70 <i>131.35</i>
14	2	Rear Bumper Side Reflector <i>Not new</i>	\$141.40	\$282.80 ✗
15	1	Rear Bumper Inner Sponge <i>cracked.</i>		\$182.10 ✓
16	1	Rear Bumper Reverse Sensor (Special Nett) <i>Dmg</i>		\$380.00 <i>200(SN)</i>
17	1	Rear End Panel <i>Dented.</i>		\$781.90 ✓
18	1	Rear End Panel Top Garnish <i>Defound</i>		\$374.45 ✓
19	1	Rear End Panel Lock Sensor <i>Not new</i>		\$184.60 ✗
20	1	Rear Floor Panel <i>Repair</i>		\$972.45 ✗
21	1	Rear Floor Panel Top Cover <i>Defound</i>		\$655.90 <i>561.50</i>
22	1	Rear Floor Panel Spanner Box <i>Defound.</i>		\$711.90 <i>581</i>
23	1	Rear Floor Panel & End Panel Sealant <i>Not new</i>		\$450.00 ✗
24	2	Rear Fender Inner Trim Board <i>Not new</i>	\$886.30	\$1,772.60 ✗
25	1	Rear Exhaust <i>3 NH</i>		\$1,433.50 ✗
26	4	Rear Exhaust Mounting <i>new</i>	\$92.20	\$368.80 ✗
27	1	Rear Center Exhaust		\$2,636.90 ✗

- 28 1 Taillamp LH *Lot*
- 29 1 Rear Bootlid Lamp LH. *Lot*
- 30 1 Rear End Panel Sealant *Na*

585 ✓

465 ✓

Subtotal :-

\$18,875.65

100
60(SN)

8558.65
644898
5 n.260

Labour charges

To remove & refit cushion	\$280.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit rear & center exhaust	\$380.00 X
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
Tuff kote	\$150.00 60
To check wiring	\$100.00 30
Panel beating	\$2,000.00 900
Spray painting	\$1,800.00 900

Subtotal :- \$4,980.00

Total:- \$23,855.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

total 8888.58
4/5 7.1K
060mp

7.1K

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 9355E

Vehicle Details

Vehicle No.: SKZ792E
Vehicle to be Exported: No
Intended Deregistration Date: 21 Mar 2019
Vehicle Make: TOYOTA
Vehicle Model: HARRIER PREMIUM 2.0 A
Primary Colour: White
Manufacturing Year: 2015
Engine No.: 3ZRB685245
Chassis No.: ZSU600065708
Maximum Power Output: 111.0 kW (148 bhp)
Open Market Value: \$30,600.00
Original Registration Date: 08 Jan 2016
First Registration Date: 08 Jan 2016
Transfer Count: 0
Actual ARF Paid: \$29,840.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 07 Jan 2026
PARF Rebate Amount: \$22,380.00

Intended COE Rebate Details

COE Expiry Date: 07 Jan 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$57,501.00
COE Rebate Amount: \$39,075.00
Total Rebate Amount: \$61,455.00

The information contained herein is correct as at 21 Mar 2019

OK

MCF HANGOUT
UNDISCOVER TASMANIA WITH JETABOUT HOLIDAYS
SATURDAY, 6 APRIL 2019
ENJOY ONE-DAY EXCLUSIVE PACKAGE DEALS + LUCKY DRAW!

REGISTER NOW - IT'S FREE!

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

BMW X2 M-Sport X, July 2018 Offer Only \$155,800!

M-Sport Package, PHL 3Yrs/
 200,000km Warranty, Great
 Savings, I-Drive GPS, High ARF
 Repulse Marketing StarAd

PRIME MOTOR & LEASING
 (BENEFIT FROM CREDIT ENHANCEMENT RELATED GROUP OR COMPANY)
 With over 200 units of vehicles
 to choose from, ranging from
 all European to Japanese Makes.

Browse by Category

Save Searches

Print

Sort by Date Posted

20 results/page

13 vehicles	Search	Harrier premium	Advanced Search	Search	View All
Make	Model	Price	Depreciation	Reg Date	Eng Cap
Mileage	Veh Type	Status			
Search Selection	Harrier premium	Any	Any	2016	Any
		Any		Any	Any
					Any
					Available



☐ **Toyota Harrier 2.0A Premium Style Mauve**

High Specs Premium Style Mauve Unit! Pearl Black Unit With Purple Trim Interior. Original Premium Suede/Leather Upholstery. Panoramic Sliding Roof. Well Maintained By 1 Owner. Low Mileage Of Only 12,0...

Republic Auto

Posted: 22-Mar-2019



☐ **Toyota Harrier 2.0A Premium Panoramic**

Search No Further! 1 Owner White Toyota Harrier Premium Unit Up For Sale! Maintained By 1 Meticulous Owner Who Polish Monthly. Almost New Tyres With Low Mileage Clock Yearly. And Custom Big Headunit F...

Posted: 24-Feb-2019



☐ **Toyota Harrier 2.0A Premium Panoramic**

Panoramic Sliding Roof. Well Maintained By 1 Owner. Authorized 60% Bank Loan At 2.28%. Please Call/SMS For Viewing Appointment.

Republic Auto

Posted: 16-Mar-2019



☐ **Toyota Harrier 2.0A Premium Panoramic**

Enjoy Loan Interest Rate At 2.28%. Trade In Welcome. 100% Accident Free. Well Maintained View To Believe. Don't Miss This Elegant Black Beast. Call/SMS To Arrange A Viewing Now. Viewing Strictly By Ap...

Posted: 26-Mar-2019



Rojam Complete Bodykit Sutable For Toyota

Rojam kit available for harrier turbo & non-turbo with or without pre-crash model

More info about this product



☐ **Toyota Harrier 2.0A Premium Panoramic**

Elegant White SUV. Premium Model With Panoramic Sunroof And Electric Tailgate. One Owner Only. Low Maintenance Cost. Very Well Maintained. Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 12-Mar-2019



☐ **Toyota Harrier 2.0A Premium Panoramic**

Low Drive Away.High Loan Available.1 Owner. Full Maintain With Hitachi. Still Under Warranty. Call Now For More Enquirers.

Posted: 18-Mar-2019

SHORTLISTED	HISTORY	Compare	<input type="checkbox"/> Toyota Harrier 2.0A Premium	\$91,888	\$10,760 /yr	28-Apr-2016	1,986 cc	78,000 km	SUV	Available
-------------	---------	---------	---	----------	--------------	-------------	----------	-----------	-----	-----------

Assignment

To: Chew Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. SC7792E and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 25 day of 03 2019.

Signature : 
Name : NEO KIU SENG
ID No. : S1559355E
Address : _____

Witness Signature : 
Witness Name : CHEW MOTOR PTE. LTD.
Witness ID : 1 Kaki Bukit Avenue 6 Blk C #01-41
Witness Address : Autobay@Kaki Bukit Singapore 417883
Tel: 6509 5545 Fax: 6509 5567
Email: claims@chewmotor.com
UEN: 201718369R



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408953 TEL : (665) 62563561 FAX : (665) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/05/2019

Survey Details:

Date of loss	20-Mar-19
Date of appointment	21-Mar-19
Date of survey	25-Mar-19
Location of survey	CHEW MOTOR PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKZ 792E
Make and Model	TOYOTA HARRIER 1986CC
Date of registration	8/1/2016
Excess	
Market Value	\$90,000
Part Rebate	\$61,500
Nett Loss	\$28,500

Repair details:

Initial Estimate	\$ 23,855.65
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 6,708.99
Check items (estimate)	
Labour	\$ 2,190.00
Total	\$ 8,898.99
Lump Sum(if applicable)	\$ 7,100.00

Number of days for repair	6
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 6256356 FAX : (065) 62564315

Remarks:

We have not authorized repairs. HEAD TO REAR

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	7,597.00
Loss of use	\$	700.00
LTA search fee	\$	7.45
Proposed Total	\$	8,304.45



Re:MANDATE IA - SKZ792E

Type

🔗 Question

Message

Pls engage OI on TP's claim and also check with surveyor if able to discount 50% for the spare parts. TY.

Reply



Re:RE: Re:RE: Re:MANDATE IA - SKZ792E

Type

🔗 Question

Message

Hi, yes. \$7,100/- global sum. TY.

Reply



Re:RE: Re:RE: Re:RE: Re:MANDATE IA - SKZ792E

Type

🔗 Question

Message

Pls offer \$8k all-in. TY

Reply

Our Reference : CM1904-0077 / SKZ792E
Your Reference : SJH8856J

23 April 2019

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#B1-01,
Singapore 068811



CHEW MOTOR PTE. LTD

WITHOUT PREJUDICE

Dear Sir/Madam

ACCIDENT INVOLVING SKZ792E & SJH8856J ON 20.03.2019 ALONG BUKIT BATOK WEST AVE 2 AT 15:17HRS

We are instructed by **NEO KIW SENG** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SKZ792E** damaged by vehicle **SJH8856J** driven by your insured at the material time.

We are informed that the said accident was caused by your insured's negligence. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows: -

➤ Repair Costs (7% GST)	\$ 7,597.00
➤ Loss of Use for 07 days (6 + 1 Weekend)	\$ 700.00
➤ LTA Search Fees	\$ 7.45
➤ Total	\$ 8,304.45

A copy of each supporting documents are enclosed for your perusal.

- GIA Report
- Invoice
- LTA Search Receipt

Please let us have your cheque for the sum of **\$8,304.45** made payable to us, **CHEW MOTOR PTE. LTD.** within the next 14 days.

Yours Sincerely,



CHEW MOTOR PTE. LTD.

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Friday, 12 July 2019 11:07 AM
To: ivanlim66@yahoo.com.sg
Subject: <Standard Notification Letter> OUR REF: CC4/ASM19005161/Aga3 *** ACCIDENT INVOLVING SJH 8856J & SKZ 792E ON 20/03/2019 ***

12 JULY 2019

LIM KOK HENG

Dear Sir/ Mdm

OUR REF : CC4/ASM19005161/Aga3

YOUR REF : SJH 8856J

ACCIDENT INVOLVING SJH 8856J AND SKZ 792E ALONG/AT BUKIT BATOK WEST AVE 2 ON 20/03/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **CHEW MOTOR PTE LTD** acting on behalf of the owner of SKZ 792E against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in our favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ceciliachong@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre.** The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Driver's Work Permit
- Employment Letter/ Authorisation letter from your company
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6749 4274 or email us at ceciliachong@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

LETTER OF AUTHORISATION

Chew Motor Pte Ltd

Kaki Bukit Avenue 6

Blk 1 #01-11

Singapore 417883

Dear Sir,

Accident on

20/03/19, 1517

Involving Vehicles

9C7792E, SJH8856J

Along

BT BOTOX West Ave 2

I/We, the registered owner/driver of vehicle registration no: _____
have involved in the above accident.

SK2792E

I/We hereby authorize **Chew Motor Pte Ltd** to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, _____, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,

Owner's Signature

(Company's stamp if applicable)

Name:

NEO KION SENG

NRIC No.:

S1559355 E

Date:

25/03/2019



WITHOUT PREJUDICE to:
(a) Insurance Undertakened Claim amount
(b) Any Personal Injury Claims
(Note: This form supersedes any correspondence issued in this Discharge Number)

AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SJH 8866J (Insd veh)	Model: TOYOTA HARRIER
	SKZ 792E (TP veh)	
Date of Accident/ Time:	20/03/2019 / 15:10	

Repair Estimate	\$ 26,756.85	
Final Repair Cost (WGST)	\$ 7,597.00	
Loss of Use	\$ 480.00	8 days at \$ 80.00 per day
Rental (if any)	\$	days at \$ per day
LTA / GIA Search Fee	\$ 7.45	
Others:	\$	
Final Settlement Sum	\$ 8,000.00	(global sum)
Payee Name: Chew Motor Pte Ltd		
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)		
A) For Non GIA Registered Workshop: Agreed Liability 100 (%)		
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: (%) Assessed Liability (%): (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.



Signature of workshop representative / Workshop stamp

Name of Representative: Sutyi chong

Date: 22.7.19



Signature of Witness / Workshop stamp (if applicable)

Name of Witness: Chioe Chew

Date: 22.7.19



Signature of AXA's surveyor representative:

Name of AXA's surveyor / Representative:

Date: 26/7/19



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

GST Reg No.: 201718369R

TAX INVOICE

AXA Insurance Pte Ltd

8 Shenton Way,

#B1-01,

Singapore 068811

Client: NEO KIW SENG

Invoice No : CPI1904-0077

Date : 23-Apr-19

Date of Accident : 20-Mar-19

Vehicle No. : SKZ792E

Model Type : Toyota Harrier

Descriptions		Amount
Lump Sum Repair Cost		7,100.00
GST 7% :		497.00
Total :		7,597.00

(SGD) Dollars: SEVEN THOUSAND FIVE HUNDRED AND NINETY SEVEN ONLY





Reena . <reena@nhtmotor.com>

Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-190321-001401

LTA <LTA-VTL@lta.gov.sg>
To: reena@nhtmotor.com

Thu, Mar 21, 2019 at 12:07 PM



Notification of Successful Vehicle Insurance Search for Receipt No.: ITNET-00000-190321-001401

Dear Sir/Madam

We wish to inform you that your transaction on "Enquire Vehicle Insurance Particulars" performed on 21 Mar 2019 was successful and the Receipt No. is ITNET-00000-190321-001401.

2. The details of the search results are as follow:

Vehicle No.	Search Date	Search Time	Search Result
SJH8856J	20 Mar 2019	15:17:00	AXA INSURANCE PTE LTD

3. Please contact our customer service officers at tel : 1800-CALL LTA (1800-2255 582) should you require further assistance.
4. Visit www.onemotoring.com.sg for more information, or go to www.lta.gov.sg/feedback if you have any feedback. This email is auto-generated, please do not reply to this email.
5. Thank you.

If you are not the intended recipient of this communication, please delete it.


As it may contain confidential or official information, do not retain it or disclose the contents to any person as it may be an offence under the Official Secrets Act.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19005161/Aga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG		Date : 06-08-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJH 8856J	Veh. Inspected	SKZ 792E
Policy No.	GA194703/1	Coverage (\$)	0.00
Claim No.	S9M01HPP	Excess (\$)	0.00
Assign From		Assign Date	21/03/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZSU600065708	Colour	WHITE
Odometer	43348	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	MICHELIN	6 mm
L/H Front Tyre	235/55 R18	MICHELIN	6 mm
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/03/2019	Inspection Date	25/03/2019
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 792E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID (CONSISTENT)	DENTED	✓ 1,718.45	1,718.45
2	REAR BOOT LID HINGE @\$182.10 (CONSISTENT)	NOT NECESSARY	✓ 364.20	-
2	REAR BOOT LID SHOCK ABSORBER @\$374.45 (CONSISTENT)	NOT NECESSARY	✓ 748.90	-
1	REAR BOOT LID HARRIER LOGO (CONSISTENT)	NECESSARY	✓ 79.80	79.80
1	REAR BOOT LID INNER LOCK ASSY (CONSISTENT)	NOT NECESSARY	✓ 963.10	-
1	REAR BOOT LID INNER RUBBER (CONSISTENT)	NOT NECESSARY	✓ 390.90	-
1	REAR BOOT LID INNER TRIM BOARD (CONSISTENT)	CRACKED	✓ 673.60	673.60
1	REAR BOOT LID WINDSCREEN SEAL (CONSISTENT)	NECESSARY	✓ 227.00	227.00
2	REAR BOOT LID WINDSCREEN MOULDING @\$182.00 (CONSISTENT)	NECESSARY	✓ 364.00	364.00
1	REAR BUMPER (CONSISTENT)	DEFORMED	✓ 1,381.50	1,381.50
8	REAR BUMPER CLIP @\$6.50 (CONSISTENT)	NECESSARY	✓ 52.00	30.00
1	REAR BUMPER LOWER (CONSISTENT)	DEFORMED	✓ 461.60	461.60
2	REAR BUMPER SIDE RETAINER @\$131.35 (CONSISTENT)	N/S DAMAGED	✓ 262.70	131.35
2	REAR BUMPER SIDE REFLECTOR @\$141.40 (CONSISTENT)	NOT NECESSARY	✓ 282.80	-
1	REAR BUMPER INNER SPONGE (CONSISTENT)	CRACKED	✓ 182.10	182.10
1	REAR END PANEL (CONSISTENT)	DENTED	✓ 781.90	781.90
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	✓ 374.45	374.45
1	REAR END PANEL LOCK SENSOR (CONSISTENT)	NOT NECESSARY	✓ 184.60	-
1	REAR FLOOR PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	✓ 972.45	-
1	REAR FLOOR PANEL TOP COVER (CONSISTENT)	DEFORMED	✓ 655.90	561.90
1	REAR FLOOR PANEL SPANNER BOX (CONSISTENT)	DEFORMED	✓ 711.90	581.00
1	REAR FLOOR PANEL & END PANEL SEALANT (CONSISTENT)	NOT NECESSARY	✓ 450.00	-
2	REAR FENDER INNER TRIM BOARD @\$886.30 (CONSISTENT)	NOT NECESSARY	✓ 1,772.60	-
1	REAR EXHAUST (CONSISTENT)	NOT NECESSARY	✓ 1,433.50	-
4	REAR EXHAUST MOUNTING @\$92.20 (CONSISTENT)	NOT NECESSARY	✓ 368.80	-
1	REAR CENTER EXHAUST (CONSISTENT)	NOT NECESSARY	✓ 2,636.90	-

Report Ref No. CC4/ASM19005161/Aga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILLAMP LH (CONSISTENT)	CUT	585.00	585.00
1	REAR BOOTLID LAMP LH (CONSISTENT)	CUT	465.00	465.00
	LESS 25% DISCOUNT		-	-2,149.66
			19,545.65	6,448.99
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	380.00	200.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	60.00
			480.00	260.00
	<u>LABOUR</u>			
1	TO REMOVE & REFIT CUSHION.		280.00	80.00
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIT REAR & CENTER EXHAUST.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	GUM.		50.00	50.00
	TUFF KOTE.		150.00	60.00
	TO CHECK WIRING.		100.00	30.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL .		2,000.00	900.00
	SPRAY PAINTING.		1,800.00	900.00
			4,980.00	2,190.00
GRAND TOTAL			25,005.65	8,898.99
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,100.00

Report Ref No. CC4/ASM19005161/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (4).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
LKKInspection (4).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
LKKAdjustment 1a (5).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
AUTHORIZATION TO ACT Form.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	14 August 2019
MARKED ESTIMATE - SKZ 792E.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2019
GIA SEARCH.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2019
MANDATE 1A - CHEVROMOTOR-SKZ792E.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2019

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 RE-SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2019
 SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	25 May 2019
 LIST OF SURVEYOR SENT.mng	Letters and Correspondence	Surveyor / Assessor	VISHNU BATHAM Shahar	21 March 2019
 TP-GIA REPORT.pdf	Reports & Statement	GIA Report	LKK AUTO CONSULTANTS PTE LTD (TP)	21 March 2019
 Surveyor appointed.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shahar	21 March 2019
 Service appointment in Vinilar Portal claim SYM0116pp for vehicle SKZ792E.html	[[getDocumentType_AuItem.documentType]]		VISHNU BATHAM Shahar	21 March 2019
 EMAIL TP.pdf.mng	Letters and Correspondence	Workshop	VISHNU BATHAM Shahar	21 March 2019