

ASS. REC. BY:

REF: CS/CT/19005166/R/D307

Special Instruction:

Surveyor: RusuASSIGNMENT (Office)From (Person): Chong Boon Sen of C12 Date/Time: 21.3.19 16:39 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 3199 Insured: _____
at Workshop m/s Eurosport's Auto Pte Ltd Tel: 65655995 (9799 7593)
of 24 Leng Kee Road #01-03Policy No: DMPCSA 1836731800 Claim No: SIVM19D201202 COT / 9Sum Insured: _____ Excess: \$ 4000.00Make of Veh: _____ D.O.A. 15.3.19
(Client's Record)

CA / (REV) / REP. / REV 24 HRS

Date/Time: 22.3.19 9:15 AM Person Contacted: Richard H.O.D. Endorsement: _____
Vehicle: IN / OUT

Date/Time	Action/Instruction	Estimate	(✓)
	SKR 3199 - X		
25/3/19	Revert via merimen		
26/3/19	Rece approved \$52,350 from Alfred by merimen		
26/3/19	Informed Richard c/A ex \$4000 f by email		
26/4/19	@ 4:49 pm Richard said vehicle waiting for spare parts		

DRIVER: Kavan

REF:

43264

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKR 3196
 at Workshop m/s Eurosport
 of 24, Leach Hill RD
CTI
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: 4000
 (Client's Record)
 Make of Veh: _____
 (Policy Condition) Richard
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$190K 25/3/19 Marcus
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKR 3196 Yr Regn: 2018 / NOV
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: LOTUS ELISE SP 220M c.c. 1798
 Colour: YELLOW A/C: Insured / Std / NI / NA
 Sp. Reading: 00 2110 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SCCLJCR03JHC10153
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 175/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 15/03/19 D.O.I. 22/03/19
 Survey held at Eurosport
 Des. of Damages: Fb / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>29/5/19</u>	<u>@ 5:10pm Richard said vehicle waiting for spare parts</u>
<u>23/7/19</u>	<u>Final fig \$55,717 confirmed by email (Ref 6639.50, 1190)</u>

RECEIVED 23 JUL 2019

23/7/2019

Date/Time, File Pass to? Prel. Report
 Final Report
 1) _____
 Date/Time, File Return to?
 2) 23/7 - typet

Report Format: mermen
 Lump Sum / I.B.I: (\$) 55,717

Days Of Repair: 6
 Resurvey No. of Trip: 2

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: 220
 Transportation: _____
 Photos _____
 Others _____
 TOTAL: 220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2019		21 Mar 2019 16:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JONATHAN KWA HIAN CHOON, ID: S7724326G, Tel: +6590039119, Email: NOEMAIL								
Vehicle Reg. No.:	SKR319G	Date of Loss:	15/03/2019 08:00 - :59						
Claim Type:	OD / SNM19D201202C01/9	Policy/Cover Note No.:	DMPCSN1836771800 (Comprehensive)						
		Excess:	S\$4,000.00						
Repairer:	Eurosports Auto Pte Ltd (HQ) 24 Leng Kee Road #01-03, 159096 Leng Kee - Tel: 65655995								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/04/2019]								
Driver/Custodian:	JONATHAN KWA HIAN CHOON (41 / Male), NRIC: S7724326G, Tel: +6590039119 Email: NOEMAIL								
Adj Asg. Remarks:	survey revert, consistency of damages, economical to repair.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***SKR319G (SNM19D201202C01/9)**

OD

Mar 15 2019 8:00AM

[JONATHAN KWA HIAN CHOON]

Eurosports Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 23/07/2019 10:44 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$55717.00) - SKR319G - Claim Handler: Chong Boon Sen

Approved:55717.00:Please proceed to authorize repairs at \$55,717.00 BEFORE Excess of \$4,000.00, RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	--

Attn: Chong Boon Sen **Date:** 22 Jul 2019

Preliminary Advice

Vehicle No : SKR319G Make : LOTUS ELISE Assignment Date : 21/03/2019 Date of Inspection : 22/03/2019 Inspection At : EUROSPOITS AUTO PTE LTD (HQ) 24 LENG KEE ROAD #01-03 SINGAPORE 159096	Accident Date : 15/03/2019 Policy No. : DMPCSN1836771800 Excess : S\$4,000.00 Est. Duration of Repair : 6.00
---	---

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	62,357.50 (incl.supplementary \$4417)
Revised Amount	:S\$	55,717.00 (incl.supplementary \$4417)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	55,717.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	190,000.00
COE / PARF Rebate	:S\$	85,605.00
Salvage Value	:S\$	
Margin for Repair	:S\$	104,395.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAuto)

From: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Sent: Tuesday, 7 May 2019 5:13 PM
To: Veron Chen (LKKAuto); Rasul (LKKAuto); SUR
Cc: SF Eyu; Khan Wei Loh
Subject: Re: SKR 319G DOA : 15/03/19

Hello Veron.

The Lotus SKR319G. Has not been repaired yet.
We are still waiting for the parts from factory.
The parts are expected to get here early June.

Regards,

Richard Harjanto
Eurosports Auto Pte Ltd.

Sent from my Samsung Galaxy smartphone.

----- Original message -----

From: "Veron Chen (LKKAuto)" <veronchen@lkkauto.com>
Date: 07/05/2019 17:04 (GMT+08:00)
To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>, "Rasul (LKKAuto)" <Rasul@lkkauto.com>, SUR <sur@lkkauto.com>
Cc: SF Eyu <Sfeyu@eurosportsauto.com.sg>, Khan Wei Loh <khanwei@eurosportsauto.com.sg>
Subject: RE: SKR 319G DOA : 15/03/19

Dear Richard,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 26 March 2019 12:16 PM
To: 'Richard Harjanto' <richardharjanto@eurosportsauto.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR

<sur@lkkauto.com>

Cc: SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>

Subject: RE: SKR 319G DOA : 15/03/19

Dear Richard,

As instructed by our client , please proceed to repair the **insured vehicle SKR 319G (Excess \$4000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>

Sent: Monday, 25 March 2019 11:02 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>

Subject: RE: SKR 319G DOA : 15/03/19

Hello,

Here is the sales invoice for the Lotus SKR319G.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865

Mobile: +65 9799 9593

Email: richardharjanto@eurosportsauto.com.sg

Web: www.lamborghini-singapore.com

Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Monday, March 25, 2019 9:27 AM
To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: SKR 319G DOA : 15/03/19

Hi Richard,

As spoken, kindly forward to me the purchase invoice for this vehicle

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 26 March 2019 12:16 PM
To: 'Richard Harjanto'; Rasul (LKKAuto); SUR
Cc: SF Eyu; Khan Wei Loh
Subject: RE: SKR 319G DOA : 15/03/19

Dear Richard,

As instructed by our client , please proceed to repair the **insured vehicle SKR 319G (Excess S4000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Sent: Monday, 25 March 2019 11:02 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>
Subject: RE: SKR 319G DOA : 15/03/19

Hello,

Here is the sales invoice for the Lotus SKR319G.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865
Mobile: +65 9799 9593
Email: richardharjanto@eurosportsauto.com.sg
Web: www.lamborghini-singapore.com
Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Monday, March 25, 2019 9:27 AM
To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: SKR 319G DOA : 15/03/19

Hi Richard,

As spoken, kindly forward to me the purchase invoice for this vehicle


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

View Received Message

This mail is associated with :

***SKR319G (SNM19D201202C01/9)**
OD
Mar 15 2019 8:00AM
[JONATHAN KWA HIAN CHOON]
Eurosports Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **26/03/2019 11:25 AM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$52350.00) - SKR319G - Claim Handler: Chong Boon Sen

Approved:52350.00:Please proceed to authorize repairs at \$52,350.00 BEFORE Excess of \$4,000.00. RE-INSPECTION OF VEHICLE REQUIRED.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	--

Attn: Chong Boon Sen **Date:** 25 Mar 2019

Preliminary Advice

Vehicle No	: SKR319G	Accident Date	: 15/03/2019
Make	: LOTUS ELISE	Policy No.	: DMPCSN1836771800
Assignment Date	: 21/03/2019	Excess	: S\$4,000.00
Date of Inspection	: 22/03/2019	Est. Duration of Repair	: 6.00
Inspection At	: EUROSPTS AUTO PTE LTD (HQ) 24 LENG KEE ROAD #01-03 SINGAPORE 159096		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	57,940.50
Revised Amount	:S\$	52,350.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	52,350.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	190,000.00
COE / PARF Rebate	:S\$	85,605.00
Salvage Value	:S\$	
Margin for Repair	:S\$	104,395.00

Brake System : In Order
 Steering System : In Order
 Tyre Condition (Front) : 6/6 mm
 Tyre Condition (Rear) : 6/6 mm

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4326G
Vehicle Details	
Vehicle No.:	SKR319G
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Mar 2019
Vehicle Make:	LOTUS
Vehicle Model:	ELISE SPORT 220 MANUAL
Primary Colour:	Yellow
Manufacturing Year:	2017
Engine No.:	22RV515601
Chassis No.:	5CCLJCRC3JHC10153
Maximum Power Output:	161.8 kW (216 bhp)
Open Market Value:	\$56,620.00
Original Registration Date:	12 Nov 2018
First Registration Date:	12 Nov 2018
Transfer Count:	0
Actual ARF Paid:	\$73,916.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Nov 2028
PARF Rebate Amount:	\$55,437.00
Intended COE Rebate Details	
COE Expiry Date:	11 Nov 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$32,552.00
COE Rebate Amount:	\$30,168.00
Total Rebate Amount:	\$85,605.00

The information contained herein is correct as at 22 Mar 2019

OK

EuroSports Auto



SALES AGREEMENT

I/W: Johnathan Kwa Hian Choon

LSA No:

M:

DATE: 28/10/18TEL: 90039119

(hereinafter called "the buyer" hereby confirm having purchased from EUROSPORTS AUTO PTE LTD hereinafter called "the seller") the undermentioned vehicle at the price and on the terms and conditions hereinafter appearing and subject to the Conditions of Sales printed on the back hereof).

		Or to be advised	
Make: <u>Lotus</u>	Body Colour: <u>Yellow</u>		
Model: <u>Elise Sport 220</u>	Upholstery:		
Demanded Delivery Date:			
Vehicle Price - Net		S\$	225,000.00
Registration Fee		S\$	inclusive
Road Tax		S\$	inclusive
Number Plates		S\$	inclusive
Accessories (<u>1 x free servicing</u>) (<u>have agreed on whole yr</u>)		S\$	inclusive
Total Cash Price		S\$	225,000.00
Low Discount / COE Subsidy		S\$	Nil
Low Deposit		S\$	12,000.00
Balance Due		S\$	213,000.00

Note: The above prices and specifications are subject to change without notice and only price ruling on date of delivery will apply.
Deposits are not refundable in the event of cancellation.

Salesman: BRYAN HOE

I/We have read and understand the terms on the back hereof and agree to them as part of this order as if they were printed above my/our signature.

Approved and accepted by:

Date:

28/10/18.

Signed:

Buyer:

Date:

28th Oct 2018.

This agreement is not binding on the vendor unless approved and accepted by an authorised representative of vendor.

EuroSports Auto Pte Ltd

24 Leng Kee Road #01-03 Singapore 159090 Tel: (65) 6565 5995 Fax: (65) 6567 5515

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/03/2019 15:35
Date Of Accident	15/03/2019 08:25
Exact Location Of Accident	953 BUKIT TIMAH RD AT THE TRAFFIC LIGHT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR319G
Insured/Policyholder	
Name Of Registered Owner	JONATHAN KWA HIAN CHOON
NRIC No	S7724326G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90039119
Alternative Phone No	OFFICE-90039119

Vehicle Particulars

Manufacturer	LOTUS
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1836771800
Cover Note Number	

Driver

Name of Driver	JONATHAN KWA HIAN CHOON
NRIC No	S7724326G
Date Of Birth	05/09/1977
Occupation	INDOOR
Date Of Driving Pass	10/12/1996
Driving Experience	22 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90039119
Fax Number	
Contact Number	OFFICE-90039119
Email Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

refer attached report.


Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG7992L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver DENG CHUN PING
 NRIC/Passport Number G3337918N
 Contact Number 90690891
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 9:25 am driving on a 3 lane road on Bukit Timah going to work. I was in the centre lane following a grey volvo at around 40-50 km/h.

At the traffic light. As we approached the traffic light, it turned amber and she proceeded to slam on the brakes. Even though I was 1 car length away, I still skiddled and slammed into her rear. My right door couldn't open and I rolled down the window asking if she was OK. She said she was fine, so we pulled to the side to exchange particulars.

Volvo is SLG 792L

Lotus is SKR 319G

Note = 15/3/18 Owner Isaac Azeat inform Alfred vehicle in other work-shop. Driver taken photo.

DECLARATION

(/We declare the foregoing particulars are true in every respect.


Policy Holder's Signature
Date & Time: 7

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, SINGAPORE 159096
TEL : (65) 6565 5995 FAX : (65) 6567 5515



20-03-19

Vehicle / Model : SKR319G / Lotus Elise
CI: China Taiping Insurance
Policy: DMPCSN1836771800
Accident Date: 15/03/2019
Own Damage Claim

Repair Quotation

PARTS

1	A117U0170F	Front Logo <i>NEE /</i>	\$	612.00	✓
2	A120B0238K	Front Clamp Shell (Bumper and Front Body) <i>CRA /</i>	\$	33,500.00	✓
3	B120M4002F	Head Lamp RH <i>CRA /</i>	\$	8,238.00	✓
4		Brackets, rivets and fasteners <i>NEE /</i> 1000	\$	1,300.00	✓
Subtotal for Parts			\$	43,650.00	

Labor Charges

Dismantle, Re Fitting and Repair (5 Days)	\$	4,800.00 <i>4000 ✓</i>
Respray for front body clamshell <i>3500</i>	\$	4,500.00 <i>4000 ✓</i>
Sealers for Body attachment <i>450</i>	\$	1,200.00 <i>700 ✓</i>
Subtotal for Labor	\$	10,500.00
GST	\$	3,790.50
Total	\$	57,940.50 <i>(S) 4417</i>

- 1 This is only an estimate, should any additional job be found necessary in the course of work, extra material and labour, cost will be charged accordingly for which you will be informed prior to action taken.
- 2 All materials prices quoted are subject to change without notification
- 3 All repairs are subject to spare parts availability
- 4 Quotation valid for one month from date of issue.

Lamborghini Singapore
Workshop Contact:
Richard Harjanto
Service Advisor
97999593

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To respray damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

RASUL
Hp 90010068
6 days
P/P
22/03/19 @ 1500 hrs
EXCESS: 4000
REVERT
Resurvey before paint

08561
26/3/19

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

*** PROFORMA INVOICE ***

Deliver To: Mr
Jonathan Kwa Hian Choon
19 Victoria Park Road
Singapore 266498

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
079909
Invoice to: 100090

Document No.:

Document Date: 17-Jul-19
REGN No.: SKR319G
Odometer: 2709
Model: 2017 Elise Sport
Variant: Lotus Elise
Vehicle ID No.: SCCLJCRC3JHC10153
Repair Order No.: 17156
Delivery Date: 12/11/2018
Page: 1 of 2
Advisor: Richard Harjanto

ACCIDENT - Own Damage CLAIM

China Taiping Insurance

DMPCSN1836771800

DOA: 15/3/2019

Surveyor: LKK Auto / Rasul

Accident repair for front body shell and door

Labor to dismantle, fitting of new parts, Recalibrate and Alignment.

\$4,000.00

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
3382748	CASTROL EDGE PRO LL III 5W-30 (A) rec ✓	29.00	29.00	4.00	116.00
D122B0192F	PANEL, HEADLAMP ACCESS, FRT RH (A) bt ✓	435.00	435.00	1.00	435.00
C120M4002F	HEADLAMP RH ELISE MY2011	8,238.00	8,238.00	1.00	8238.00
C117K0021F	RADIATOR ELISE/EXIGE (A) bt ✓	3,310.00	3,310.00	1.00	3310.00
A147B0002K	FRT CLAMSHELL MY18 ELISE	33,500.00	33,500.00	1.00	33500.00
A117U0170F	FRT LOGO ELISE / EXIGE / EVORA	612.00	612.00	1.00	612.00
G013A8JM1	COOLANT 1.5L (AUDI) (A) rec ✓	38.00	38.00	2.00	76.00
					\$46,287.00

To repair Aircon Condensor

To repair aircon condenser (A) ✓

\$250.00

To supply new number plate for front bumper (A) rec ✓

To supply new plate SKR319G


\$30.00

To service aircon system, and Recharge AC gas (A) ✓

\$200.00

To supply new screws, clips, fastening parts, Rivets, and brackets.

1000 \$1,300.00



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



TAX INVOICE

GST Reg No.: M90368995L

*** PROFORMA INVOICE ***

Deliver To: Mr
Jonathan Kwa Hian Choon
19 Victoria Park Road
Singapore 266498

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
079909
Invoice to: 100090

Document No.:
Document Date: 17-Jul-19
REGN No.: SKR319G
Odometer: 2709
Model: 2017 Elise Sport
Variant: Lotus Elise
Vehicle ID No.: SCCLJCRC3JHC10153
Repair Order No.: 17156
Delivery Date: 12/11/2018
Page: 2 of 2
Advisor: Richard Harjanto

To supply new screws, clips, fastening parts, Rivets, and brackets.

Labor for repair, knocking and respray of driver side door. And Painting of new Front body shell.

3500 ~~54000.00~~

To supply Special Bond Gasket Sealer for Body Shell.

450 ~~3700.00~~

Towing service from accident site to workshop

TOWING FROM DUNEARN RD To LengKee Rd 15/3/2019

(AS) X separate invoice

\$250.00

EuroSports Auto Pte Ltd



Signature

Date

17/7/19

Sub Total for All: \$57,017.00
Rounding: \$0.00
GST: \$3,991.19
Total: \$61,006.19

Terms:

Any objections to the validity of the charges must be made within seven (7) days from the date of this invoice otherwise it is assumed this Bill is accepted as correct.

GOODS SOLD ARE NOT RETURNABLE OR REFUNDABLE

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096
 Main Line: (65) 6565 5995 Fax: (65) 6567 5515
 REG. NO.: M90368995L



*** PROFORMA INVOICE ***

Deliver To: Mr
 Jonathan Kwa Hian Choon
 19 Victoria Park Road
 Singapore 266498

China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 079909
 Invoice to: 100090

TAX INVOICE

GST Reg No.: M90368995L

Document No.:
 Document Date: 22-Jul-19
 REGN No.: SKR319G
 Odometer: 2709
 Model: 2017 Elise Sport
 Variant: Lotus Elise
 Vehicle ID No.: SCCLJCRC3JHC10153
 Repair Order No.: 17156
 Delivery Date: 12/11/2018
 Page: 1 of 2
 Advisor: Richard Harjanto

ACCIDENT - Own Damage CLAIM

China Taiping Insurance
 DMPCSN1836771800
 DOA: 15/3/2019
 Surveyor: LKK Auto / Rasul
 Accident repair for front body shell and door
 Labor to dismantle, fitting of new parts, Recalibrate and Alignment.

\$4,000.00

Part Number	Part Description	List Price	Nett Price	Quantity	Total Cost
3382748	CASTROL EDGE PRO LL III 5W-30 (A) nec	29.00	29.00	4.00	116.00
D122B0192F	PANEL,HEADLAMP ACCESS,FRT RH (A) bt	435.00	435.00	1.00	435.00
C120M4002F	HEADLAMP RH ELISE MY2011	8,238.00	8,238.00	1.00	8238.00
C117K0021F	RADIATOR ELISE/EXIGE (A) bt	3,310.00	3,310.00	1.00	3310.00
A147B0002K	FRT CLAMHELL MY18 ELISE	33,500.00	33,500.00	1.00	33500.00
A117U0170F	FRT LOGO ELISE / EXIGE / EVORA	612.00	612.00	1.00	612.00
G013A8JM1	COOLANT 1.5L (AUDI) (A) nec	38.00	38.00	2.00	76.00
					\$46,287.00

To repair Aircon Condensor

To repair aircon condenser (A) ✓ \$250.00

To supply new number plate for front bumper (A) nec

To supply new plate SKR319G \$30.00

To service aircon system, and Recharge AC gas (A) ✓

\$200.00

To supply new screws, clips, fastening parts, Rivets, and brackets.

\$1,000.00



Continued Next Page ...

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



*** PROFORMA INVOICE ***

Deliver To: Mr
Jonathan Kwa Hian Choon
19 Victoria Park Road
Singapore 266498

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
079909
Invoice to: 100090

Document No.:

Document Date: 22-Jul-19
REGN No.: SKR319G
Odometer: 2709
Model: 2017 Elise Sport
Variant: Lotus Elise
Vehicle ID No.: SCCLJCRC3JHC10153
Repair Order No.: 17156
Delivery Date: 12/11/2018
Page: 2 of 2
Advisor: Richard Harjanto

TAX INVOICE

GST Reg No.: M90368995L

To supply new screws, clips, fastening parts, Rivets, and brackets.

Labor for repair, knocking and respray of driver side door. And Painting of new Front body shell.

\$3,500.00

To supply Special Bond Gasket Sealer for Body Shell.

\$450.00

EuroSports Auto Pte Ltd



Signature

Date

22/7/19

Sub Total for All: \$55,717.00

Rounding: \$0.00

GST: \$3,900.19

Total: \$59,617.19

Terms:

Any objections to the validity of the charges must be made within seven (7) days from the date of this invoice otherwise it is assumed this Bill is accepted as correct.

GOODS SOLD ARE NOT RETURNABLE OR REFUNDABLE

EUROSPORTS AUTO PTE LTD

24 Leng Kee Road #01-03, Singapore 159096

Main Line: (65) 6565 5995 Fax: (65) 6567 5515

REG. NO.: M90368995L



*** PROFORMA INVOICE ***

Deliver To: Mr
Jonathan Kwa Hian Choon
19 Victoria Park Road
Singapore 266498

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
079909
Invoice to: 100090

TAX INVOICE

GST Reg No.: M90368995L

Document No.:
Document Date: 22-Jul-19
REGN No.: SKR319G
Odometer: 2709
Model: 2017 Elise Sport
Variant: Lotus Elise
Vehicle ID No.: SCCLJCRC3JHC10153
Repair Order No.: 17156
Delivery Date: 12/11/2018
Page: 1 of 1
Advisor: Richard Harjanto

Towing service from accident site to workshop

TOWING FROM DUNEARN RD To LengKee Rd 15/3/2019

\$250.00

EuroSports Auto Pte Ltd



Signature

Date

22/7/19


Sub Total for All: \$250.00
Rounding: \$0.00
GST: \$17.50
Total: \$267.50

Terms:

Any objections to the validity of the charges must be made within seven (7) days from the date of this invoice otherwise it is assumed this Bill is accepted as correct.

GOODS SOLD ARE NOT RETURNABLE OR REFUNDABLE

Front LH wheel arch front panel headlamp access.



ELISE
12.01

Updated 19th December 2010

Service Parts List



Function Code 12.01 Wheelarch Liners

Dep	Part Description	Remarks	Option	Part Number	Qty
01	Panel, headlamp access, front wheelarch, RH		Elise	A120B0076F	1
01a	Panel, headlamp access, front wheelarch, RH		Exige, B122B0191F R/B	C122B0192F	1
02	Panel, headlamp access, front wheelarch, LH		Elise	A120B0075F	1
02a	Panel, headlamp access, front wheelarch, LH		Exige, B122B0191F R/B	C122B0191F	1
03	Wheelarch Liner, front, RH, LHD		Elise	C120B0112F	1
03a	Wheelarch Liner, front, RH, LHD		Exige	A122B0120F	1
03b	Wheelarch Liner, front, RH, RHD		Elise	B120B0004F	1
03c	Wheelarch Liner, front, RH, RHD		Exige	A122B0172F	1
04	Wheelarch Liner, front, LH, LHD		Elise	B120B0113F	1
04a	Wheelarch Liner, front, LH, LHD		Exige	A122B0121F	1
04b	Wheelarch Liner, front, LH, RHD		Elise	C120B0003F	1
04c	Wheelarch Liner, front, LH, RHD		Exige	A122B0171F	1
04e	Wheelarch Liner, front, LH, RHD, LHD	1ZR, 2ZR powertrain	1ZR, 2ZR Bosch, ABS from vin BH_10931	A120B0415F	1
05	Wheelarch Liner, rear, RH		Elise	B120B0030F	1
05a	Wheelarch Liner, rear, RH		Exige	B122B0124F	1
06	Wheelarch Liner, rear, LH		Elise	B120B0031F	1
06a	Wheelarch Liner, rear, LH		Exige	B122B0125F	1
07	Mudflap, front, RH		Elise	D117B0172F	1


ELISE

Function Code: 12.01, Page: 1

Updated 31st May 2013


Service port cap colours





-  R-134A Gas
-  R-1234VF Gas



18.03

Updated 2nd January 2018





ELISE
10.01e

Updated 3rd April 2017

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 23 July 2019 11:55 AM
To: Rasul (LKKAuto); Richard Harjanto; SUR
Subject: FW: LOTUS SKR319G
Attachments: SKR 319G-22Jul2019- amended invoice.pdf

Dear Richard,

Confirmed final amount \$55,717 before excess \$4000 and GST @ 6 working days

Kindly send Final invoice and all supporting documents directly to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Sent: Monday, 22 July 2019 11:02 AM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: SF Eyu <Sfeyu@eurosportsauto.com.sg>; Khan Wei Loh <khanwei@eurosportsauto.com.sg>
Subject: RE: LOTUS SKR319G

Hello Rasul,

I have attached the amended invoice for the claim of SKR319G
And also separated the invoice for the towing charge.
Please proceed to finalize this claim.
And let me know as soon as you get a reply from China Taiping.
As I need to close this invoice by end of month.

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865
Mobile: +65 9799 9593
Email: richardharjanto@eurosportsauto.com.sg
Web: www.lamborghini-singapore.com
Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper use of the contents of this email will be prosecuted by law in compliance with the laws in the matter of data protection as well as in order to protect the right of confidentiality of correspondence.

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Monday, July 22, 2019 10:39 AM
To: Richard Harjanto <richardharjanto@eurosportsauto.com.sg>
Subject: RE: LOTUS SKR319G

Hi Richard,

Refer to attachment

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Richard Harjanto [<mailto:richardharjanto@eurosportsauto.com.sg>]
Sent: Friday, 19 July, 2019 5:33 PM
To: Rasul (LKKAuto)
Cc: SF Eyu; Khan Wei Loh
Subject: LOTUS SKR319G

Hi Rasul,

Here are the parts catalog and the photo of the AC condenser, We sent it outside for checking and repair.

And the Headlamp access panel at the wheel arch RH side (TORN)

Thank you and,

Best regards,
Richard Harjanto

Lamborghini Singapore
EuroSports Auto Pte Ltd
Richard Harjanto
Service Advisor

24 Leng Kee Road #01-03
Singapore 159096
Phone: +65 6882 0865
Mobile: +65 9799 9593
Email: richardharjanto@eurosportsauto.com.sg
Web: www.lamborghini-singapore.com
Web: www.eurosportsglobal.com

The contents of this e-mail, and any attachments, are confidential and intended only for the person(s) to whom they are addressed. If you have received the email by mistake please notify the sender immediately and delete it from your computer system. Do not copy or distribute it or disclose its contents to any person. Any improper

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Mar 2019		21 Mar 2019 16:39 Edit Adj Rpt	S\$55,717.00 Edit Estimates	S\$55,717.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	JONATHAN KWA HIAN CHOON , ID: S7724326G, Tel: +6590039119, Email: NOEMAIL								
Vehicle Reg. No.:	SKR319G	Date of Loss:	15/03/2019 08:00 - :59 [4 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D201202C01/9	Policy/Cover Note No.:	DMPCSN1836771800 (Comprehensive)						
		Excess:	S\$4,000.00						
Repairer:	Eurosports Auto Pte Ltd (HQ) 24 Leng Kee Road #01-03, 159096 Leng Kee - Tel: 65655995								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/04/2019]								
Driver/Custodian:	JONATHAN KWA HIAN CHOON (41 / Male), NRIC: S7724326G, Tel: +6590039119 Email: NOEMAIL								
Adj Asg. Remarks:	survey revert, consistency of damages, economical to repair.								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> CHINA_TAIPING (23/07/2019): Alert - Adj Mandate Approved (S\$55717.00) - SKR319G - Claim Handler: Chong Boon ... CHINA_TAIPING (26/03/2019): Alert - Adj Mandate Approved (S\$52350.00) - SKR319G - Claim Handler: Chong Boon ... 									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKR319G (SNM19D201202C01/9)
 OD
 Mar 15 2019 8:00AM
 [JONATHAN KWA HIAN CHOON]
 Eurosports Auto Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)						Thumbnail	Print		
1	16/03/19 15:48	Accident Statement					1	Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	25/03/19 13:31	Adjuster Immediate Advice					1	Load HTM			
2	22/07/19 11:42	Adjuster Immediate Advice					1	Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)						Thumbnail	Print		
1	16/03/19 15:40	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>		
2	16/03/19 15:40	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>		
3	16/03/19 15:40	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>		
4	16/03/19 15:40	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>		
5	16/03/19 15:40	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>		
6	16/03/19 15:40	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>		
7	16/03/19 15:40	Accident Photo [Linked Accident Report Documents]					1	Load JPG	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	25/03/19 12:39	General View					1	Load PDF			
2	22/07/19 11:35	Reinspection Photo (1)					1	Load PDF			
3	22/07/19 11:35	Reinspection Photo (2)					1	Load PDF			
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	21/03/19 16:40	repair bill					1	Load PDF			
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)						Thumbnail	Print		
1	16/03/19 15:40	Sketch Plan [Linked Accident Report Documents]					1	Load TIF			
2	16/03/19 15:40	Sketch Plan #2 [Linked Accident Report Documents]					1	Load TIF			
3	16/03/19 15:40	Sketch Plan #3 [Linked Accident Report Documents]					1	Load TIF			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	25/03/19 12:39	MARK ESTIMATE					1	Load PDF			
2	22/07/19 11:36	SUPPLEMENTARY					1	Load PDF			

Linked Accident Report Documents

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)						Thumbnail	Print		
1	16/03/19 15:48	Accident Statement					1	Load HTM			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)						Thumbnail	Print		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	16/03/19 15:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	16/03/19 15:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	16/03/19 15:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	16/03/19 15:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	16/03/19 15:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	16/03/19 15:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	16/03/19 15:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	16/03/19 15:40	Sketch Plan	 Load TIF	
2	16/03/19 15:40	Sketch Plan #2	 Load TIF	
3	16/03/19 15:40	Sketch Plan #3	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119005166/R1VD3E2

Date: 08/08/2019

REFERENCE

Insured/Claimant: JONATHAN KWA HIAN CHOON Policy No: DMPCSN1836771800

Date of Loss: 15/03/2019

Nature of Claim: OD

Claim No: SNM19D201202C01/9

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR319G	Engine No:	2ZRV515601
Make & Model:	LOTUS ELISE, 1.6 (M)	Chassis No:	SCCLJCRC3JHC10153
Reg. Date:	12/11/2018 (Man. Year: 2017)	Odometer:	2710 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$190,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/55 R16	Rear Tyre Size:	175/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,587.00	47,287.00	300.00	0.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,980.00	8,430.00	2,550.00	23.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	58,567.00	55,717.00	2,850.00	4.87
- Excess (S\$)	4,000.00	4,000.00	0.00	0.00
(S\$)	54,567.00	51,717.00	2,850.00	5.22
+ GST 7.00/7.00% (S\$)	3,819.69	3,620.19	199.50	5.22
Nett Amount (S\$)	58,386.69	55,337.19	3,049.50	5.22

INSPECTION

Date of Assignment: 21/03/2019

Date Inspected: 22/03/2019

Inspected At:

Eurosports Auto Pte Ltd (HQ)

24 Leng Kee Road #01-03

Singapore 159096

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Aug 2019)	
Parts:	N/A	LOTUS ELISE 1.6 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR319G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LOGO	Necessary	612.00 FS	*612.00 FS
2	1		*FRONT CLAMP SHELL (BUMPER AND FRONT BODY)	Cracked	33,500.00 FS	*33,500.00 FS
3	1		*HEAD LAMP RH	Cracked	8,238.00 FS	*8,238.00 FS
4	1		*BRACKETS, RIVETS AND FASTENERS	Necessary	1,300.00 FS	*1,000.00 FS
5	4		*CASTROL EDGE PRO LL III 5W-30	Necessary	116.00 FS	*116.00 FS
6	1		*PANEL, HEADLAMP ACCESS, FRT RH	Bent	435.00 FS	*435.00 FS
7	1		*RADIATOR ELISE / EXIGE	Bent	3,310.00 FS	*3,310.00 FS
8	2		*COOLANT 1.5L (AUDI)	Necessary	76.00 FS	*76.00 FS
Total Parts (\$\$)					47,587.00	47,287.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISMANTLE, RE FITTING AND REPAIR	New	4,800.00	4,000.00
2	RESPRAY FOR FRONT BODY CLAMSHELL	New	4,500.00	3,500.00
3	SEALERS FOR BODY ATTACHMENT	New	1,200.00	450.00
4	TO REPAIR AIRCON CONDENSOR	New	250.00	250.00
5	TO SUPPLY NEW NUMBER PLATE FOR FRONT BUMPER	New	30.00	30.00
6	TO SERVICE AIRCON SYSTEM, AND RECHARGE AC GAS	New	200.00	200.00
Gross Labour Cost (S\$)			10,980.00	8,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >