

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmala D/O Raja Singam

Date: 17 Apr 2019

Preliminary Advice

Vehicle No	: SKK8773L	Accident Date	: 15/03/2019
Make	: MERCEDES-BENZ E250	Policy No.	: 28629631
Assignment Date	: 21/03/2019	Excess	: S\$500.00
Date of Inspection	: 22/03/2019	Est. Duration of Repair	: 8 days
Inspection At	: Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,913.73
Revised Amount	:S\$	15,283.86
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,283.86
Lump Sum Repair	:S\$	14,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	41,241.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,759.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.