

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Vimmala D/O Raja Singam

Date: 25 Mar 2019

## Preliminary Advice

Vehicle No	: SKK8773L	Accident Date	: 15/03/2019
Make	: MERCEDES-BENZ E250	Policy No.	: 28629631
Assignment Date	: 21/03/2019	Excess	: S\$500.00
Date of Inspection	: 22/03/2019	Est. Duration of Repair	: 8 days
Inspection At	: Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,913.73
Revised Amount	:S\$	16,356.33
Check Items (Estimated)	:S\$	3,773.15
Total	:S\$	20,129.48
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	41,241.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,759.00

### Remarks

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.