

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0365/2019/KN
Date : 21-Mar-19

Vehicle IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Speers Peter Francis
Address : 83 Science Park Drive
#04-04
Singapore 118258
Telephone : 91252880
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SKU 1749 B**
Model Code : Q5 2.0 SEDAN TFSI
Model / Year : 31/1/2019
Engine No : CNC 096016
Chassis No : WAUZZZ8R5FA079511
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Mar-19
Place of Accident : BASEMENT 2 OF D'LEEDON CONDO BUILDING

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimated Labour Charges for Accident Vehicle SKU 1749 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer RHS front door's multi lock system and power window devices. Check function.	S/N \$ 280.00	✓
2	To dismantle and renew RHS front door and RHS wing mirror assy. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00	750.
3	To respray front door, door cover and RHS wing mirror cover and RHS upper A-pillar.	\$ 2,500.00	Door, Door Pillar : 1100 Door Cover 250 Mirror Cover 150
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,372.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Material List for Accident Vehicle Regn No. SKU 1749 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - RHS <i>Dented</i>	\$ 2,829.00	✓
2	GROMMET COVER FOR DOOR - OUTER <i>new</i>	3 \$ 8.00	+
3	OUTER DOOR SEAL - RH <i>new</i>	\$ 185.00	✓
4	BONDING AGENT <i>2</i>	\$ 45.00	+
5	CLEANING SOLUTION <i>new</i>	\$ 65.00	+
6	APPLICATOR	\$ 7.00	+
7	DOOR CATCH - LH / RH <i>new</i>	\$ 132.00	+
8	COVER FOR DOOR CATCH - LH/ RH <i>new</i>	\$ 14.00	+
9	ATTACHMENT PARTS FOR DOOR <i>?</i>	\$ 117.00	?
10	EXTERIOR MIRROR MOUNTING - RH <i>Missing</i>	\$ 1,121.00	✓
11	MIRROR CAP - RH <i>could</i>	\$ 382.00	✓
12	MIRROR GLASS - RH <i>Missing could ?</i>	\$ 1,553.00	✓
13	TURN SIGNAL INDICATOR - RH <i>could</i>	\$ 149.00	✓
14	PERIPHERAL LIGHT - RH <i>missing</i>	\$ 196.00	✓
15	LOUDSPEAKER TRIM - RH	\$ 42.00	+
16	RETAINER FOR ROOF MOULDING - RH <i>new</i>	\$ 3.00	+
17	MOULDING FOR ROOF - RH	\$ 574.00	+
18	WINDOW SLOT SEAL WITH TRIM STRIP - RH <i>new</i>	\$ 285.00	+
19	WINDOW SEAL - RH <i>new</i>	\$ 31.00	+
20	COVER FOR DOOR - RH <i>new</i>	\$ 467.00	✓

SUB TOTAL SPARE PARTS

: \$ 8,205.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Material List for Accident Vehicle Regn No. SKU 1749 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	DATA PLATE FOR TYRE PRESSURE <i>mm</i>	\$ 26.00	<i>/</i>
22	SUNDRIES <i>?</i>	\$ 500.00	<i>?</i>
SUB TOTAL SPARE PARTS		\$ 8,731.00	
TOTAL LABOUR CHARGES		\$ 4,372.00	
GRAND TOTAL		\$ 13,103.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lim

Surveyed Date

: 22/03/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 05 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant