

1/03/2001

ASS. REC. BY:

REF: CS/CTI19005263/d3

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

of

CTI

Date/Time:

25/3/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8TF7898E

Insured:

YP591E

at Workshop m/s JEC Automotive

Tel:

65096585

of 1 Kaki Bukit Ave 6 #02-11

Policy No: DMCVEN30776618000

Claim No:

SNM19D201263C02

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

19/3/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	8TF7898E -X
	YP591E -X.
7/1/21	Cancel case. Double reference. Insurance give wrong vehicle number. Please refer to CS/CTI19005163/Avd37 vehicle should be 8TIS898Y.

7/1/2021

Celine Fong (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 25 March 2019 2:40 PM
To: Admin-D (LKKAuto)
Cc: assignments
Subject: RE: (OUR REF: SNM19D201263-YP591E) Urgent: Pre-Repair Inspection: Your Vehicle: YP 591 E; JEC's Vehicle: SJJ 5898 Y; ACCIDENT INVOLVING SJJ 5898 Y & YP 591 E ON 19 March 2019

Done

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 25 March, 2019 2:05 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: assignments <assignments@lkkauto.com>
Subject: RE: (OUR REF: SNM19D201263-YP591E) Urgent: Pre-Repair Inspection: Your Vehicle: YP 591 E; JEC's Vehicle: SJJ 5898 Y; ACCIDENT INVOLVING SJJ 5898 Y & YP 591 E ON 19 March 2019

Dear Boon Sen,

Kindly assist to amend the TP vehicle number in merimen.

TP vehicle number is SJJ 5898Y and not SJF 7898E.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)