



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 22/03/2019

Attn: The Motor Claims Department
Your Insured veh no : SMH 112 P
AIG ASIA PACIFIC INSURANCE PTE LTD.
78 Shenton Way
07-16 Chartis Building
Singapore 079120

WITHOUT PREJUDICE

(By Email Only)

Dear Sir / Madam

Estimate Cost repair Bill To Mit Lance SGT 9751 T & SMH 112 P on 19/03/2019

To Supply :-

1pc	Front bonnet <i>Painted</i>	\$ 751.00	nett ✓
1pc	Front head lamp RH <i>changed</i>	\$ 549.00	nett ✓
1pc	Front fender RH <i>Area</i>	\$ 573.00	nett ✓
1pc	Front bumper <i>Painted</i>	\$ 773.00	nett ✓
1pc	Front bumper side bracket <i>m</i>	\$ 125.00	nett 36
		\$2,771.00	
	less	10%	\$ 277.10
			\$2,493.90

To dismantl & replace damage parts, panel beat where necessary.

\$ 780.00 *400*

To putty, apply primer & spray paint on the affected portion.

\$ 850.00 *400*

To remove upholstery.

\$ 100.00 *x*

To check wiring functions.

\$ 80.00 *30*
\$4,303.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total: 2728.10 *Adrian Lim*
h/s: 2150 *4/3 27/03/19*
04 Days