

> Back to OneMotoring

Enquiry on Vehicle Recall - Vehicle Specific

* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

| Vehicle Owner Particulars | | |
|------------------------------|---|---|
| Owner ID Type: | Singapore NRIC | |
| Owner ID: | 1802E | |
| Vehicle Details | | |
| Vehicle Registration number: | SJM8954H | |
| Make: | SUZUKI | |
| Vehicle Model: | SX4 1.6HB AT | |
| Engine No.: | M16A1444469 | |
| Chassis No.: | JSAGYA21S00203790 | |
| Recall Details | | |
| 1 | Recall No.: | R2010110062 |
| | Manufacturer Recall Date: | 15 Oct 2010 |
| | Estimated Completion Year of Recall: | 2013 |
| | Brief Description (As Provided by Motor Dealer): | Due to absence of pre-coated adhesive (thread lock) on three (3) screws on the outside rear view mirror base, the screw(s) may work loose and cause vibration of mirror itself resulting in the visibility performance decreased. |
| | Date Rectified: | 05 Jan 2011 |
| | For more details, contact CHAMPION MOTORS (1975) PTE. LTD. | |
| | Hotline Information: | Champion Motors at 66311118 |

OK