Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Wednesday, 10 April 2019 3:14 PM

To:

Ng Sin Hai

Cc:

assignments; CS A Team; Admin A

Subject:

RE: 3rd party direct settlement SLQ7584D/ & your insured

GBB9339E/DOA:20/03/2019/Est \$ *** LKK REF: CC4/ASM19005405/pa3

Without Prejudice

Dear Sirs/Mdm.

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Sent: Monday, 8 April 2019 11:30 AM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: assignments <assignments@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com> Subject: RE: 3rd party direct settlement SLQ7584D/ & your insured GBB9339E/DOA:20/03/2019/Est \$ *** LKK REF: CC4/ASM19005405/pa3

Dear All,

May I know how long do I have to wait this direct case to get the liability clearance???

Thank you and have a nice day, @

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

DID: 6471 5419 HP: 9072 1769

E-mail: shng@honda.com.sg





CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Ng Sin Hai

Sent: Wednesday, 3 April, 2019 12:55 PM

To: 'Hsiao Tong (LKKAuto)' < chewht@lkkauto.com">chewht@lkkauto.com

Cc: assignments <assignments@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: 3rd party direct settlement SLQ7584D/ & your insured GBB9339E/DOA:20/03/2019/Est \$ *** LKK REF:

CC4/ASM19005405/pa3

Dear All,

This is a direct hit from the rear, I don't understand why is there a need to take so long for the clearance.

Thank you and have a nice day, @

Warmest Regards,


Ng Sin Hai

Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419

DID: 6471 5419 HP: 9072 1769

E-mail: shng@honda.com.sg





CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Hsiao Tong (LKKAuto) < chewht@lkkauto.com>

Sent: Wednesday, 3 April, 2019 12:01 PM

To: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Cc: assignments <assignments@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com> Subject: RE: 3rd party direct settlement SLQ7584D/ & your insured GBB9339E/DOA:20/03/2019/Est \$ *** LKK REF: CC4/ASM19005405/pa3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Our insured had reported the accident. Attached is a copy of his police report for your easy reference.

We are currently pending for a copy of authorisation to act from our insured before we could advise DS.

We will follow up and get back to you asap.

Brief Details.

On 20/03/2019 at about 1650hrs, while I was driving my company van bearing registration GBB9339E along Upper Serangoon Road towards Bendemeer Rd at the speed of 20-30k an accident with another car bearing registration plate number SLQ7584D. While I was driving documents in the car was about to drop and I trying to grab hold on it. Thereafter, I realise front of my van, suddenly came to a stop. We both alighted and exchanged particulars an privately. The front bonnet of my company van was dented whereas the rear bumper of SI dented. No one is injured due to the accident.

I am lodging this report as the driver decided to do insurance claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Sent: Tuesday, 2 April 2019 4:38 PM

To: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) < chewht@lkkauto.com >; assignments < assignments@lkkauto.com >; CS A Team < cs-

a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: 3rd party direct settlement SLQ7584D/ & your insured GBB9339E/DOA:20/03/2019/Est \$ *** LKK REF:

CC4/ASM19005405/pa3

Dear All,

Kindly advise the liability for this case as I understand that your insured has made the report since 29/03/2019.

Thank you and have a nice day, @

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937

DID: 6471 5419 HP: 9072 1769

E-mail: shng@honda.com.sg



4

Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

From: Mei Kwan (LKKAuto) < Meikwan@lkkauto.com>

Sent: Tuesday, 26 March, 2019 5:09 PM

To: Ng Sin Hai < shng@kahmotor.onmicrosoft.com>

Cc: Hsiao Tong (LKKAuto) < chewht@lkkauto.com >; assignments < assignments@lkkauto.com >; CS A Team < cs-

a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: 3rd party direct settlement SLQ7584D/ & your insured GBB9339E/DOA:20/03/2019/Est \$ *** LKK REF:

CC4/ASM19005405/pa3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Please be informed that OI has yet to report the accident and we are currently **pending verification for direct** settlement.

Please provide us the following and arrange for TP survey.

- Evidence i.e. video/ scene photo.
- Estimate cost of repair

Please note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai < shng@kahmotor.onmicrosoft.com>

Sent: Monday, 25 March, 2019 8:26 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Subject: RE: 3rd party direct settlement SLQ7584D/ & your insured GBB9339E/DOA:20/03/2019/Est \$

Dear Motor Claims,

Please refer to the attached pdf, we are assisting our insured vehicle SLQ7584D to file a 3rd party claim against your insured vehicle GBB9339E and to request for direct settlement.

Please assist and expedite to check the claim liability soonest.

Thank you and have a nice day, @

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937

DID: 6471 5419 HP: 9072 1769

E-mail: shng@honda.com.sg



CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited.

If you have received this message in error, pyou for your collaboration.	blease immediately notify the sender and delete the mail. Thank
	6

Menu



<TP - Mandate IA> - S9M01I3Y [ACCIDENT INVOLVING GBB 9339E(OI) & SLQ 7584D(TP) ON 20/03/2019]

Type

Question

Message

Liability: 100%. Insured driver rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$7,676.45(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 05 June 2019

Reply



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX: (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 5/6/2019

Survey Details:

Date of loss	20-Mar-19
Date of appointment	26-Mar-19
Date of survey	29-Apr-19
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM		
Vehicle number	SLQ7584D		
Make and Model	HONDA HRV 1.5 LX CVT		
Date of registration	21-Jul-17		
Parf Rebate			
Market Value	\$ 80,00		
Parf Rebate	\$ 47,977.0		
Nett Loss	\$ 32,023.00		

Repair details:

The state of the s	
Initial Estimate	\$ 14,498.59

Proposed/Revised repair cost:

Parts	\$ 1,235.89
Check items (estimate)	NIL
Labour	\$ 5,480.00
Total	\$ 6,715.89
Lump Sum(if applicable)	\$ -

Number of days for repair	6
---------------------------	---



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 7,189.00	
Loss of use	\$ 480.00	(8days x \$60.00)
Loss of rental	NIL	no. of days
Loss of income	NIL	no. of days
LTA search fees	\$ 7.45	
Others	NIL	
Proposed Total	\$ 7,676.45	

Menu



Service Request Details

Claim

S9M01I3Y

Reference

CC4/ASM19005405/R1pa3 2

Loss Date

20 March 2019

Report Date

26 Mar 2019 9:09:24 AM

Request Date

26 March 2019

Due Date

26 March 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

ctions		
ext Step		
nish the work		
Complete Work	More ▼	

Vehicle Information

SUBJECT

BODY

LKK AUTO CONSULTANTS PTE LTD (TP) ▼ Menu маке TPVD HONDA Model HR-V-1.5 (A) Service Address Primary Contact/Insured NETWORK EXPRESS COURIER SERVICES PTE LTD 46 HORNE ROAD, NETWORK COURIER BUILDING, 209068, Singapore 62933303 Claim Handler WANG Peter peter.wang@axa.com.sg Additional Instructions NON-REPORTED Messages Invoices History Documents Metrics Notes Assessment New Message TYPE 0 SENT 6/6/19 11:12 AM FROM WANG Peter

Pls proceed DS with quantum as proposed

Menu

IYPE

0

SENT

5/6/19 2:53 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

<TP - Mandate IA> - S9M01I3Y [ACCIDENT INVOLVING GBB

9339E(OI) & SLQ 7584D(TP) ON 20/03/2019]

BODY

Liability: 100%. Insured driver rear-ended third p...



TYPE

0

SENT

10/4/19 2:57 PM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

RE: Liability clear - pls get company LOA and proceed DS with

quantum to be reviewed

BODY

Hi, I have uploaded a copy of OI LOA in SC. We wil...



TYPE

0

SENT

3/4/19 9:51 AM

FROM

WANG Peter

SUBJECT

Liability clear - pls get company LOA and proceed DS with quantum

to be reviewed

BODY

OI GIA linked to you.

LKK AUTO CONSULTANTS PTE LTD (TP) -

Menu

TYPE

0

SENT

28/3/19 2:42 PM

FROM

WANG Peter

SUBJECT

OI non-reporting

BODY

Pls follow up



Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 11 June 2019 6:19 PM

To:

shng@kahmotor.onmicrosoft.com

Cc: Subject: Rasul (LKKAuto); Vivian Lau (LKKAuto)

Attachments:

RE: Submission Pre-Invoice for vehicle SLQ7584D FINALISATION_MARKED.pdf

Without Prejudice

Dear Sirs/Mdm.

For COR, recommended amount at P/P \$6,715.89(before GST) with 6 repair days. Kindly refer to the attached for your reference.

Kindly confirm.

** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Sent: Wednesday, 8 May 2019 8:23 PM

To: Rasul (LKKAuto) < Rasul@lkkauto.com>; SUR < sur@lkkauto.com>

Subject: RE: Submission Pre-Invoice for vehicle SLQ7584D

Dear Rasul,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle.

Cost of repair: \$7,195.89 (before GST) No of working days: 06 days. (LOU)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy.

Thank you and have a nice day, @

Warmest Regards,

Ng Sin Hai **Kah Motor Co. Sdn. Bhd** (A member of Oriental Holdings Berhad)

Body Repair & Paint Centre 255 Alexandra Road

Singapore 159937

DID: 6471 5419 HP: 9072 1769

E-mail: shng@honda.com.sg



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

Hsiao Tong (LKKAuto)

From: Desmond Toh <desmondtoh@honda.com.sg>

Sent: Saturday, 14 September 2019 12:20 PM

To: Hsiao Tong (LKKAuto)
Cc: Jerome Tan; Winson Chow

Subject: FW: SLQ7584D - TP CLAIM AGAINST GBB9339E DOA: 20.03.2019

Attachments: 4262_001.pdf

Your Ref: GBB9339E

Our Ref: SLQ7584D

M/s: AXA Insurance Singapore Pte Ltd

C/o: LKK Auto Consultants Pte Ltd

8 Shenton Way #27-01 AXA Tower Singapore 068811

Attn: Case Handler

Dear All,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

We'll appreciate if you could reply to us once receive this mail.

Best Regards

Desmond Toh

Contact No. 65145848

Kah Motor Co Sdn Bhd

Website: www.honda.com.sg





Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Hsiao Tong (LKKAuto)

From:

Desmond Toh <desmondtoh@honda.com.sg>

Sent:

Saturday, 5 October 2019 9:11 AM

To:

Hsiao Tong (LKKAuto)

Cc:

Jerome Tan; Winson Chow

Subject:

RE: SLQ7584D - TP CLAIM AGAINST GBB9339E DOA: 20.03.2019

Dear Hsiao Tong,

We have accepted the offer.

Best Regards

Desmond Toh

Contact No. 65145848

Kah Motor Co Sdn Bhd

Website: www.honda.com.sg



From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Sent: Saturday, 5 October, 2019 8:37 AM

To: Desmond Toh <desmondtoh@honda.com.sg>

Cc: Jerome Tan <jerometan@honda.com.sg>; Winson Chow <winsonchow@honda.com.sg>

Subject: RE: SLQ7584D - TP CLAIM AGAINST GBB9339E DOA: 20.03.2019

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

AND THE PROPERTY OF THE PROPER	\$ 7,665.99
2. Loss of Use (8days x \$60.00)	\$ 480.00
Cost of Repair (w/GST)	\$ 7,185.99

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) From: Desmond Toh < desmondtoh@honda.com.sg > Sent: Saturday, 14 September 2019 12:20 PM
To: Hsiao Tong (LKKAuto) < chewht@lkkauto.com >

Cc: Jerome Tan < jerometan@honda.com.sg>; Winson Chow < winsonchow@honda.com.sg>

Subject: FW: SLQ7584D - TP CLAIM AGAINST GBB9339E DOA: 20.03.2019

Your Ref: GBB9339E

Our Ref: SLQ7584D

M/s: AXA Insurance Singapore Pte Ltd

C/o: LKK Auto Consultants Pte Ltd

8 Shenton Way #27-01 AXA Tower Singapore 068811

Attn: Case Handler

Dear All,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

We'll appreciate if you could reply to us once receive this mail.

Best Regards


Desmond Toh

Contact No. 65145848

Kah Motor Co Sdn Bhd

Website: www.honda.com.sg





Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Kah Motor Co. Sdn. Bhd.

A Member of Oriental Holdings Berhadl
Body Repair & Peint Centre
8A Mendai Estate
Singapore 729903
Tel: +65 6841 3838
Fax: +65 6362 5015

www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd

Date : 5/9/2019

8 Shenton Way

#27-01

Singapore 068811

Attn: Motor Claims Department

Your ref : GBB9339E

Our ref : SLQ7584D

Dear All,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SLQ7584D AND GBB9339E ON 20/03/2019.

We refer to the item(s) marked (✓) below:

- (✓) We refer to your email dated 10/04/2019
- (🗸) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- () Kindly forward the discharge voucher for our client's signature within <u>2 weeks</u> via email to: desmondtoh@honda.com.sg
- (<) We return your discharge voucher duly completed.
- (V) Kindly expedite settlement the following:-

Repair Cost S\$7,185.99 payable to Kah Motor Co. Sdn. Bhd.

Repair Cost S\$7,185.99 payable
Loss of RENTAL

Loss of Use

S\$60.00 X 9 days=S\$540.00 payable to YUEN MUN FONG HELENA (INCLUDING 01 SAT 01 SUN 01 PRI)

LTA Search

- (/) Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.
- (
 Letter of Authority

Thank you.

Yours faithfully,

Ng Sin Hai



Service Tax Invoice

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No.: +65 6841 3838 Fax No.:

MOTOR CLAIMS DEPT 8 SHENTON WAY #27-01 AXA TOWER

SINGAPORE, 068811

Customer Code: CU0129734

AXA INSURANCE S'PORE PTE LTD

Payment Term: 30 Days

GST Reg No.

M200050223

Company Ref. No. S60FC1380G

SINV-BM19001429 Invoice No. 27/08/19 Invoice Date

SVO19026992 Order No.

Reference Job Card No.

10551 10/04/19 / 3:15:31 PM Date/Time Received

SLQ7584D Licence No. HRV LX-SIN CVT YM 2016 Model JHMRU1830GX202640 Car Chassis No.

L15B4532640 Car Engine No. Mileage 19834

Service Advisor NG SIN HAI 1596 SHNG Served By

Page

Sales and the sa		EV 855588	2000	SUPPLY WILL				7% GST Am	
No.		Description	Qty.	UoM	U. PriceDi	sc %	Amount	Amount	GS
		TP DIRECT SETTLEMENT (J/NO:)						
		OWNER: YUEN MUN FONG HELENA							
		OWNER INSURER:							
		ACC DATE: 20/03/2019							
		SURVEYED BY: RASUL							
		DATE: 29/04/2019							
		REF NO:							
		TP INSURER: AXA INSURANCE							
		TP VEH:							
BOSUN	0701	SUNDRIES	1	Hours	30.00		30.00	2.10	32.1
BOJSE	0701	SEALANT FOR TAILGATE	1	Hours	80.00		80.00	5.60	85.6
BML02I	0701	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	Hours	180.00		180.00	12.60	192.6
BA02R	0701	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	Hours	180.00		180.00	12.60	192.6
BG02D	0701	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	Hours	560.00		560.00	39.20	599.2
BKBU01R	0701	WINDSCREEN DAMKIT	1	Hours	100.00		100.00	7.00	107.0
BKBU01R	0701	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	1	Hours	380.00		380.00	26.60	406.6
BKBU01R	0701	RESET VEHICLE SMART KEY ACCESS/ENTRY SYSTEM	1	Hours	380.00		380,00	26.60	406.6
BMI03D	0701	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	Hours	280.00		280.00	19.60	299.6
BKTG02R	0701	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	Hours	560.00		560.00	39.20	599.2
3P06R	1718	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	Hours	1,350.00		1,350.00	94.50	1,444.5
BKRP21M	1729	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN	1	Hours	1,400.00		1,400.00	98.00	1,498.0
		ALIGN CHASSIS INCLUDING FITTING ON ATT.	ACHN	ENT					
BO-WS-SEALANT		WINDSCREEN SEALANT (N)	2	Each	60.00		120.00	8.40	128.4
1505-TM8-003		CLIP,BUMPER	14	Each	2.30	25	24.15	1.69	25.8
5722-T7W-A01		EMBLEMRR.	1	Each	13.30	25	9.97	0.70	10.6
5725-T8N-T00		EMBLEM,RR. I-VTEC	1	Each	14.50	25	10.87	0.76	11.6
4715-T7A-900ZZ		FACE,RR.BUMPER	1	Each	463.70	25	347.77	24.34	372.1
1593-T7A-000		SPACER,R.RR.BUMPER SIDE	1	Each	17.20	25	12.90	0.90	13.8
8100-T7A-J20ZZ		TAIL GATE COMP	1	Each	855.70	25	641.77	44.92	686.6
3214-T7J-H01		RUBBER CR.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.4

Printed by SHNG on 27 Aug 2019 at 3:29:40 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions. Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Please give us your feedback by scanning the QR Code using mobile device.





Kah Motor Co. Sdn. Bhd.

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

(A Member of Oriental Holdi	ngs Berhad)
6A Mandai Estate, SINGAPORE	729903
Mandai Parts Centre	

	29 (9) (15)			
Mandai Parts Centre	Invoice No.		SINV-BM19001429	
Phone No.: +65 6841 3838 Fax No.:	Invoice Date	:	27/08/19	
	Order No.	:	SVO19026992	
	Reference	:		
AXA INSURANCE S'PORE PTE LTD	Job Card No.	:	10551	
MOTOR CLAIMS DEPT	Date/Time Received		10/04/19 / 3:15:31 PM	
8 SHENTON WAY	Licence No.	2	SLQ7584D	
#27-01 AXA TOWER	Model	:	HRV LX-SIN CVT YM 2016	
SINGAPORE, 068811	Car Chassis No.	:	JHMRU1830GX202640	
	Car Engine No.	:	L15B4532640	
	Mileage	:	19834	
	Service Advisor	:	NG SIN HAI 1596	
Customer Code: CU0129734	Served By	:	SHNG	
Payment Term: 30 Days	Page		2	

							7% GST Am	ount incld
No.	Description	Qty.	UoM	U. PriceD	isc %	Amount	Amount	GST
73226-SZW-000	DAMPERSTD 5X5	1	Each	8.50	25	6.37	0.45	6.82
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	Each	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	Each	4.80	25	3.60	0.25	3.85
91501-S70-003	FASTENER BW/SHIELD	4	Each	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	Each	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	Each	3.80	25	5.70	0.40	6.10
		Sum Sum	Labor Item			5,480.00 1,235.89	383.60 86,50	5,863.60 1,322.39
		Total	SGD			6,715.89	470.10	7,185.99

Total Payable (SGD) 7,185.99





5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	nationale Des Experts En Auton	nobile	
AXA	INSURANCE PTI	E LTD	Ref : CC4/ASM1900	5405/R1pa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		ORE 068811	Date: 14-10-2019 Code: ASM		
1.	N: PETER WANG				
1.	Insured Veh.	GBB 9339E	ars :- THIRD PARTY CLA		
	Policy No.	VFX/P1986584	Veh. Inspected	SLQ 7584D	
-	Claim No.	S9M01I3Y	Coverage (\$)	0.00	
	Assign From	PETER WANG	Excess (\$)	0.00 26/03/2019	
^	Assign From		Assign Date	26/03/2019	
2.	Make & Model	HONDA HRV 1.5 A	articulars & Condition		
			c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JHMRU1830GX202640	Colour	BROWN	
_	Odometer	027383	Steering	IN ORDER	
_	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.			ditions of Tyres		
_		Size	Make	Balance	
_	R/H Front Tyre	215/60 R16	DUNLOP	5 mm	
	L/H Front Tyre	215/60 R16	DUNLOP	5 mm	
	R/H Rear Tyre	215/60 R16	DUNLOP	5 mm	
	L/H Rear Tyre	215/60 R16	DUNLOP	5 mm	
4.			ption of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.		
	DAMAGES SEE D	ETAILS.			
5.		Gen	eral Information		
	Accident Date	20/03/2019	Inspection Date	29/04/2019	
	Survey held at KAH MOTOR CO SDN BERHAD				
		NO. 255 ALEXANDRA ROAL SINGAPORE 159937)		
5a.			Remarks		
	A)THE INSPECTION	ON WAS CONDUCTED ON A"	WITHOUT PREJUDICE" BAS	IS.	

Estimate Days of Repair

6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 7584D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
	REPLACEMENT OF PARTS				
2	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	120.00	120.00	
36,75	CLIP, BUMPER (SN) (CONSISTENT)	NECESSARY	24.15	24.15	
	EMBLEMRR. (SN) (CONSISTENT)	NECESSARY	9.97	9.97	
	EMBLEM,RR. I-VTEC (SN) (CONSISTENT)	NECESSARY	10.87	10.87	
1	FACE,RR.BUMPER (SN) (CONSISTENT)	DEFORMED	347.77	347.77	
1	REFLECTOR ASSYR.RR. (SN) (CONSISTENT)	SERVICEABLE	117.22		
	REFLECTOR ASSYL.RR. (SN) (CONSISTENT)	SERVICEABLE	117.22	-	
	SPACER R.RR.BUMPER SIDE (SN) (CONSISTENT)	NECESSARY	12.90	12.90	
	SPACERL.RR.BUMPER SIDE (SN) (CONSISTENT)	NOT NECESSARY	8.62	-	
1	FACER, RR, BUMPER CORNER (SN) (CONSISTENT)	SERVICEABLE	70.57		
1	FACEL.RR.BUMPER CORNER (SN) (CONSISTENT)	SERVICEABLE	70.57		
1	PANEL COMPRR. (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	279.82		
1	TAIL GATE COMP (SN) (CONSISTENT)	BENT	641.77	641.77	
	WEATHERSTRIP TAILGATE (SN) (CONSISTENT)	SERVICEABLE	74.02		
1		SERVICEABLE	59.17		
1	ANTENNA ASSYL.F. (SN) (CONSISTENT)	SERVICEABLE	44.47		
100	BUZZER ASSYSMART (SN) (CONSISTENT)	SERVICEABLE	45.30		
4		SERVICEABLE	320.00		
1	RUBBER CR.WINDSHIELD DAMPER (SN) (CONSISTENT)	NECESSARY	14,47	14.47	
	DAMPERSTD 5X5 (SN) (CONSISTENT)	NECESSARY	6.37	6.37	
		NECESSARY	14.47	14.47	
1	CAPPIVOT (SN) (CONSISTENT)	NECESSARY	3.60	3.60	
_	FASTENER BW/SHIELD (SN) (CONSISTENT)	NECESSARY	15.90	15.90	
1	FASTENER B (SN) (CONSISTENT)	NECESSARY	7.95	7.95	
	FASTENER AW/SHIELD (SN) (CONSISTENT)	NECESSARY	5.70	5.70	
N 333	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00	
	SEALANT FOR TAILGATE (SN) (CONSISTENT)	NECESSARY	80.00	80.00	
- 63	SEALANT FOR REAR END PANEL (SN) (CONSISTENT)	NOT NECESSARY	80.00	0	
- 23	WINDSCREEN DAM KIT (SN) (CONSISTENT)	NECESSARY	100.00	100.0	
			2,802.8	7 1,445.8	

Report Ref No. CC4/ASM19005405/R1pa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	BODY UNDERSIDE COATING.	NOT NECESSARY	450.00	
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		180.00	180.00
	REMOVE & RENEW REVERSE SENSORS.		180.00	180.00
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	250.00	
	REMOVE & INSTALL RR. WINDSCREEN.		560.00	560.00
	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION.		480.00	380.00
	RESET VEHICLE SMART KEY ACCESS / ENTRY SYSTEM.	l	480.00	380.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		560.00	280.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &		560.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		3,000.00	1,350.00
	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN. INCLUSIVE OF THE REPAIR OF PANEL COMPRR.		5,000.00	1,400.00
	Profession (1996)		11,700.00	5,270.00
	GRAND TOTAL		14,502.87	6,715.89

RECOMMENDED COST OF REPAIRS	6,715.89

Report Ref No. CC4/ASM19005405/R1pa3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

10

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part, Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.