

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Friday, 5 July 2019 5:25 PM
To: Chee-Heng.Loh@aig.com
Cc: Admin A
Subject: SEEK MANDATE - AIG REF: TP / 6316597873SG [ACCIDENT INVOLVING SLH3401Y (OI) AND SKN7575H (TP) ON 21/03/2019]

Tracking:	Recipient	Delivery
	Chee-Heng.Loh@aig.com	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 5/7/2019 5:25 PM
	olivialau@lkkauto.com	Delivered: 5/7/2019 5:25 PM
	shupeil@lkkauto.com	Delivered: 5/7/2019 5:25 PM

AIG Ref: TP / 6316597873SG
LKK Ref: CC3/AIG19005411/Ekb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLH3401Y (OI) AND SKN7575H (TP) ON 21/03/2019

We refer to the above matter.

Our Insured driver travel straight without stopping at the line. We are of the opinion that BOLA scenario 4(a) is applicable for this matter. The liability is not in our Insured's favour.

We seek your approval to offer to Third Party repairer, "**Performance Motors Ltd** " as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 32,824.02	\$ 22,686.51
2. Loss of Rental (10 days x \$180)	\$ 1,800.00	\$ 1,800.00 (10 days x \$180)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 34,626.02	\$ 24,488.51

**8days recommendation for repair + 1 Sunday + 1 PRS = 10 days

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate in Merimen.

Best Regards,
Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)