



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19005414/T1ga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER			Date : 16-09-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	S 1201CD	Veh. Inspected	SBS 6320M
	Policy No.		Coverage (\$)	0.00
	Claim No.	S9M01115	Excess (\$)	0.00
	Assign From		Assign Date	26/03/2019
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CITARO O530	c.c	6374
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WEB62808323123798	Colour	GREEN
	Odometer	307516	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	GOODYEAR	8 mm
	L/H Front Tyre	275/70 R22.5	GOODYEAR	8 mm
	R/H Rear Tyre	275/70 R22.5 (D)	GOODYEAR	8/8 mm
	L/H Rear Tyre	275/70 R22.5 (D)	GOODYEAR	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/03/2019	Inspection Date	04/04/2019
	Survey held at	TOWER TRANSIT SINGAPORE PTE. LTD. 21 BULIM DRIVE SINGAPORE 648170		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	