

Your Ref : S9M01I10

Date: 10th April 2019

Our Ref : CS/ASM19005417/Dvd3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Yvonne Ang

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGG 1769P
ACCIDENT ON 25/03/2019**

Instruction was received to inspect the vehicle Reg. No. SGG 1769P. The inspection was conducted on 28/03/2019 at the premises of M/s Progressive Car Care Pte Ltd, Blk 3022A Ubi Road 1 #01-45/46, Singapore 048716.

The following vehicle information was recorded:

Registration Number	: SGG 1769P
Make/Model	: Toyota Wish
Year of Registration	: 2006
Body Colour	: Silver
Chassis Number	: ZNE100300406
Engine Capacity	: 1794 cc

The vehicle caught fire at its engine compartment. The cause of fire due to electric nature.
(Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 17,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 9,605.00)
Nett Liability	<u>S\$ 7,395.00</u>

Vehicle Inspected By:



ANG BRYAN TANI
Automotive Assessor / Investigator



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.