R.	CS /EGI 180		1 Klg q3-1/ IDAC:	12/1.0
Ka luin	-77 1	/2018	Date / Time :	10/2/27
1- or (A1.4)				
PTF	3613/1		Registered in Mertinen.	
	,			
o. : GBF 71201	<u> </u>	Claim No.		
1		Policy No.	:	
	HP:	Make / Mode	1 :	
	_	Place of Acci		
A	Self or a light of the self-		00000.00	
	THIRD OF MODIGER	OLGIA BUD	annama ara mara na	mont (me)
	CUR (VER INGS		7	
140	(VILL IDST NO)	msured Liani	my: 56 Final:	108/200
INS	ps.	DISDS.		NSRS:
		wsp:	<i>tt</i> 11	VSP:
	P P	Tel:		d:
100 -071	1/04/1		107 - 107	iability:
Ron	K5.	RMAS:		MKS:
She (2000) - An Art	Hannagar Gur - na A -	201000		
				DATE/PIC
100 H N			Non-Reporting ltr (2nd):	
atter It to		ALLEPTANIE -	Non-Reporting ltr (Final):	4
	Chinate 2004.1);
TP LOWWHAY Pro	PESE Aldral IVIN \$5	08.00	After call itr to Oi:	
	100		Documentation Check List:	Handler Typist
		d. Ho pass	Notification ltr (if non-pickup	
			After call ltr to Ol:	
SULL ANTE TO VISI	ON TO LIBOR			
			Towing Invoice	
			LTA/GIA;	
			Medical Bill:	12
			PIR:	
			The same of the sa	
Date/Time:	Sent By:			R 1
				BH
Date/Time;	Confirm with:		Confirm by:	
S\$ (- days) Reduction:	% '	Email	Call
	The second second second second second		Emnil Call	
	d / Assessed) BOLA S/N No.:			
The state of the s	6 down X 6108. 93	WIGST	KLAY EVIDED IF	
		Cortellar	20058	PMS2
			100531	- pill
	LOR + LOI Tick only on	e]	10126	1911
S\$ — S\$ —	(e.g. Tow/ Independe	nt \	1) Claim status: Normal/Rej	ect/Private Settle
7.7	(e.g. 10w/ independe	ui j	2) Report Format: 1/ 3) Survey fee: 10-40.)- +DD = 4.190)
8\$			100	
ss 5149 58	Global Sum SS: 5100	UO		
SS 5149 58 Date/Time:	Confirm with:	ΠQ	Email Call	
ss 5149 58	Confirm with:	towattre le	Email Call	
	PTE O. : GBP 71201 O. : GBP	ASSIGNATION ASSIG	ASSIGNMENT OS /11/2018 /FTE o. : GBF F120 k Claim No. Policy No. HP: Make / Mode D.O.A: 78 /11 /2018 Place of Acci (YES / NO) Nature of Accident: me / Age: OI GIA REP Insured Liabi INSRS: WSP: Tel: Liability: Liability: RMKS: WSP: Tel: Liability: RMKS: Shc (4444 - 100 / 12 1200 0444 / 84 - 100 ft	ASSIGNMENT OF / 11/2016 Date / Time : Registered in Merimen: / PTE O. : G B F 1/20 k Claim No. : Policy No. : HP: Make / Model : DO.A.: Of / 11/2016 Place of Accident : O. (YES / NO.) Nature of Accident : OI GIA REPORT YES / NO. (TP GIA RE No. : Liability : Liabil

and for	Kalvin	1	ASSIGN	MEN	(Office)	-			
rom (Person)	You for li	6		FU	n.	E	ste/Time:	08-11-2018	256pm
Estimated Cost				В	all to:				
_	TP RES / OD I		FILL THE				GBI	F 7116K	
To lisspect Veh at Workshop in	The state of the s	Fremier	9119 rd O			Insured:	6544		
of	13	(hung)	South	five	J # 03-07				
Policy No.		2			Claim No:	68F 717	OK /RY	1/01	
Sum Insured:					Execus,			1	
Make of Veh: (Client's Record)						D	A.O.	810(1180	
CA / REV / Date/Time:	REP. / REV 2-	HRS WP	on Contact	od:	Goh -	Vo		lorsenmi:	
Date/Time	Action/lestruction	on (V) Estino	ate.					
	SHIC GHEN!	1 - 713	7011	0000	96 / Illhos e	al .		DIA LAUN	7
	BBF TIDUK	- x			1				
09/4/1803	17 revis		obain	by	soun's.				
	-			-					

Simeye: Kolvin REF:	
	SIGNMENT
From: Date:	Vehinte SHC 6464 Yr Regn: 16 Mary 2017
Estimate/Cost	Type: M.Car / M.Cycle / Bus / Van / Lorry / T / Prime Mover /
OD/TP/WS/TP RES/ OD RES/ EVA / INV / MV	Truck / Treller or
"o Inspied Vehicle No:	Make: KIA optime as 1687.
at WorkStep m/s	Colour Silver NC: Inspect Std INI NA
of the second	Sp.Reading 4 (8627 T/Radio: Insgred / Std / NI / NA
osured:	Eng/No:
Policy No.	CNO: KNA GM 414AFTT 88504
Claims No.	Gen. Cond: Good / Pir / Poor / Burnt
Sum in swed: Excess:	Steering: Inord / Jarnmed / Leaked / Burnt or
(Client's Record)	Brake: Inorder I Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD AMIm or
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Ball or Market Value: IDAC Accident Rport: Consistent?: Yes or No	Tyre Size; F: 205/60R/6 R: B5/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/ TOYO/YOKO or Maxxxx Front R/Bal. 7 mm R/Bal. 7
GIA / PR Seen: Consistent?: Yes or No	Little I I I I I I I I I I I I I I I I I I I
Est Repaire G days Res.: Yes or No	D.O.A. 8/1/4 D.O.I. 8/1/4
Lum Sum: 30 % 3 Val: Yes or No	Survey held at Prenser
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Des. of Damages : Frt 1 Rear 1 O/S 1 N/S 1,U/C 1 Rooftop or
	The U/C / Chassis frame / Body Structure affected due to collision.
	. (Red 62977.70, 43%) EGI
25/11/18 Library ch \$420/ 4/2,	
RECEIVED	2 6 1/0V 2018
	The state of the s

Date / Time	Action / Instruction	
Date / Time	Library of \$420/ 4/2. (Red & 2977.70, 42%)	562
		45.
	RECEIVED 2 6 1/07 2018	
	E D	
Date/Time, File Fas	sid? : Prell. Report Days Of Repair: 4	

Date Time, File Return to? Final Report

4200

Report Format :

Lump Sum / I.Bd: (S

Add Fee:

: Site Insp (\$ Interview (\$. Transportation: S+RS__SI Photos Others

Tech, Invs (\$ Weekend (\$

Resurvey No. of Trip:

250

TOTAL

Survey Fee:



51 UBI AVE 1, 401-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 400933 TEL.: (065) 62563561 FAX: (065) 62564315

Your Ref: GBF 7120K/RH/pl

Date: 09th November 2018

Our Ref: CS/EGI18020222/K1qb

Without Prejudice

The Motor Claims Department ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SHC 6464U .

We thank you for the instruction on _08/11/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/11/2018 at the premises of M/s PREMIER AUTOMOTIVE and have the following to report:-

Workshop Estimate Amount	: S\$	7,179.70	- 5
Revised Estimate Amount	: S\$	4,680.50	-
"Check" Items Amount	: S\$	1,033.20	_
Market Value	: S\$		
Salvage Value	: S\$		_
Nett Value	: S\$		_

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 3 days.

We have NOT authorise repair.

Yours faithfully

Kalvin Ang Automotive Assessor

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 . SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

B-Nov-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6464 C

			4 440 00
1 pc	Boot lid And	S	1,119.00
1 pc	Boot lid lock	5	99.00
1 pc	Bootlid striker	S	21,00
1 pc	Bootlid emblem	\$	27.00
1 pc	Bootlid CRDi	5	29.00
1 pc	Boot lid rubber weatherstrip	\$	96.00
1 pc	Boot lid lower garnish	S	290.00
2 pcs	Bootlid hinges @ \$56.00	5	132.00
1 pc	End panel	5	250.00
1 pc	End panel garnish 7500	\$	74.00
1 pc	Rear n/s tail lamp	\$	421.00
1 pc	Bootlid n/s reflector	\$	350.00
1 pc	Rear bumper	\$	696.00
1 pc	Rear bumper lower cover Rear bumper side bracket o/s & n/s @ \$29.00 7/5 7/5 %	5	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 7/5	5	58.00 29
1 pc	Pear humner inner snonge	5	114.00
1 pc	Rear bumper reinforcement	5	607.00
2 pcs	Bear human stay o/s & n/s @ \$53.00	5	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 \$350	\$	36.00
1 pc	Rear bumper reflector n/s	\$	46.00
		\$	4,813.00
	Less 10%	5	481.30
		\$	4,331.70
S/NETT			
1 set	Rear bumper clips	\$	48.00
1 set	End panel inner garnish clips	\$	30.00
1 set	Bootlid lower garnish clips > **	\$	60.00
1 set	Bootlid stickers	S	100.00
1 set	Reverse sensor	5	288:00 200
1 pc	Rear bumper top protector	\$	80.00

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6464 C

Sundry	\$	50.00 20
Towing Fee	\$	50.00 - 1
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	12000 33
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	5	180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the same etc	5	900.00
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end ganel for the feature	\$	800.00 150.00 50
To apply rustproofing on the repaired and replaced panels.	\$	7,179.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kali (lla)

1+3 hys.

His Reprint plants of the state of

Enquire Transaction History

Transaction History Details

Log Date/Time:

16 Mar 2015 / 09:07:04

Receipt No.:

AACCK001-AX239-150316-000002

Asset Type:

Vehicle

Transaction Amount:

\$65,391.00

Asset ID:

SHC6464U

Channel:

AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Transaction Type:

Business Transaction

01.02 Register New Vehicle (AA)

Reference No.:

20150316090704695860

Vehicle No.:

SHC8484U

Vehicle Type:

H10 - Public Transport Taxi (Motor Car)

Vehicle Attachment 1:

Air-Con (Taxi)

Vehicle Attachment 2:

Vehicle Attachment 3:

Vehicle Scheme:

Taxi (Company)

First Registration Date: 16 Mar 2015

Original Registration

Date:

15 Mar 2015

Vehicle Make:

KIA OPTIMA 1.7(A) DIESEL

Vehicle Model:

KNAGM414MF5588504

Chassis No.: Engine Non-

D4FDEH313613 ----

Motor No.: "

Trailer Chassis No.:

Propellant:

Diesel

Passenger Capacity:

Engine Capacity:

1685

4

Power Rating:

Unladen Weight:

1584

Maximum Laden Weight:

2050

Primary Color:

Silver

Secondary Color:

Manufacturing Year:

2014

Open Market Value:

\$21,185.00

Minimum PARF Benefit: \$8,495.00

PARF Eligibility:

٧

No. of Transfer.

0

Effective Ownership Date/Time:

18 Mar 2015 09:07:04

COE No.:

2015031601002241W

COE Expiry Date:

15 Mar 2023

COE Bid Category:

Actual QP/PQP Paid

Amount:

\$51,092.00

Lifespan Expiry Date:

15 Mar 2023



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5095103893

1. Index mark and Registration Number of Vehicle

Chassis Number

2. Name of Policyholder

3. Effective Date of Insurance

4. Expiry Date of Insurance

5. Persons or Classes of Persons entitled to drive*

(a) The Pollcyholder.

(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the Ilcensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any

: SHC6464U

: 20 Oct 2017

: 31 Jan 2019

Cover : Third Party

: KNAGM414MF5588504

: PREMIER TAXIS PTE. LTD.

enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use* (a) Use as a Taxl.

(b) Use for social domestic and pleasure purposes.

This Policy does not cover

(a) Use for racing, pace-making, reliability trial or speed-testing.

(b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled

 Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Majaysia), are not to be included under these headings.

EXCESS (SECTION I) N/A EXCESS (SECTION II) : \$\$3,500 INSURE WITH COE : N/A HIRE PURCHASE COMPANY : N/A SUM INSURED : N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

: HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)

: 16 Oct 2017 17:13 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

Catherine Chong (LKK Auto)

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Thursday, 8 November, 2018 2:56 PM

To:

'admin-d@lkkauto.com'

Cc: Subject: SUR (sur@lkkauto.com)
OI: GBF7120K / TP: SHC6464C/LKK / DOA: 08/11/2018

Attachments:

SHC6464C - SAS.pdf; SHC6464C - PRS FORM.pdf; Pre-inspection SHC6464C &

GBF7120K on 08.11.18 (1.38 MB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please assist to conduct this survey from PREMIER AUTOMOTIVE SERVICES PTE LTD,

ADDRESS

: 23 CHANGI SOUTH AVE 2

#03-02

SINGAPORE 486443

PERSON TO CONTACT

: GOH WEE DEK @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE

: ROHAINI

Nate: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards, Yee Pei Li Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five Singapore 038985

OID: +65 6829 9194 Tel: +65 6829 9199 Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 9 November 2018 3:17 PM

To:

'Survey Report (ERGO Insurance Pte. Ltd.)'; Rohaini Bte Hussain

Ce:

SUR; assignments

Subject:

RE: GBF7120K / TP : SHC6464C/LKK / DOA : 08/11/2018

Attachments:

CSEGI18020222K1qb.pdf

Dear Rohaini,

Enclosed herewith preliminary advice of SHC 6464U.

Best Regards,

Shiau Chan (Ms) | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 8 November 2018 3:09 PM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg> Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: GBF7120K / TP: SHC6464C/LKK / DOA: 08/11/2018

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Thursday, 8 November, 2018 2:56 PM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: SUR (sur@lkkauto.com) <sur@lkkauto.com>

Subject: OI: GBF7120K / TP: SHC6464C/LKK / DOA: 08/11/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please assist to conduct this survey from PREMIER AUTOMOTIVE SERVICES PTE LTD,

ADDRESS

23 CHANGI SOUTH AVE 2

#03-02

SINGAPORE 486443

ERGO

ite:	08.11.20	18	e	Sent via Fax		
ur Reference:	GBF 7120	OK/RH/pl				
	SHC 6464		_			
our Raference:	3110 010			Email	weed	ek.goh@premiertaxi.com/
2:	PREMIE	ER AUTOMOTIVE SERV	ICES PTE LTI	D	lnce	nt.chus@premiertaxi.com
) Acknowledgement				
Vehicle For Inspection: SHC 6464C						
nsured's Vehic	ie:	GBF 7120K	-			
ate Of Accide		08.11.2018	-			
Ve acknowled	ge receipt of	your request for PRS on:	08.11.2018			
- compliance	with "State	Courts Practice Directions Am	endment No.1	of 2016", do se	elect an ass	essor fram
		your selection in the box ma			•	LKK
			1 100	LB.S Auto Co	neultants P	te Ltd
AIS	_	le Inspection Services Pte Ltd	LES	LKK Auto Co		and the same of th
FTA		n Consultancy Pte Ltd praisal Service	PS	Priority Servi		
JPK.	JP Knights		VAC	Vicom Ltd		
V. Your re-	quest for insp	ection does not have your client'				η.
V Your red Your red We ack V Our Inst V Others:	quest for insp quest for insp nowledge you ured's driver i		s GIA report, kindl we will assess & re ws todate.	y forward a cop	V-	itimate.
V your red Your red We ack: V Our Inst V Others:	quest for insp quest for insp nowledge you ured's driver i	ection does not have your client's ection does not have your client's ir interest for direct settlement, v has not reported the accident to	s GIA report, kindi ve will assess & re us todate.	y forward a cop	y. receipt of e	claims@ergo.com.s
V Your re- Your re- We ack	quest for insp quest for insp nowledge you ured's driver i	ection does not have your client's ection does not have your client's ir interest for direct settlement, v has not reported the accident to	s GIA report, kindl we will assess & re ws todate.	y forward a cop	y. receipt of e	itimate.
V Your re- Your re- We ack V Our Ins- V Others:	quest for insp quest for insp nowledge you ured's driver to OFFICI	ection does not have your client's ection does not have your client's ir interest for direct settlement, v has not reported the accident to	S GIA report, kindle ve will assess & re us todate. Pei U Workshop use Assessor atter Date: Time Inspector:	y forward a cop wert soon upon 682 e only: nded workshop	y. receipt of er 9 9194	claims@ergo.com.s FAX: 6829 9247
V Your re- Your re- Your re- We ack V Our ins- V Others: Prepared by: Signature: Assessor use s Assignment Di Assignment Ti	quest for insp quest for insp nowledge you ured's driver to OFFICI	ection does not have your client's ection does not have your client's ir interest for direct settlement, v has not reported the accident to	S GIA report, kindle ve will assess & re us todate. Pei U Workshop use Assessor atter Date: Time Inspector:	y forward a cop wert soon upon 682	y. receipt of er 9 9194	claims@ergo.com.s FAX: 6829 9247
V Your rei Your rei Ve ack V Our Ins V Others: Prepared by: Signature: Assessor use s	quest for insp quest for insp nowledge you ured's driver to OFFICI	ection does not have your client's ection does not have your client's ir interest for direct settlement, v has not reported the accident to	Workshop use Assessor atter Date: Time Inspector: Vehicle not at	y forward a cop vert soon upon 682 e only; nded workshop vallable at the a	y. receipt of er 9 9194 9n:	claims@ergo.com. FAX: 6829 9247
V Your re- Your re- Your re- We ack V Our ins- V Others: Prepared by: Signature: Assessor use s Assignment Di Assignment Ti	quest for insp quest for insp nowledge you ured's driver to OFFICI	ection does not have your client's ection does not have your client's ir interest for direct settlement, v has not reported the accident to	Workshop use Assessor atter Date: Time Inspector: Vehicle not at Kindly acknow	y forward a cop vert soon upon 682 e only; nded workshop vallable at the a	y. receipt of er 9 9194 on: ppointed di	claims@ergo.com.s FAX: 6829 9247

Suwanna (LKK Auto)

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 26 March 2019 9:33 PM

To:

Admin A

Cc:

CS A Team

Subject:

Fw: LOD / Accident involving SHC6464U & GBF7120K on 08.11.18 (ERGO case)

Attachments:

SHC6464U LOD.pdf; SHC6464U scene video.avi

Follow Up Flag:

Follow up

Flag Status:

Flagged

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shafawati <shafawati.rabu@premiertaxi.com>

Sent: Tuesday, 26 March 2019 7:18 PM To: Joy Irene (LKKAuto); Asher Sng (LKKAuto)

Cc: AccReport; Steve Lim; CS A Team

Subject: LOD / Accident involving SHC6464U & GBF7120K on 08.11.18 (ERGO case)

WITHOUT PREJUDICE

Dear Joy & Asher,

Your Ref: GBF7120K Our Ref: SHC6464U/SR Date of accident: 08.11.2018

We refer to the above mentioned accident.

Hereby we would like to append our losses from ERGO Insurance Pte Ltd, as insurers of vehicle number GBF7120K which their insured driver's negligence driving in the above accident.

Enclosed herewith our letter of demand, supporting documents and scene video for your kind perusal.

Kindly look into the matter and let us have your favourable reply as soon as possible.

To expedite this claim settlement, please reply to us by email.

Thank you

Regards

- Shafawati Md Rabu - Claims Settlement Assistant Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 076 | DID: 64100946 | Fax: 6214 1511

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

A Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 🔥

Cecilia Chong (LKK Auto)

From:

Shafawati <shafawati.rabu@premiertaxi.com>

Sent:

Thursday, 18 April 2019 4:01 PM

To:

Cecilia Chong (LKK Auto)

Cc:

Hsiao Tong (LKKAuto); Admin A; AccReport

Subject:

RE: Your ref: SHC 6464U (Our ref: CS/EGI18020222/K1ga3-1) *** ACCIDENT INVOLVING

GBF 7120K & SHC 6464U ON 08/11/2018 ***

Attachments:

LOA SHC6464U.pdf

WITHOUT PREJUDICE

Dear Cecilia.

We thank you for your reply.

On a without prejudice basis and without admission of liability whatsoever on our client's part and driver of SHC6464U, our client is agreeable on your offer of \$5,100/- for the settlement on the above claim.

We attached hereby the Authorisation Letter duly signed by our client for your kind attention.

Kindly let us have your settlement sum of \$5,100/- in favour of Premier Automotive Services Pte Ltd soonest possible.

Please be informed that this settlement excludes any bodily injuries arising out of the above said accident and pertains to property damages only.

Thank you.

Regards

Shafawati Md Rabu Claims Settlement Assistant Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 076 | DID: 64100946 | Fax: 6214 1511

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

📥 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 🚓

Sent: Thursday, 18 April, 2019 3:25 PM

To: Shafawati

Cc: Hsiao Tong (LKKAuto); Admin A; AccReport

Subject: RE: Your ref: SHC 6464U (Our ref: CS/EGI18020222/K1ga3-1) *** ACCIDENT INVOLVING GBF 7120K & SHC

6464U ON 08/11/2018 ***

Without Prejudice,

Dear Shafawati,

We refer to your email below.

We agreed to offering global settlement of \$5,100.00(all in). Please final confirm.

DV not required. Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: <u>CeciliaChong @lkkauto.com</u> fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shafawati [mailto:shafawati.rabu@premiertaxi.com]

Sent: Wednesday, 17 April 2019 7:02 PM

To: Cecilia Chong (LKK Auto) < Cecilia Chong@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) < chewht@lkkauto.com; Admin A < admin-a@lkkauto.com; AccReport < AccReport < AccReport@Premier-

Corp.net>

Subject: RE: Your ref: SHC 6464U (Our ref: CS/EGI18020222/K1ga3-1) *** ACCIDENT INVOLVING GBF 7120K & SHC

6464U ON 08/11/2018 ***

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email below.

For swift and amicable settlement, we counter propose global settlement at \$5,100/- (Inc PRI,4 working days + weekend).

Please consider and looking forward to your acceptance.

Thank you

Regards

Shafawati Md Rabu Claims Settlement Assistant Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443 Tel: 6214 8880 Ext 076 | DID: 64100946 | Fax: 6214 1511

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]

Sent: Wednesday, 17 April, 2019 6:20 PM

To: Shafawati

Cc: Hsiao Tong (LKKAuto); Admin A

Subject: Your ref: SHC 6464U (Our ref: CS/EGI18020222/K1ga3-1) *** ACCIDENT INVOLVING GBF 7120K & SHC 6464U

ON 08/11/2018 ***

Your Ref: SHC 6464U Without Prejudice

Our Ref: CS/EGI18020222/K1ga3-1

Dear Sirs/Mdm,

ACCIDENT INVOLVING GBF 7120K & SHC 6464U ON 08/11/2018

We refer to the above matter.

We propose settlement at a global sum of \$5,040.00(all-in).

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.


Best Regards,


Cecilia Chong | Case Handler


LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com] fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Save the Earth Print only when necessary
















YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

EFFECTIVE DATE

Class 28 Class 2A Class 2 Class 3

Motorcycles =< 200 cc
Motorcycles between 201 cc and 400 cc
Motorcycles = 400 cc
Motor cars with unladen weight =< 3000kg with =< 7
passingers, exclusive of driver; and other motor
vehicles with unladen weight =< 2500kg

07 Jun 1976 07 Jun 1978 07 Jun 1978 15 Aug 1978





This card is not transferable and is the property of the Land Transpor Authority (LTA). It must be surrendered to the LTA on request. If found please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Description

TAXI VL

Issue Date 04/06/1993



PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443 TEL:64100946 FAX:62141511 CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6464U/SR

WITHOUT PREJUDICE

20 December 2018

(AR Registered)

Attn: The Motor Claims Department

ERGO Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower 5 Singapore 038985

Dear Sir/Madam

ACCIDENT INVOLVING SHC6464U AND GBF7120K ALONG PIE - CITY (BEFORE ENG NEO EXIT) ON 08.11.2018

We have been authorized by Premier Taxis Pte Ltd, the owner of Taxi vehicle number: SHC6464U, to claim against the party/parties responsible for the damages arising from the above-mentioned accident.

Our records show that you are the insurers of vehicle number: GBF7120K at the material time of the accident with the driver of our client's vehicle, Mr. Lee Fon Kim.

As a result of the accident caused by your Insured Driver's negligent driving and/or management of your insured's Vehicle Number: GBF7120K, our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of Repairs (GST Included)	\$	4,494.00
(2) Loss of Rental - 8 Days @\$108.93 per day	S	871.44
(3) GIA Search fee	\$	2.00
	S	5,367.44

A copy of each of the following supporting documents is enclosed:

- GIA report & sketch plan of SHC6464U
- (2) Driver's I/C and Driving Licence
- (3) Final Repair Bill,
- (4) Vehicle Registration card, Certificate of Insurance, Certification Letter
- (5) Check In/Out Voucher
- (6) GIA search
- (7) Scene video (When require)

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443 TEL:64100946 FAX:62141511 CO. REG:200707743D GST REG:200707743D

Our Ref: SHC6464U/SR

We would appreciate if you could look into the subject matter and let us have your favorable offer within 14 days. If you are agreeable to the settlement of the above said claims, please forward us your discharge voucher as for our client's signature and payment made to "Premier Automotive Services Pte Ltd".

Please note that if we do not hear from you within the stipulated 14 days, we will have no alternative but to appoint our solicitor to act on our behalf to commence proceedings against you without further notice to you.

Yours faithfully,

Claims Department - Shafawati Md Rabu


Email: shafawati.rabu@premiertaxi.com

DID: 64100946

NB: We encourage all parties to liaise with us via email to expedite all matters

PS: Please quote our reference no when replying

c.c. Client - Premier Taxis Pte Ltd



WITHOUT PREJUDICE

ERGO Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower 5 Singapore 038985

Attn: The Motor Claims Department

Dear Sir/Madam,

ACCIDENT INVOLVING SHC6464U AND GBF7120K ALONG PIE - CITY (BEFORE ENG NEO EXIT) ON 08.11.2018

We, Premier Taxis Pte Ltd, the registered owner of vehicle No: SHC6464U. We hereby authorize you to release all compensation monies pertaining to the above-mentioned accident directly to our workshop, M/s Premier Automotive Services Pte Ltd. We, hereby authorize the said workshop, M/s Premier Automotive Services Pte Ltd to collect all compensation monies due to us from you or any other party, regarding the said accident.

Thank You.

Premier Taxis Pte Ltd

Date 18 04 19

Authorized Signatory



PREMIER AUTOMOTIVE SERVICES PTE LTD OFFICE: 23 Changi South Avenue 2 #01-02 S(486443) TEL: 65436676 / 65436689 FAX: 62141511 CO. REG NO.: 200707743D GST. REG. NO.: 200707743D

TAX INVOICE

DATE

13-Dec-2018

PAGE

1 OF 1

PREMIER TAXIS PTE LTD 23 CHANGI SOUTH AVENUE 2 #03-02 SINGAPORE 486443

TEM	Description Q	ΓY	U.PRICE	,	MOUNT
0	FINAL REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6464 U			\$	4,200.00
	TOTAL LUMPSUM REPAIR COSTS AS RECOMMENDE		SURVEYOR GST @ 7% GRAND TOTAL		4,200.00 294.00 4,494.00

for Premier Automotive Services Pte Ltd

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)



14 November 2018

To Whom It May Concern

Dear Sir/Madam

CERTIFICATION LETTER

This letter serves to inform that Lee Fon Kim of NRIC Number S1112958G is a registered driver of SHC6464U. Lee Fon Kim is paying daily rental rate of \$108.93 (Inclusive of GST).

Should you require further information, please contact us at 6214 8880.

Thank you.

Yours sincerely

Kellie Poh

Administration Manager

Prepared By: SY

PREMIER TAXIS PTE LTD
23 Chungi South Avenue 2
#03-02
Singapore 486443
Telephone: +65 6214 8880 Fax: +65 6214 0330
www.nrrmieriat.kenn
Co. Reg. No. 200304975H



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffies Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

RECORDS MANAGEMENT CENTRE

Third Party Insurer Enquiry

Our Ref No:

GR-18-172803

Date of Request:

08/11/2018

Your Ref No:

Online Purchase

Premier Automotive Services Pte Ltd 23 Changi South Ave 2

#01-02

Singapore 486443

Dear Sir/Madam,

Enquiry Date

08/11/2018

Enquiry By

GOH WEE DEK

Vehicle No.

GBF7120K

accident Date

08/11/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel, No.	
GBF7120K	ERGO Insurance Pte, Ltd.	27/02/2018-26/02/2019	6829 9199	

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quey #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-172803

Date of Request:

08/11/2018

Your Ref No:

Online Purchase

Premier Automotive Services Pte Ltd 23 Changi South Ave 2

#01-02

Singapore 486443

Dear Sir/Madam,

Enquiry Date

08/11/2018

Enquiry By

GOH WEE DEK

Vehicle No.

GBF7120K

ocident Date

08/11/2018

DESCRIPTION	AMOUNT (S\$)
	1.87
TP Insurer Enquiry	0.13
GST Amount	2,00
Total Amount Due (GST Inclusive)	

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

[X] GIRO [] Cash [] Cheque

REPLACEMENT	VEH	GIVEN	YES / NO
-------------	-----	-------	----------

PREMIER

CHECK IN / OUT VOUCHER

DRIVER'S NAME LEE 1	FON KIM		INDICATE AREA OF	DAMAGE HERE:
NRIC 8 1 1 1 2 9 5 8	To the second second second second	8489788	REAL	` П
TAXI REGN NO. B H C 6 4	THE PARTY OF THE P	IA OTIMA		
DATE IN TIME IN D S-T II 1 8 U.2 IF	DATE OUT	TIME OUT		\exists m
KILOMETRES IN FUEL E 1/4 1/2	IN KILOMETRES OUT	FUEL OUT E 1/4 1/2 3/4 F		
YES NO I ACKNOWELDGE AND CONFIRM TO THAT THE SAME IS IN GOOD CONTOGETHER WITH THE ACCESSOR CONJUNCTION WITH THE TEAM RECHECK IN LEE FON KIA	HAT I HAVE EXAMINED THE ABDITION AND TO MY SATISFACT INEB / ITEMS LIST ABOVE. THE ENTAL AGREEMENT. CHI A LEE FO DRIVER'S NAME LEE FO	H H M M RIVERFOR VEHICLE COLLECTION H H M M ROVE SAID VEHICLE AND TON IN EVERY RESPECT	BODY MARKINGS 1 - Light Dent	5 - Damaged
CHECKED IN BY (PREMIER'S AUTHORISED WORKS	CHECKED OUT B (PREMIER'S AUT)	Y HORISED WORKSHOP)	2 - Serious Dent 3 - Light Scratch 4 - Serious Scratch	6 – Chip 7 – Cruck 8 – Peeling
SERVICE / REPAIRS DONE		DRIVER'S REMARKS		
SERVICING OTHERS OT/BELT OARCON SYSTEM OACCIDE OTHERS OTHERS OACCIDE OTHERS OACCIDE OTHERS OACCIDE OAC	NT: DATE / TIME of ACCIDENT:			



51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL ; (065) 62563561 FAX ; (065) 62564315

To: M/s ERGO INSURANCE PTE LTD

Date: 29/04/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBF 7120K	(Insd Veh)	Your Ref. No. : GBF7120K/RH/pl
venicie No.	SHC 6464U	(TP Veh)	Our Ref. No.: CS/EGI18020222/K1ga3q2-1
Date of Accident	8/11/2018		

	100%	
: \$	4,494.00	
: \$		days
: \$	653.58	6 days
: \$	2.00	
: \$		
	5,149.58	
: \$	5,100.00	GLOBAL SUM
	: \$: \$: \$: \$ 4,494.00 : \$: \$ 653.58 : \$ 2.00 : \$

Pay	yment Instruction: Payee's Breakdown		
1)	PREMIER AUTOMOTIVE SERVICES PTE LTD	:\$	5,100.00
		: \$	

JOANNE LEE LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD CS/EGI18020222/K1qbn2 Ref :

5 TEMASEK BOULEVARD

	-01 SUNTEC TOW GAPORE 038985	ER FIVE	Date: 03-12-2018		
1.		Policy Particul	Code : EGI ars :- THIRD PARTY CLAI	IM.	
10.	Insured Veh.	GBF 7120K	Veh. Inspected	SHC 6464U	
	Policy No.	ODI 7120K	Coverage (\$)	0.00	
_	Claim No.	GBF7120K/RH/pl	Excess (\$)	0.00	
	Assign From	YEE PEI LI	Assign Date	08/11/2018	
2.	The same of the sa		articulars & Condition		
- N	Make & Model	KIA OPTIMA	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	KNAGM414MF5588504	Colour	SILVER	
	Odometer	468627	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.	E. T. C.	Con	ditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	MAXXIS	7 mm	
	L/H Front Tyre	205/60 R16	MAXXIS	7 mm	
	R/H Rear Tyre	205/60 R16	MAXXIS	7 mm	
	L/H Rear Tyre	205/60 R16	MAXXIS	7 mm	
4.		Descri	ption of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR N/S PORTION.		
5.	DAME OF THE PROPERTY OF THE PR		eral Information		
	Accident Date	08/11/2018	Inspection Date	08/11/2018	
	Survey held at	PREMIER AUTOMOTIVE SE	(F)	1500 VI Venda IVV	
		23 CHANGI SOUTH AVENU	E 2 #01-02 SINGAPORE 486	443	
5a.			Remarks		
		ON WAS CONDUCTED ON A"			
5b.	ID/IN ACCORDANC		ate Days of Repair	LU NEFAINO.	
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6464U

ty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	DENTED	1,119.00	1,119.00
1	BOOT LID LOCK	BENT	99.00	99.00
1	BOOTLID STRIKER	SERVICEABLE	21.00	
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	SERVICEABLE	96.00	
1	BOOT LID LOWER GARNISH	TO REPAIR SEE LABOUR	290.00	
2	BOOTLID HINGES @\$66.00	BENT	132.00	132.0
1	END PANEL	TO REPAIR SEE LABOUR	250.00	
1	END PANEL GARNISH	SERVICEABLE	74.00	
1	REAR N/S TAILLAMP	CRACKED	421.00	421.00
1	BOOTLID N/S REFLECTOR	CRACKED	350.00	350.0
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CUT	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	N/S CRACKED / O/S SERVICEABLE	58.00	29.00
1	REAR BUMPER INNER SPONGE	SERVICEABLE	114.00	
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S @\$53.00	SERVICEABLE	106.00	
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	SERVICEABLE	36.00	
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	SERVICEABLE	36.00	
1	REAR BUMPER REFLECTOR N/S	CRACKED	46.00	46.00
	LESS 10% DISCOUNT		-481.30	-376.10
			4,331.70	3,384.90
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NOT NECESSARY	30.00	
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NOT NECESSARY	60.00	

Report Ref No. CS/EGI18020222/K1qbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

SET BOOTLID STICKERS (SN) SET REVERSE SENSOR (SN)	NECESSARY	400.00	
SET REVERSE SENSOR (SN)	The Court Property of the Court	100.00	100.00
- I I I I I I I I I I I I I I I I I I I	SHORTED	280.00	200.00
REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
SUNDRY (SN)	NECESSARY	50.00	20.00
LABOUR		648.00	418.00
TOWING FEE.	NOT NECESSARY	50.00	_
TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.	100 min	120.00	30.00
TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME ETC. INCLUSIVE OF THE REPAIR OF BOOT LID LOWER GARNISH AND END PANEL.		900.00	600.00
TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, REAR LH FENDER.		800.00	720.00
TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		150.00	50.00
		2,200.00	1,450.00
GRAND TOTAL		7,179.70	5,252.90
TETLITATISSLITLITA	TOWING FEE. TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME. TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS. TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME ETC. INCLUSIVE OF THE REPAIR OF BOOT LID LOWER GARNISH AND END PANEL. TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, REAR LH FENDER. TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	TOWING FEE. TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME. TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS. TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME ETC. INCLUSIVE OF THE REPAIR OF BOOT LID LOWER GARNISH AND END PANEL. TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, REAR LH FENDER. TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	TOWING FEE. TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME. TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS. TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME ETC. INCLUSIVE OF THE REPAIR OF BOOT LID LOWER GARNISH AND END PANEL. TO PUTTY AND SPRAY PAINTING ON BOOTLID, BOOTLID LOWER GARNISH, REAR BUMPER, REAR LH FENDER. TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS. 150.00 120.00 180.00 180.00 180.00 2,200.00

Report Ref No. CS/EGI18020222/K1qbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

(TO ITS PRE-ACCIDENT CONDITION)

XX.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report. In whole or in part, does so at his or her own risk.