



ASS. REC. BY:

REF:

1161

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGG 3254S

Yr Regn:

01 07  
12/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy WH

c.c.

1794

Colour:

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

147202

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ENE10 0349331

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dayton

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

21/3/19

D.O.A.

26/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

1/5 - 84200 (Red 1402/281)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH6733U  
Accident Date : 21-Mar-2019

No. : 05948

Date : 25-Mar-2019

Our Ref : 219049 (AIG) / CHAN

PAGE : 1

LEE BOON KWONG  
BLK 521 HOUGANG AVE 6  
#01-53  
Singapore 530521

*Not Authorized  
61 Day @ 4200h  
Recovery After Pay*

## ESTIMATED COST OF REPAIR FOR TOYOTA WISH SGQ3254S

*5 days*

- 1 pc Tail gate
- 1 pc Tail gate glass moulding
- 1 pc Tail gate inner lock
- 1 pc Tail gate rubber
- 1 pc Rear bumper fascia
- 2 pcs Rear bumper bracket
- 2 pcs Rear bumper reflector
- 2 pcs Rear bumper side retainer-L
- 1 pc Rear bumper side retainer-S
- 1 pc O/s taillamp
- 1 pc Rear end panel -top
- 1 pc Rear end panel -lower
- 1 pc End panel top garnish

	1,210.40	✓
	80.40	✓
	443.50	✓
	304.10	✓
	491.90	✓
@ S\$ 48.50	97.00	✓
@ S\$ 54.10	108.20	✓
@ S\$ 57.10	114.20	✓
	20.10	✓
	472.60	✓
	441.20	✓
	199.50	✓
	232.90	✓
	4,216.00	✓
Less 25% :	1,054.00	✓
	3,162.00	✓
	912.40	✓
	2,249.60	✓

- 1 pc Rear w/s glass sealant
- 1 pc Rear bumper reverse sensor(set
- 1 pc Rear no. plate with box

	3,162.00	✓
	60.00	✓
	300.00	✓
	50.00	✓

To remove & refix rear windscreen glass and conduct water leak test.

*120h*  
150.00

To remove roof lining, front and rear seats, trim board and carpet

*60h*  
120.00

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH6733U

Page : 2

To apply undersealing

60.00

To putty and spray replaced parts

900.00 *7201*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

*6001*  
800.00

Total : S\$ 5,602.00

Singapore Dollars Five Thousand Six Hundred and  
Two Only

*L/Sum*  
*644.00*  
*Kenrick PUS*  
*(on Rm)*  
*AKS.*

*P 2737.20*  
*S.P 785.70*  
*SN 437.05*  
*L 1560.00*  

---

*5519.95*  
*- 1103.99*  

---

*24415.96*

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH6733U (AIG)

Date : 28-03-2019

Accident Date : 21-03-2019

Our Ref : 219049 /CHAN

LEE BOON KWONG

C/O ALAN'S UNITED AUTO PTE LTD

## SUPPLEMENTARY ITEM PRICE FOR TOYOTA WISH 5GQ32545

1 PC REAR O/S FENDER INNER TRIM

CM \$697.40 ✓

1 PC REAR FLOOR PANEL COVER TOP GARNISH

SW \$350.20 X

\$1,047.60

LESS 25% \$261.90

\$785.70

Singapore Dollars Seven Hundred Eighty Five And Cents Seventy Only

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05948

Vehicle Insured : SLH6733U  
Accident Date : 21-Mar-2019

Date : 25-Mar-2019

Our Ref : 219049 (AIG) / CHAN

PAGE : 1

LEE BOON KWONG  
BLK 521 HOUGANG AVE 6  
#01-53  
Singapore 530521

*Not Notified  
6 Days @ ?  
Running After Policy*

*5 days*

## ESTIMATED COST OF REPAIR FOR TOYOTA WISH SGQ3254S

1 pc Tail gate  
1 pc Tail gate glass moulding  
1 pc Tail gate inner lock  
1 pc Tail gate rubber  
1 pc Rear bumper fascia  
2 pcs Rear bumper bracket  
2 pcs Rear bumper reflector  
2 pcs Rear bumper side retainer-L  
1 pc Rear bumper side retainer-S  
1 pc O/s taillamp  
1 pc Rear end panel -top  
1 pc Rear end panel -lower  
1 pc End panel top garnish

*Br* 1,210.40 ✓  
*me* 80.40 ✓  
443.50  
*me* 304.10 *50% in*  
*Br* 491.90 ✓  
97.00 ?  
@ S\$ 48.50 *in* 108.20 X  
@ S\$ 54.10 *01/10/11* 114.20 ✓  
@ S\$ 57.10 *Div* 20.10 ✓  
472.60 ?  
441.20 ?  
199.50 ?  
*Br* 232.90 ✓  
-----  
4,216.00  
Less 25% : 1,054.00  
-----

1 pc Rear w/s glass sealant  
1 pc Rear bumper reverse sensor(set  
1 pc Rear no. plate with box

*me* 3,162.00  
*40% in* 60.00 sn  
*share 200%* 300.00 sn  
50.00 sn

To remove & refix rear windscreen  
glass and conduct water leak test.

*120%*  
150.00

To remove roof lining, front and  
rear seats, trim board and carpet

*60%*  
120.00



Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH6733U

Page : 2

To apply undersealing

✓  
60.00

To putty and spray replaced parts

900.00 720/-

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

600/-  
800.00

Total : S\$ 5,602.00

=====

Singapore Dollars Five Thousand Six Hundred and  
Two Only

## Jia Le (LKK Auto)

---

**From:** alan khong chin wah <alanauto@gmail.com>  
**Sent:** Monday, 6 May 2019 5:35 PM  
**To:** Jia Le (LKK Auto)  
**Subject:** Re: Your Ref: SGQ3254S \*Our Ref: CC4/AIG19005466/Kpa3 [ACCIDENT INVOLVING SLH6733U & SGQ3254S ON 21/03/2019]  
**Attachments:** SKM\_284e19050617400.pdf

Dear Jia Le

Enclosed duly signed DV for process payment to us, thank you .

Regards  
Kenny  
Alan's United Auto pte Ltd  
64538686

On Mon, May 6, 2019 at 4:58 PM Jia Le (LKK Auto) <[JiaLe@lkkauto.com](mailto:JiaLe@lkkauto.com)> wrote:

### WITHOUT PREJUDICE

Dear Kenny,

Amount \$5056.00 confirmed.

Please duly sign the DV enclosed and return to us for our necessary action.

-  
-  
Best Regards,

Carlton Chan | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-  
From: alan khong chin wah [mailto:[alanauto@gmail.com](mailto:alanauto@gmail.com)]

Sent: Monday, 6 May 2019 4:44 PM

To: Jia Le (LKK Auto)

Subject: Re: Your Ref: SGQ3254S \*Our Ref: CC4/AIG19005466/Kpa3 [ACCIDENT INVOLVING SLH6733U & SGQ3254S ON 21/03/2019]



Dear Jia Le

Offer not accept , counter propose for \$5056 (all -in) , kindly revise your offer thank you ,

Regards

Kenny

Alan's United Auto pte Ltd

64538686

On Mon, May 6, 2019 at 3:21 PM Jia Le (LKK Auto) <JiaLe@lkkauto.com> wrote:

**WITHOUT PREJUDICE**

Dear Sirs/Mdm,

**ACCIDENT INVOLVING SLH 6733U & SGQ 3254S ON 21/03/2019**

We refer to the above matter.

We propose settlement at a global sum of **\$5,000.00(all-in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Carl or Chan | Case Handler**

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: Jiale@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKIC

LEE BOON KWONG

c/o Blk 7 Sin Ming Industrial Estate  
#01-76  
Singapore 575642

Date: 8-4-2019

AIG ASIA PACIFIC INSURANCE PTE LTD  
MOTOR CLAIMS DEPT.  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120

Dear Sir / Madam

ACCIDENT INVOLVING MOTOR VEHICLES SGQ 3254 S AND SLH 6733 U  
ALONG HOUBANH AVE 6 AND BUANGKOK AVE ON 31-3-2019

I / We, the owner of Vehicle No. SGQ 3254 S which was involved in the above accident.

My / Our vehicle sustained damages as a result of the above said accident and I / we are now claiming against you for the followings:-

- |  |   |                  |
|--|---|------------------|
| 1. Costs of repair                           | - | \$4494.00        |
| 2. Loss-of-Use/Rental fees 10 Days (PRL Sum) | - | \$800.00         |
| 3. Police / GIA report / LTA fees            | - | \$2.00           |
| 4. Surveyor report fees                      | - |                  |
| 5. Others                                    | - |                  |
| Total:                                       |   | <u>\$5296.00</u> |

Please advise whether you are now prepare to settle my claims as outlined above.

I / We hereby authorise my / our repairers, M/s Alan's United Auto Pte. Ltd. and/or their representatives to negotiate/compromise settlement of my / our above claim on my / our behalf. If there is a settlement I / we further authorise you to pay whatever settlement sum to my / our repairers being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours faithfully,



## LETTER OF AUTHORITY

ACCIDENT INVOLVING SGQ 3254 S AND SLH 6733 U  
ALONG HOUGANG AVE 6 AND BUANG KOK AVE  
ON 21-03-2019

BY THE LETTER OF AUTHORITY, I / We, LEE BOON KWONG  
NRIC NO. S7006303 D The owner of Vehicle No. SGQ 3254 S


Hereby irrevocably appoint Messrs **Alan's United Auto Pte. Ltd.** at Block 7, Sin Ming Industrial Estate, Sector C, #01-76, Singapore 575642, and/or their representative to process the Third Party claim on my/our behalf and to do all and/or any of the followings:-

1. To submit, negotiate/compromise and to resolve settlements of my/our above mentioned claim.
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favor of **Alan's United Auto Pte. Ltd.**
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever as they deem necessary for the purpose of settling my/our said claim.

I / We hereby declare that all the processing and documents done by virtue of this letter of authority on my/our behalf by my/our repairers or any person authorized by them shall be as good valid and effectual to all intends and purposes whatsoever as if the same had been done or executed by me/us in person.

I / We further confirm that the acceptance by Messrs **Alan's United Auto Pte. Ltd.** of the settlement amount constitute the full discharge of my/our claim(s) in respect of the above accident.

Signed on the 23 (day) 03 (month) 2019 (year)

  
\_\_\_\_\_  
Acknowledged by Owner  
(company stamp if applicable)

Lee Boon Kwong

Blk 521 Hougang Ave 6 #01-53

Singapore 530521

Mobile : +65 8288 0077/+86 189 1278 7877

NRIC : S7006303D

To whom it may concern ,

Re : Letter Of Authorisation

I , hereby , authorized , Lee Chin Yang , NRIC: S9720242G to transact or act on my behalf to sign on documents that is related during my absent due to working in overseas.

Regards ;

A handwritten signature in black ink, appearing to be 'Lee Boon Kwong', with a large loop at the start and a wavy line at the end.

Lee Boon Kwong



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19005466/Kpa3

04 APRIL 2019

**KHOA WEILONG GEOFFREY**

11 TAMPINES CENTRAL 7

#10-01

SINGAPORE 528769

Dear Sir/Madam,

**ACCIDENT INVOLVING SH 6733U & SGQ 3254S ALONG/AT PUNGGOL SLIP ROAD  
ON 21/03/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SGQ 3254S against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as it is head-to-rear collision. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG

Case Handler

DID: 6742 3197

FAX: 6741 4108

Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)*

## LETTER OF AUTHORITY

ACCIDENT INVOLVING SGA 3254 S AND SLH 6733 U  
ALONG HOUGANG AVE 6 AND BUANG KOK AVE  
ON 21-03-2019

BY THE LETTER OF AUTHORITY, I / We, LEE BOON KWONG  
NRIC NO. S7006303 D The owner of Vehicle No. SGA 3254 S

Hereby irrevocably appoint Messrs Alan's United Auto Pte. Ltd. at Block 7, Sin Ming Industrial Estate, Sector C, #01-76, Singapore 575642, and/or their representative to process the Third Party claim on my/our behalf and to do all and/or any of the followings:-

1. To submit, negotiate/compromise and to resolve settlements of my/our above mentioned claim.
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favor of Alan's United Auto Pte. Ltd.
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever as they deem necessary for the purpose of settling my/our said claim.

I / We hereby declare that all the processing and documents done by virtue of this letter of authority on my/our behalf by my/our repairers or any person authorized by them shall be as good valid and effectual to all intends and purposes whatsoever as if the same had been done or executed by me/us in person.

I / We further confirm that the acceptance by Messrs Alan's United Auto Pte. Ltd. of the settlement amount constitute the full discharge of my/our claim(s) in respect of the above accident.

Signed on the 23 (day) 03 (month) 2019 (year)



Acknowledged by Owner  
(company stamp if applicable)

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, ALAN'S UNITED AUTO PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,494.00 (Repair Cost), S\$560.00 (Loss of Use/Rental), S\$2.00 (Disbursement) for vehicle no. SGO 3254S that was damaged pursuant to the accident which occurred on 21/03/2019 (date) along HOUGANG AVE 6 AND BUANGKOK AVE (location) involving vehicle no/s SLH 6733U. This is pursuant to the inspection conducted on 26/03/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LEE BOON KWONG ("the third party claimant") of vehicle no. SGO 3254S make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGO 3254S (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 23 (day) of MAY (month) 2019 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)



# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

## TAX INVOICE

Vehicle Insured : SLH6733U  
Accident Date : 21-Mar-2019  
Our Ref : 219049 (AIG) / CHAN

No. : 225332

Date : 08.04.2019

PAGE : 1

LEE BOON KWONG  
BLK 521 HOUGANG AVE 6  
#01-53  
Singapore 530521

FINAL REPAIR COST FOR TOYOTA WISH SGQ3254S  
=====

To supply spare parts

To remove & refix rear windscreen  
glass and conduct water leak test.

To remove roof lining, front and  
rear seats, trim board and carpet

To apply undersealing

To putty and spray replaced parts

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

	-----
	4,200.00
Add 7% GST :	294.00
	-----
Total :	S\$ 4,494.00
	=====

Singapore Dollars Four Thousand Four Hundred  
and Ninety Four Only



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-19-046253

Date of Request: 25/03/2019

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd  
Blk 7 Sin Ming Industrial Estate  
#01-76  
Singapore 575642

Dear Sir/Madam,

Enquiry Date 25/03/2019  
Enquiry By Chan Yew Siah  
TP Vehicle No. SLH6733U  
Accident Date 21/03/2019

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLH6733U	AIG Asia Pacific Insurance Pte. Ltd.	10/03/2019-09/03/2020	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-046253

Date of Request: 25/03/2019

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd  
Blk 7 Sin Ming Industrial Estate  
#01-76  
Singapore 575642

Dear Sir/Madam,

Enquiry Date 25/03/2019  
Enquiry By Chan Yew Siah  
TP Vehicle No. SLH6733U  
Accident Date 21/03/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Mar 2019 <a href="#">Edit Reg</a>		26 Mar 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$4,200.00</b> <a href="#">Edit Estimates</a>	<b>\$4,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>KHOA WEILONG GEOFFREY</b> , ID: S8438721E									
Main Claimant: <b>LEE BOON KWONG</b> , ID: S7006303D									
Vehicle Reg. No.: <b>SGQ3254S</b>		Date of Loss: 21/03/2019 20:00 - :59	[146 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type: <b>TP / 6726906937SG</b>		Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured): <b>SLH6733U</b>		Policy No. (Claimant):	5096903351-01						
		Excess:							
Repairer: <b>Alan's United Auto Pte Ltd (SIN MING)</b> BLOCK 7, SIN MING INDUSTRIAL ESTATE, #01-76, 575642 Sin Ming - Tel:									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Loh, Chee-Heng</b> ] Chee-Heng.Loh@aig.com									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 05/04/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGQ3254S (6726906937SG)  
[SLH6733U]  
TP  
LEE BOON KWONG  
Mar 21 2019 8:00PM  
[KHOA WEILONG GEOFFREY]  
Alan's United Auto Pte Ltd

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	04/04/19 09:54	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> <b>Video - Accident</b> <small>From:OD - Reg. No: SLH6733U, Claimant: KHOA WEILONG GEOFFREY</small>	 Load MP4	
<b>Letters/Correspondences</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	(Draft)	<b>LKK Auto Consultants Pte Ltd (HQ)</b> <b>Third Party Express Settlement - Payment Breakdown</b>	 Edit	
<b>Photos/Images</b>				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
<b>LKK Auto Consultants Pte Ltd (HQ)</b>				
1	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	04/04/19 08:52	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>
13	04/04/19 08:52	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>
14	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	04/04/19 08:52	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
18	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
19	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
20	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
21	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
22	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
23	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
24	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
25	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
26	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
27	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
28	10/05/19 10:47	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				
			1 per page	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/03/19 15:35	EMAIL FROM AIG DD 26.03.2019		Load PDF
2	27/03/19 15:35	TP ESTIMATE + TP GIA REPORT		Load PDF
3	31/03/19 23:48	TP ESTIMATE-MARKED		Load PDF
4	27/05/19 17:14	WORKSHOP INVOICE		Load PDF
5	27/05/19 17:14	AUTHORISATION TO ACT FORM		Load PDF
6	27/05/19 17:14	Release Voucher		Load PDF
7	27/05/19 17:14	GIA SEARCH		Load PDF
8	27/05/19 17:14	LETTER TO OI		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	28/03/19 09:36	OI GIA REPORT		Load PDF
2	04/04/19 09:56	TP GIA		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>	^ v
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLH6733U (Insd veh)	Model:	TOYOTA WISH 1.8 (A)
	SGQ3254S (TP veh)		
Date of Accident:	21/03/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	6,834.84	
Final Repair Cost	: \$	4,494.00	
Loss of Use	: \$	560.00	7.00 days at \$80.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	5,056.00	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Alan's United Auto Pte.Ltd.	: \$	5,056.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

27 May  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19005466/KPA3Q2

Date: 27/05/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SGQ3254S

**Insured Vehicle No :** SLH6733U

Date of Loss: 21/03/2019

Nature of Claim: TP

Claim No: 6726906937SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGQ3254S**

Make &amp; Model: TOYOTA WISH, 1.8 (A)

Engine No: 1ZZ2813201

Reg. Date: 11/01/2007 (Man. Year: 2006)

Chassis No: ZNE100349331

Colour: Metallic Grey

Odometer: 147202 km

Engine Capacity: 1794 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size:

215/45 R17

Front Left Side: Dayton 3 mm

Rear Left Side:

Dayton 3 mm

Front Right Side: Dayton 3 mm

Rear Right Side:

Dayton 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,357.70	3,697.30	660.40	15.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,030.00	1,560.00	470.00	23.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,387.70</b>	<b>5,257.30</b>	<b>1,130.40</b>	<b>17.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
(S\$)	6,387.70	4,200.00	2,187.70	34.25
<b>+ GST 7.00/7.00% (S\$)</b>	447.14	294.00	153.14	34.25
<b>Nett Amount (S\$)</b>	<b>6,834.84</b>	<b>4,494.00</b>	<b>2,340.84</b>	<b>34.25</b>
<b>+ Loss of Use (7.0 x S\$80.00/day) (S\$)</b>		560.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>5,056.00</b>		

### INSPECTION

Date of Assignment: 26/03/2019

Date Inspected: 26/03/2019 Inspected At:

Alan's United Auto Pte Ltd (SIN MING)  
BLOCK 7, SIN MING INDUSTRIAL



ESTATE, #01-76  
Singapore 575642

Estimated Period of Repair: 5.0 days

---

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,210.40 FL	*1,210.40 FL
2	1		*TAIL GATE GLASS MOULDING	Necessary	80.40 FL	*80.40 FL
3	1		*TAIL GATE INNER LOCK	Necessary	443.50 FL	*443.50 FL
4	1		*TAIL GATE RUBBER (50%)	Cut	228.08 FS	*152.05 FS
5	1		*REAR BUMPER FASCIA	Bent	491.90 FL	*491.90 FL
6	2		*REAR BUMPER BRACKET	Repair	97.00 FL	*- FL
7	2		*REAR BUMPER REFLECTOR	Serviceable	108.20 FL	*- FL
8	1		*REAR BUMPER SIDE RETAINER -L	O/S Distorted	114.20 FL	*57.10 FL
9	1		*REAR BUMPER SIDE RETAINER -S	Distorted	20.10 FL	*20.10 FL
10	1		*O/S TAILLAMP	Mtg Cracked	472.60 FL	*472.60 FL
11	1		*REAR END PANEL -TOP	Bent	441.20 FL	*441.20 FL
12	1		*REAR END PANEL -LOWER	Bent	199.50 FL	*199.50 FL
13	1		*END PANEL TOP GARNISH	Buckled	232.90 FL	*232.90 FL
14	1		*REAR W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
15	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
16	1		*REAR NO.PLATE WITH BOX	Necessary	50.00 FS	*45.00 FS
17	1		*REAR O/S FENDER INNER TRIM	Cracked	697.40 FL	*697.40 FL
18	1		*REAR FLOOR PANEL COVER TOP GARNISH	Serviceable	350.20 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc

<b>Sub Total (\$\$)</b>	<b>5,597.58</b>	<b>4,784.05</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,239.88</b>	<b>1,086.75</b>
<b>Total Parts (\$\$)</b>	<b>4,357.70</b>	<b>3,697.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
3	TO APPLY UNDERSEALING	New	60.00	60.00
4	TO PUTTY AND SPRAY REPLACED PARTS	New	900.00	720.00
5	TO REMOVE,CUT -OUT DAMAGED PARTS, PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	800.00	600.00
Gross Labour Cost (S\$)			2,030.00	1,560.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;