

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBH365G190320

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Date: 25-03-19

Address: Motor Claims Department

Vehicle No: GBH365G

8 Shenton Way #27-01

Model/Make: Fiat Doblo Cargo

AXA Tower

Singapore 068811

Maxi 1.6 MTJ AMT Glaze

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front 2 Bumper	\$ 1,245.50	
2	Bumper Clips 1 set	\$ 58.00	
3	Bumper Bracket	\$ 171.80	
4	Grille	\$ 484.70	
5	Fender <i>ALS</i>	\$ 780.00	
6	Head Lamp <i>ALS</i>	\$ 862.40	
7	Fog Lamp Cover <i>ALS</i>	\$ 23.60	
	To check all wiring & electrical component for proper function	\$ 50.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	
	To putty & spray painting & including touch up paint on accident affected	\$ 500.00	
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 4,856.00

Total amount in Lump Sum Basis for repaired vehicle



SDLS:

M/s Liu's Brother Auto Engrg Wks

not Adhered
hkr
2/s \$ 2400
3 day.

27/3/19

Take photo After repair

1-3141.7
500
1-1570.65
10hr - 810.00
2420.65

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: