

ASSIGNMENT

Surveys:

LVP

DOI:

29/3/2019

Date / Time:

22/3/19

Registered in Merimen:

22/3/19

Pre-assign / CCU / FTE

SKD 9922D



Insured Vehicle No. :

Molly Tan Poh Hai

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A :

26/3/19

Place of Accident :

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L/YES/NO)

OI GIA REPORT: YES/NO ; TP GIA REPORT: YES/NO

Insured Liability : % Final ? Yes/No

SKD 9922D

SKV 136P

SS 342D



INSRS:
WSP:
Tel:
Liability:
RMKS:

07



INSRS:
WSP: Premium
Tel:
Liability:
RMKS:

TP



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
24/4/19 @ 3:15pm Khanhhuo	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	22/4/19 - KChan Hai
2/5/19 @ 9:58am - Khanhhuo	Documentation Check List: Handler Typist	
08/05/19	Notification ltr (if non-pickup) After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice LTA / GIA : Medical Bill: PIR: Mandate/Reject Instruction: LOD	<input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/> <input checked="" type="checkbox"/>
11/12/19 Khanhhuo	Payment Breakdown Form: Post-Repair Photos: Others:	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
23/12/19 Khanhhuo		

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$11P SS 7,129.16 (6 days) Reduction: 66 % Email Call

FINAL SETTLEMENT Date/Time: 23/12/19 Confirm with: WLP Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 28

Repair Cost: \$7,625.20 If NO or B 28, Ass. Lia : 100%

Loss of Rental (LOR): \$ - (- days) 3 VEH C C COI (LAST VEH) ✓

Loss of Use (LOU): \$ 900 (580 x 7 days)

Loss of Income (LOI): \$ - (\$ - x - days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$ 2.00

Medical \$ -

Disbursement: \$ - (e.g. Tow/ Independent)

Legal Cost \$ -

Total: \$ 8,190.20 Global Sum SS:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$ 8,190.20 Name 1: PREMIUM AUTOMOBILES PTELTD

Payee 2: (Strike if N.A.) \$ Name 2:

Payee 3: (Strike if N.A.) \$ Name 3:

COPY SENT 22/1/19

- 1) Claim status: Non- / Reject / Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$320

REF: **ALG**

ASSIGNMENT

From: _____ Date: **29/3/19**

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. **SKV 1136P**

at Workshop no/s **Premium**

of **55 Ubi Rd 1**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh. **2:30pm**

Veh No: **SKV1136P** Yr Regn: **2015 / Agust.**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Audi A6** c.c. **1798**

Colour: **White** A/C: **Insured / Std / NI / NA**

Sp. Reading: **39/69** T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: **WAUZZZA43FN091668**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: **Nil** / S/Rim / STD A/Rim or _____

Tyre Size: F: **245/45R18**

R: **245/45R18**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: **06** days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **lup**

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Front	Rear
R/Bal. 06 mm	R/Bal. 0.6 mm
L/Bal. 06 mm	L/Bal. 06 mm
D.O.I.	D.O.I. 29/03/19.

Survey held at **Premium.**

Des. of Damages: Fr / Rear / O/S / NIS / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP ALG
	CP / P \$ 7,129.16 Red \$ 13,722.84 (66%)
	6 days + 1 Sunday = 7 days.
	MV: 105k
	PV: 76k.
	Net: 29k

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

TOTAL _____

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0402/2019/GW
Date : 28-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No: SKD 9922 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Koh Kwang Haw
Address : 56 Bukit Batok St 31
#25-15
Singapore 659445
Telephone : (HP)96774028
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SKV 1136 P**
Model Code : Audi A6 1.8 TFSI Ultra S
Model / Year : Aug-15
Engine No : CYG 005827
Chassis No : WAUZZZ4G3FN091668
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Mar-19
Place of Accident : Along PIE Near Toa Payoh Exit Towards Jurong

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 1136 P

S/N	Nature of Jobs	Estimated Charges
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper.	\$ 1,050.00 500
3	To respray front bumper.	\$ 900.00 550
TOTAL LABOUR CHARGES - FRONT		: \$ <u>2,430.00</u>

1530

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1136 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	\$ 2,549.00	+
2	FRONT BUMPER GRILLE <i>Not Nec</i>	\$ 598.00	+
3	FRONT BUMPER CHROME TRIM <i>Not Nec</i>	\$ 276.00	+
4	FRONT BUMPER FIXING PARTS <i>Not Nec</i>	\$ 45.00	+
5	FRONT BUMPER CLOSING ELEMENT <i>Not Nec</i>	\$ 199.00	+
6	FRONT BUMPER SPOILER <i>Not Nec</i>	\$ 227.00	+
7	RADIATOR GRILLE <i>Could</i>	\$ 1,766.00	✓
8	RADIATOR GRILLE COVER <i>Not Nec</i>	\$ 33.00	+
9	RADIATOR GRILLE SENSOR SUPPORT-LH/RH <i>Not Nec</i>	2 \$ 122.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>Not Nec</i>	2 \$ 638.00	+
11	FRONT BUMPER COVER-LH/RH <i>Not Nec</i>	2 \$ 92.00	+
12	FRONT BUMPER COVER CAP-LH/RH <i>Not Nec</i>	2 \$ 104.00	+
13	FRONT BUMPER LIFT CYLINDER-LH/RH <i>Not Nec</i>	2 \$ 432.00	+
14	FOAM FILLER PIECE <i>Not Nec</i>	\$ 215.00	+
15	FRONT BUMPER REINFORCEMENT BEAM <i>Not Nec</i>	\$ 754.00	+
16	FRONT BUMPER COVER CAP-LH/RH <i>Not Nec</i>	\$ 112.00	+
17	SIGN ' CAUTION ' <i>Free</i>	\$ 13.00	+
18	AIR CONDITIONER STICKER	\$ 18.00	+
19	FRONT SENSOR-INNER <i>Not Nec</i>	2 \$ 419.00	+
20	FRONT SENSOR SEAL RING <i>Not Nec</i>	4 \$ 5.00	+
SUB-TOTAL SPARE PARTS CHARGES - FRONT :		\$ 8,617.00	

1,412.80
96.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

1 888

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1136 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT AIR GUIDE -LH/RH <i>all on</i>	2 \$	50.00 T
22	RADIATOR GRILLE UPPER CENTRE COVER <i>Not Nec</i>	\$	27.00 X
23	RADIATOR LOWER SUPPORT SEAL STRIP <i>Not Nec</i>	\$	21.00 X
TOTAL SPARE PARTS CHARGES - FRONT		:	\$ 8,715.00
TOTAL LABOUR CHARGES - FRONT		:	\$ 2,430.00
GRAND TOTAL - FRONT		:	\$ 11,145.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 1136 P

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid and rear kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓
2	To dismantle and renew rear bumper. Re-organsie rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500
3	To respray rear bumper.	\$ 900.00 550
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 2,502.00

1602

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKV 1136 P

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
1	REAR BUMPER <i>reformed</i>	S	2,438.00 ✓	1,950.40
2	REAR BUMPER FIXING PARTS <i>new</i>	S	247.00 ✗	
3	REAR BUMPER SPOILER <i>cut</i>	S	437.00 ✓	349.60
4	REAR BUMPER SECURING STRIP <i>new</i>	S	203.00 ✓	162.40
5	REAR BUMPER CLOSING ELEMENT-LH/RH <i>3 new</i>	2 S	146.00 ✗	
6	CABLE TERMINAL HOLDER RETAINER	13 S	90.00 ✗	
7	REAR LID CONTROL UNIT <i>3 new</i>	S	387.00 ✗	
8	EXHAUST TAIL PIPE TRIM <i>3 new</i>	S	517.00 ✗	
9	REAR BUMPER CARRIER <i>3 new</i>	S	887.00 ✗	
10	REAR BUMPER SEAL-LH/RH	2 S	26.00 ✗	
11	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 S	60.00 ✗	
12	REAR BUMPER GUIDE SECTION-LH/RH	2 S	96.00 ✗	
13	REAR BUMPER CONNECTING PIECE	2 S	22.00 ✗	
14	REAR BUMPER GUIDE PROFILE-LH/RH	2 S	120.00 ✗	
15	REAR BUMPER CENTER GUIDE SECTION	S	96.00 ✗	
16	REAR BUMPER HOLDING STRAP-LH/RH	2 S	116.00 ✗	
17	REAR SENSOR SEAL RING <i>3 new</i>	4 S	5.00 ✗	
18	REAR SENSOR-OUTER	2 S	462.00 ✗	
19	FRONT NO. PLATE <i>best</i>	S/N S	25.00 ✓	25
20	REAR NO. PLATE <i>not a</i>	S/N S	25.00 ✗	
21	SUNDRIES <i>Not Nec</i>	S	800.00 ✗	
TOTAL SPARE PARTS - REAR		:	\$ 7,205.00	3103
TOTAL LABOUR CHARGES - REAR		:	\$ 2,502.00	
GRAND TOTAL - REAR		:	\$ 9,707.00	
GRAND TOTAL - FRONT/REAR		:	\$ 20,852.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adian hiny
Surveyed Date : 29/03/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorized, 06 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

L - \$3132
P - 4,991

8,123

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	4598D
Vehicle Details	
Vehicle No.:	5KV1136P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Mar 2019
Vehicle Make:	AUDI
Vehicle Model:	A6 1.8 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	CYG005827
Chassis No.:	WAUZZZ4G3FN091668
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$44,444.00
Original Registration Date:	28 Aug 2015
First Registration Date:	28 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$49,222.00
Intended PARF Eligibility	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2025
PARF Rebate Amount:	\$36,916.00
Intended COE Details	
COE Expiry Date:	27 Aug 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$61,001.00
COE Rebate Amount:	\$39,109.00
Total Rebate Amount:	\$76,025.00

The information contained herein is correct as at 29 Mar 2019

OK

500+ dealers competed to buy my car!

Sell ur Car for More Cash
Highest Price or Get \$100 Free
Get Paid Now, Handover Later

SELL YOUR CAR

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A

2.88%P.A Low Interest @ Gv
Finance 2 Years Warranty.
\$2000 Down Monthly From \$568

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SYTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category Sort by Date Posted 20 results/page

7 vehicles | **Search** audi a6 [Advanced Search](#) [Search](#) [View All](#)

Search Selection	audi a6	Any	Any	2015	Any	Any	Any	Any	Available
------------------	---------	-----	-----	------	-----	-----	-----	-----	-----------

Audi A6 2.0A TFSI MU | **\$92,800** | **\$12,070 /yr** | **26-Mar-2015** | **1,984 cc** | **-** | **Luxury** | **Available**

Flexible In House Loan Available. Warranty Package To Suit To Your Needs. Bank Financing With Low Interest Too. Call Or Visit Us Now For Further Details.

★ Posted: 24-Mar-2019 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi

Audi A6 2.0A TFSI MU | **\$93,800** | **\$12,210 /yr** | **31-Mar-2015** | **1,984 cc** | **103,339 km** | **Luxury** | **Available**

Graded **B** by **STP**

Purchase From An Award Winning Dealership! 1 Year Comprehensive Warranty Inclusive! STA Certified Accident-Free Quality Pre-Owned With Low Mileage And Agent Service History For Peace Of Mind. 100% Loa...

Cosmo Automobiles

★ Posted: 26-Mar-2019 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi

Audi A6 2.0A TFSI MU | **\$96,800** | **\$12,460 /yr** | **29-Apr-2015** | **1,984 cc** | **71,000 km** | **Luxury** | **Available**

Graded **B** by **STP**

(100% Loan Available) Promo Bank Interest Rate From 1.99%. Original Condition And Maintained By Audi Singapore. Free 1 Year Warranty With Certified 120 Points Test Report With Detailed Chassis Inspect...

Dynamic Motoring

★ Posted: 22-Mar-2019 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi

Audi A6 1.8A TFSI Ultra S-tronic | **\$112,000** | **\$14,380 /yr** | **24-Jun-2015** | **1,798 cc** | **85,000 km** | **Luxury** | **Available**

Facilitated Model. Fully Serviced By Premium Automobiles/Just Serviced 19 July. Original Matrix Headlights. Wooden Trims. Brown Leather. Original Paint And Condition. Fold Down Back Seats. 100% Accident...

★ Posted: 24-Feb-2019 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi

Sleek Steering Wheel with Customised Cover

100% Handmade Genuine Carbon Fiber Steering Wheel Comes With Steering Wheel Cover.

[More info about this product.](#)

Audi A6 3.0A TFSI Quattro S-Line | **\$156,000** | **\$16,850 /yr** | **29-Sep-2015** | **2,995 cc** | **39,000 km** | **Luxury** | **Available**

Rare Few APR Stage 2 Tuned. More Than 328 Bhp, Forged Rims And Body Kit. Actual 2 Owners, Transfer Between Directors. Only Face Lift A6 In The Market With New Matrix LED Lights. Trade In, Viewing By A...

360 VR Cars

★ Posted: 01-May-2019 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi

Audi A6 1.8A TFSI Ultra S-tronic | **\$108,999** | **\$13,510 /yr** | **30-Sep-2015** | **1,798 cc** | **99,292 km** | **Luxury** | **Available**

Fully Audi Agent Servicing Since Day One! Loan Available! In House Loan Approval! One Management Owner! Lowest Bank Interest Rate 2.48%. Showroom Condition! Superb Tip Top Condition! Trade In Welcome!...

Premium Automobiles

★ Posted: 16-Mar-2019 Tags: 2015 Audi A6, 2015 audi a6, Audi A6, audi a6, Audi, A6, a6, Used Audi



Audi A6 1.8A TFSI Ultra S-tronic \$110,800 \$13,440 /yr 30-Nov-2015 1,798 cc 71,899 km Luxury Available

1 Owner Only! Fully Serviced And Maintain By Agent! Low Mileage! 100% Accident Free! STA Evaluation Welcome! View To Believe! 100% Loan Available! High Trade In For Your Used Car! Call Us Now To Make ...

ST Carz Pte Ltd

★ Posted: 20-Mar-2019 Tags: 2015 Audi A6, 2015 Audi A6, Audi A6, Audi A6, Audi A6, 1.8, Used A6S

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make ▼ Model ▼ Price ▼ Depreciation ▼ Reg Date ▼ Eng Cap ▼ Mileage ▼ Veh Type ▼ Status ▼

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & DPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used audi a6, audi a6 Singapore, used audi a6 Singapore, used audi a6, used vehicles Singapore or even buy used audi a6 Singapore. We have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Khanchna (LKK Auto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Thursday, 22 August 2019 3:33 PM
To: Adrian Ling (LKKAuto); Vic (LKKAuto); CS A Team; Admin A; Carrine Leong; Chang Chee Sing; jayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SKV1136P - TP AIG - SURVEYED 29 MAR 19
Attachments: PA04022019 - SKV 1136 P - A6 1.8 TFSI ULTRA- FRONT + REAR (AIG).xls; WhatsApp Image 2019-07-16 at 11.29.58 AM.jpeg; WhatsApp Image 2019-07-16 at 11.29.59 AM.jpeg; WhatsApp Image 2019-07-16 at 11.30.00 AM.jpeg; WhatsApp Image 2019-07-16 at 11.29.59 AM (1).jpeg; WhatsApp Image 2019-07-16 at 11.29.57 AM.jpeg; WhatsApp Image 2019-07-16 at 11.30.09 AM.jpeg; WhatsApp Image 2019-07-16 at 11.30.11 AM.jpeg; WhatsApp Image 2019-07-16 at 11.30.10 AM.jpeg

Hi Adrian and all,

Revised estimate and photos attached.

Please confirm repair cost of \$7129.16 @ 6 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0402/2019/GW
Date : 28-Mar-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Veh No: SKD 9922 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
6 days - ok - /b - 22 Aug 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Koh Kwang Haw
Address : 56 Bukit Batok St 31
#25-15
Singapore 659445
Telephone : (HP)96774028
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SKV 1136 P**
Model Code : Audi A8 1.8 TFSI Ultra S
Model / Year : Aug-15
Engine No : CYG 005827
Chassis No : WAUZZZ4G3FN091668
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Mar-19
Place of Accident : Along PIE Near Toa Payoh Exit Towards Jurong

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 1136 P

S/N	Nature of Jobs	Estimated Charges	
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper.	\$ 1,050.00	\$ 500.00
3	To respray front bumper.	\$ 900.00	\$ 550.00
TOTAL LABOUR CHARGES - FRONT		: \$ 2,430.00	\$ 1,530.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1136 P

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$	2,549.00
2	FRONT BUMPER GRILLE	\$	598.00
3	FRONT BUMPER CHROME TRIM	\$	276.00
4	FRONT BUMPER FIXING PARTS	\$	45.00
5	FRONT BUMPER CLOSING ELEMENT	\$	199.00
6	FRONT BUMPER SPOILER	\$	227.00
7	RADIATOR GRILLE	\$	1,766.00
8	RADIATOR GRILLE COVER	\$	33.00
9	RADIATOR GRILLE SENSOR SUPPORT-LH/RH	2 \$	122.00
10	FRONT BUMPER AIR GUIDE GRILLE-LH/RH	2 \$	638.00
11	FRONT BUMPER COVER-LH/RH	2 \$	92.00
12	FRONT BUMPER COVER CAP-LH/RH	2 \$	104.00
13	FRONT BUMPER LIFT CYLINDER-LH/RH	2 \$	432.00
14	FOAM FILLER PIECE	\$	215.00
15	FRONT BUMPER REINFORCEMENT BEAM	\$	754.00
16	FRONT BUMPER COVER CAP-LH/RH	\$	112.00
17	SIGN ' CAUTION '	\$	13.00
18	AIR CONDITIONER STICKER	\$	18.00
19	FRONT SENSOR-INNER	2 \$	419.00
20	FRONT SENSOR SEAL RING	4 \$	5.00
SUB-TOTAL SPARE PARTS CHARGES - FRONT :		\$	8,617.00
		\$	1,509.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKV 1136 P

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 1,509.76
21	FRONT AIR GUIDE -LH/RH	2	\$ 50.00	
22	RADIATOR GRILLE UPPER CENTRE COVER		\$ 27.00	
23	RADIATOR LOWER SUPPORT SEAL STRIP		\$ 21.00	
	TOTAL SPARE PARTS CHARGES - FRONT	:	\$ 8,715.00	\$ 1,509.76
	TOTAL LABOUR CHARGES - FRONT	:	\$ 2,430.00	\$ 1,530.00
	GRAND TOTAL - FRONT	:	\$ 11,145.00	\$ 3,039.76

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKV 1136 P

S/N	Nature of Jobs	Estimated Charges	
	<i>LABOUR FRONT C/F</i>	\$ 2,430.00	\$ 1,530.00
1	To remove and transfer rear parking aid and rear kick sensor. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00	\$ 500.00
3	To respray rear bumper.	\$ 900.00	\$ 550.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
	SUB-TOTAL LABOUR CHARGES - (REAR)	\$ 4,932.00	\$ 3,132.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SKV 1136 P

S/N	Parts Description	Damage Parts & Prices			
		S/NETT	REMARKS		
		\$	8,715.00	\$	1,509.76
1	REAR BUMPER	\$	2,438.00	\$	1,950.40
2	REAR BUMPER FIXING PARTS	\$	247.00		
3	REAR BUMPER SPOILER	\$	437.00	\$	349.60
4	REAR BUMPER SECURING STRIP	\$	203.00	\$	162.40
5	REAR BUMPER CLOSING ELEMENT-LH/RH	2 \$	146.00		
6	CABLE TERMINAL HOLDER RETAINER	13 \$	90.00		
7	REAR LID CONTROL UNIT	\$	387.00		
8	EXHAUST TAIL PIPE TRIM	\$	517.00		
9	REAR BUMPER CARRIER	\$	887.00		
10	REAR BUMPER SEAL-LH/RH	2 \$	26.00		
11	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$	60.00		
12	REAR BUMPER GUIDE SECTION-LH/RH	2 \$	96.00		
13	REAR BUMPER CONNECTING PIECE	2 \$	22.00		
14	REAR BUMPER GUIDE PROFILE-LH/RH	2 \$	120.00		
15	REAR BUMPER CENTER GUIDE SECTION	\$	96.00		
16	REAR BUMPER HOLDING STRAP-LH/RH	2 \$	116.00		
17	REAR SENSOR SEAL RING	4 \$	5.00		
18	REAR SENSOR-OUTER	2 \$	462.00		
19	FRONT NO. PLATE	S/N \$	25.00	\$	25.00
20	REAR NO. PLATE	S/N \$	25.00		
21	SUNDRIES	\$	800.00		
	Total materials frt/rr	:	\$ 15,920.00	\$	3,997.16
	Total labour frt/rr	:	\$ 4,932.00	\$	3,132.00
	Grand Total	:	\$ 20,852.00	\$	7,129.16 ✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 23 December 2019 10:48 AM
To: Claims
Cc: Admin A
Subject: CONFIRM SETTLEMENT- FINAL REVISION - SKV1136P - TP AIG - SURVEYED 29 MAR 19

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

We confirm settlement as follows:

1. Cost of Repair (w/GST)	\$ 7,628.20
2. Loss of Use (7 days x \$80)	\$ 560.00
3. LTA Search fee	\$ 2.00
TOTAL	\$ 8,190.20

We will proceed to do the necessary accordingly.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Khanchna (LKK Auto)
Sent: Wednesday, 18 December 2019 5:26 PM
To: Claims <claims@premiumauto.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: LOD - FINAL REVISION - SKV1136P - TP AIG - SURVEYED 29 MAR 19

WITHOUT PREJUDICE

Dear Sir/Madam,

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 18 December 2019 5:18 PM
To: Claims
Cc: Admin A
Subject: RE: LOD - FINAL REVISION - SKV1136P - TP AIG - SURVEYED 29 MAR 19

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We confirm settlement as per your LOD for **S8,188.20(all in)**.

We will proceed to do the necessary accordingly.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Friday, 13 December 2019 5:17 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>;

Admin A <admin-a@lkkauto.com>

Cc: claims@premiumauto.com.sg

Subject: RE: LOD - FINAL REVISION - SKV1136P - TP AIG - SURVEYED 29 MAR 19

Dear Khanchna,

Attached LOD for your perusal. We will submit over original documents by hand to Adrian.

Kindly keep a look out and organize for payment upon receipt.

Thank you.

Best Regards,

Nadia

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 8826 8736 p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Khanchna (LKK Auto) [<mailto:khanchna@lkkauto.com>]

Sent: Wednesday, 11 December, 2019 1:26 PM

To: Boo seng yak <boojohnny@gmail.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiayee.vap@premiumauto.com.sg

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: FINAL REVISION - SKV1136P - TP AIG - SURVEYED 29 MAR 19

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter and e-mails as trailed.

For COR, recommended amount at P/P S 7129.16(before GST) with 6 repair days.

** Kindly forward your LOD and final repair bill to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Thursday, 22 August 2019 3:33 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiavee.yap@premiumauto.com.sg

Subject: FINAL REVISION - SKV1136P - TP AIG - SURVEYED 29 MAR 19

Hi Adrian and all,

Revised estimate and photos attached.

Please confirm repair cost of \$7129.16 @ 6 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Print Received Message

This mail is associated with :

*SKV1136P (9973448355SG)
[SKD9922D]
TP
KOH KWANG HAW
Mar 26 2019 3:00PM
[MOLLY TAN POH LAI]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 18/12/2019 17:11 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8188.20) - SKV1136P - Claim Handler: Loh, Chee-Heng

Approved:8188.20.

Claim Audit

AUDIT TRAIL				
No	On	By	Remarks	By
1	27 Mar 2019 16:38	Cim Dtl Modified	Claimant's Name: -> KOH KWANG HAW. Claimant's ID: -> S76045980.	[A] HOW MEI KWAN
2	27 Mar 2019 16:38	Cim Veh Model Changed	(204806) AUDI A6 1.8 TFSI S-tronic (A).	[A] HOW MEI KWAN
3	27 Mar 2019 16:38	Cim Created	Reg No: SKV1136P. Acct Date: 2019/03/26. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: Premium Automobiles Pte Ltd (UBI)	[A] HOW MEI KWAN
4	27 Mar 2019 16:38	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); Suggested Adj. : LKK Auto Consultants Pte Ltd.	[A] HOW MEI KWAN
5	27 Mar 2019 16:38	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/04/05	[A] HOW MEI KWAN
6	27 Mar 2019 16:38	Adj Mandate Set	Approved:8000.00.Reinspr:Adj decides.	[A] HOW MEI KWAN
7	27 Mar 2019 16:38	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	27 Mar 2019 16:39	Label Added	(23):Express.	[A] HOW MEI KWAN
9	27 Mar 2019 16:39	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] HOW MEI KWAN
10	28 Mar 2019 11:42	Cim Registration Modified	Acct Time:14:00:00->15:00:00.	[I] AIG OneClaim Integration User
11	12 Dec 2019 17:14	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	12 Dec 2019 17:14	Cim Dtl Modified	JPJ Reg. Date: -> 2015/08/28.	[A] Elaine Kuan Hwa Meen
13	12 Dec 2019 17:14	Cim Details Notified		[A] Elaine Kuan Hwa Meen
14	18 Dec 2019 16:20	Adj Mandate Request	Cur.Reg:8188.20:Three vehicle chain collision, OI vehicle last. BOLA 28. ** 6 days recommendation for repair + 1 Sundays = 7 days	[A] Khanchna Pothura]

Date From



Date To



Audit Type None



Go

ACTIVITY

[24/04/2019 15:16] Khanchna Pothura]:
Called OI - No answer - Khanchna

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc. Type	Acc Name	Co Name (Insurer)	Ref 1	Ref 2	Amount
2375400	12 Dec 2019 17:14:23	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKV1136P	SKD9922D	11.77

BREAKDOWN OF PAYMENT

Vehicle No: SKV1136P

Accident on 26/03/2019 at ALONG PIE TOWARDS JURONG

Involving vehicle/s SE099220

1) Repair cost \$ 7628.20 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 560 Payable to: KOH KWANG HAW

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

Print Received Message

This mail is associated with :

*SKV1136P (9973448355SG)
[SKD9922D]
TP
KOH KWANG HAW
Mar 26 2019 3:00PM
[MOLLY TAN POH LAI]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/12/2019 17:01 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8190.20) - SKV1136P - Claim Handler: Loh, Chee-Heng

Approved:8190.20.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2019 Edit Reg		29 Mar 2019 00:00 Edit Adj Rpt	S\$7,129.16 Edit Estimates	S\$7,129.16 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	MOLLY TAN POH LAI, ID: S1124699		
Main Claimant:	KOH KWANG HAW, ID: S7604598D		
Vehicle Reg. No.:	SKV1136P	Date of Loss:	26/03/2019 15:00 - :59 [42 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9973448355SG	Policy/Cover Note No.:	1800097854 (Comprehensive) Coverage: 20/08/2018 - 19/08/2019
Vehicle Reg. No. (Insured):	SKD9922D	Policy No. (Claimant):	-
		Excess:	
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/04/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG_EXPRESS (20/12/2019): Alert - Adj Mandate Approved (S\$8190.20) - SKV1136P - Claim Handler: Loh, Chee-H... AIG_SG_EXPRESS (18/12/2019): Alert - Adj Mandate Approved (S\$8188.20) - SKV1136P - Claim Handler: Loh, Chee-H... 			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SKV1136P (9973448355SG)
 [SKD9922D]
 TP
 KOH KWANG HAW
 Mar 26 2019 3:00PM
 [MOLLY TAN POH LAI]
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
2	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
3	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
4	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
5	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
6	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
7	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
8	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
9	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
10	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
11	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
12	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
13	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
14	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
15	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
16	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
17	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
18	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
19	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
20	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
21	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
22	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
23	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
24	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
25	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
26	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
27	25/10/19 09:44	General View							Load JPG	<input checked="" type="checkbox"/>	
28	25/10/19 09:46	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
29	25/10/19 09:46	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
30	25/10/19 09:46	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
31	25/10/19 09:46	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
32	25/10/19 09:46	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
33	25/10/19 09:46	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
34	25/10/19 09:46	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
35	25/10/19 09:46	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	27/03/19 16:39	TP GIA REPORT							Load PDF		
2	01/04/19 21:33	TP ESTIMATE - MARKED							Load PDF		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
LKK Auto Consultants Pte Ltd (HQ)				
3	24/04/19 15:19	LETTER TO OI		Load PDF
4	18/12/19 16:10	LOD, FINAL BILL, LTA SEARCH, ATA		Load PDF
5	27/12/19 12:30	WORKSHOP INVOICE		Load PDF
6	27/12/19 12:30	AUTHORISATION TO ACT FORM		Load PDF
7	27/12/19 12:30	Release Voucher		Load PDF
8	27/12/19 12:30	GIA SEARCH		Load PDF
9	27/12/19 12:30	LOD		Load PDF
AIG Asia Pacific Insurance Pte. Ltd. (SG)				
1	28/03/19 14:03	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKD9922D (Insd veh)	Model:	AUDI A6 1.8 TFSI S-TRONIC (A)
	SKV1136P (TP veh)		
Date of Accident:	26/03/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	22,311.64
Final Repair Cost	:	\$	7,628.20
Loss of Use	:	\$	560.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	8,190.20

7.00 days at \$80.00 per day
days

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ 100 _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	Premium Automobiles Pte Ltd	: \$ 8,190.20
2)		: \$
3)		: \$

 JOANNE LEE KHANG MIN
 LKK Auto Consultants Pte Ltd

 27 Dec
 2019
 Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19005480/AKA3Q2

Date: 27/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800097854
 Claimant Vehicle No : SKV1136P Insured Vehicle No : SKD9922D
 Date of Loss: 26/03/2019 Nature of Claim: TP Claim No: 9973448355SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV1136P
 Make & Model: AUDI A6, 1.8 TFSI S-tronic (A) Engine No: CYG005827
 Reg. Date: 28/08/2015 (Man. Year: 2015) Chassis No: WAUZZZ4G3FN091668
 Colour: White Odometer: 39169 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,920.00	3,997.16	11,922.84	74.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,932.00	3,132.00	1,800.00	36.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,852.00	7,129.16	13,722.84	65.81
+ GST 7.00/7.00% (S\$)	1,459.64	499.04	960.60	65.81
Nett Amount (S\$)	22,311.64	7,628.20	14,683.44	65.81
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,190.20		

INSPECTION

Date of Assignment: 29/03/2019
 Date Inspected: 29/03/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,549.00 FS	*- FS
2	1		*FRONT BUMPER GRILLE	Not Necessary	598.00 FS	*- FS
3	1		*FRONT BUMPER CHROME TRIM	Not Necessary	276.00 FS	*- FS
4	1		*FRONT BUMPER FIXING PARTS	Not Necessary	45.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	199.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	227.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,766.00 FS	*1,412.80 FS
8	1		*RADIATOR GRILLE COVER	Not Necessary	33.00 FS	*- FS
9	2		*RADIATOR GRILLE SENSOR SUPPORT -LH/RH	Necessary	122.00 FS	*96.96 FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE -LH/RH	Not Necessary	638.00 FS	*- FS
11	2		*FRONT BUMPER COVER -LH/RH	Not Necessary	92.00 FS	*- FS
12	2		*FRONT BUMPER COVER CAP -LH/RH	Not Necessary	104.00 FS	*- FS
13	2		*FRONT BUMPER LIFT CYLINDER -LH/RH	Not Necessary	432.00 FS	*- FS
14	1		*FOAM FILLER PIECE	Not Necessary	215.00 FS	*- FS
15	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	754.00 FS	*- FS
16	1		*FRONT BUMPER COVER CAP -LH/RH	Not Necessary	112.00 FS	*- FS
17	1		*SIGN CAUTION	Not Necessary	13.00 FS	*- FS
18	1		*AIR CONDITIONER STICKER	Not Necessary	18.00 FS	*- FS
19	2		*FRONT SENSOR -INNER	Not Necessary	419.00 FS	*- FS
20	4		*FRONT SENSOR SEAL RING	Not Necessary	5.00 FS	*- FS
21	2		*FRONT AIR GUIDE -LH/RH	Not Necessary	50.00 FS	*- FS
22	1		*RADIATOR GRILLE UPPER CENTRE COVER	Not Necessary	27.00 FS	*- FS
23	1		*RADIATOR LOWER SUPPORT SEAL STRIP	Not Necessary	21.00 FS	*- FS
24	1		*REAR BUMPER	Deformed	2,438.00 FS	*1,950.40 FS
25	1		*REAR BUMPER FIXING PARTS	Not Necessary	247.00 FS	*- FS
26	1		*REAR BUMPER SPOILER	Cut	437.00 FS	*349.60 FS
27	1		*REAR BUMPER SECURING STRIP	Necessary	203.00 FS	*162.40 FS
28	2		*REAR BUMPER CLOSING ELEMENT -LH/RH	Not Necessary	146.00 FS	*- FS
29	13		*CABLE TERMINAL HOLDER RETAINER	Not Necessary	90.00 FS	*- FS
30	1		*REAR LID CONTROL UNIT	Not Necessary	387.00 FS	*- FS
31	1		*EXHAUST TAIL PIPE TRIM	Not Necessary	517.00 FS	*- FS
32	1		*REAR BUMPER CARRIER	Not Necessary	887.00 FS	*- FS
33	2		*REAR BUMPER SEAL -LH/RH	Not Necessary	26.00 FS	*- FS
34	2		*REAR BUMPER UPPER GUIDE SECTION -LH/RH	Not Necessary	60.00 FS	*- FS
35	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	96.00 FS	*- FS
36	2		*REAR BUMPER CONNECTION PIECE	Not Necessary	22.00 FS	*- FS
37	2		*REAR BUMPER GUIDE PROGILE -LH/RH	Not Necessary	120.00 FS	*- FS
38	1		*REAR BUMPER CENTER GUIDE SECTION	Not Necessary	98.00 FS	*- FS
39	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	116.00 FS	*- FS
40	4		*REAR SENSOR SEAL RING	Not Necessary	5.00 FS	*- FS
41	2		*REAR SENSOR -OUTER	Not Necessary	462.00 FS	*- FS
42	1		*FRONT NO.PLATE	Bent	25.00 FS	*25.00 FS
43	1		*REAR NO.PLATE	Not Necessary	25.00 FS	*- FS
44	1		*SUNDRIES	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	15,920.00	3,997.16
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER	New	1,050.00	500.00
3	TO RESPRAY FRONT BUMPER	New	900.00	550.00
4	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR KICK SENSOR ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
5	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANSIE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
6	TO RESPRAY REAR BUMPER	New	900.00	550.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,932.00	3,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >