



not Arthur
name
L/S ~~1600~~
4 Aug.
The photo of the

ATTN:	DESCRIPTION - PARTS	QTY	PRICE
NO.			
	FRONT DOOR RH	1	\$ 884.20
	FRONT DOOR HINGE RH	1	\$ 98.00
	FRONT DOOR CHECKER RH	1	\$ 78.00
	FRONT DOOR LOCK RH	1	\$ 460.00
	FRONT DOOR PROTECTOR RH	1	\$ 129.40
	FRONT DOOR OUTER MOULDING RH	1	\$ 127.90
	FRONT DOOR STICKER RH	1	\$ 56.40
	FRONT DOOR P/W WINDOW MOTOR ASSY RH	1	\$ 384.20
	FRONT DOOR BOARD RH	1	\$ 659.80
	FRONT DOOR HANDLE RH	1	\$ 113.60
	REAR DOOR RH	1	\$ 812.90
	REAR DOOR HINGE RH	1	\$ 88.40
	REAR DOOR CHECKER RH	1	\$ 58.00
	REAR DOOR LOCK RH	1	\$ 254.60
	REAR DOOR PROTECTOR RH	1	\$ 124.60
	REAR DOOR OUTER MOULDING RH	1	\$ 127.90
	REAR DOOR STICKER RH	1	\$ 56.40
	REAR DOOR P/W WINDOW MOTOR ASSY RH	1	\$ 384.20
	REAR DOOR BOARD RH	1	\$ 659.80
	REAR DOOR HANDLE RH	1	\$ 113.60
	REAR FENDER RH	1	\$ 1,248.00
	REAR BUMPER RH	1	\$ 790.00
	REAR BUMPER SIDE RETAINER RH	1	\$ 45.00
	REAR BUMPER BRACKET RH	1	\$ 38.00
	ROCKER PANEL RH	1	\$ 890.00
	ROCKER PANEL GARNISH CLIPS RH	1	\$ 50.00
	P-869.30		
	SUBTOTAL		\$ 8,732.90
	LESS 10%		\$ 873.29
	PARTS TOTAL		\$ 7,859.61
	SPECIAL NETT	QTY	PRICE
	REAR BUMPER CLIPS	1	\$ 100.00
	REAR FENDER COWLING CLIPS	1	\$ 100.00
	REAR DOOR INNER TRIM CLIPS	1	\$ 100.00
	SPECIAL NETT TOTAL		\$ 300.00
	LABOUR	QTY	PRICE
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	400	\$ 2,600.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	700	\$ 2,400.00
	TO RUST PROOF ACCIDENT AFFECTED AREA	30	\$ 160.00

TO RNR DOOR MECHANISM	60		\$ 400.00
TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	60		
TO RNR UNDERCARRAIGE SYSTEM	11 X		\$ 800.00
TO CHECK WHEEL ALIGNMENT	11 X		\$ 200.00
TO RNR TYRE AND WHEEL BALANCING	11 X		\$ 100.00
		LABOUR TOTAL	\$ 7,260.00
		GRAND TOTAL COST	\$ 15,419.61

PAGE 2 OF 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: