



FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



1/71: Front View



2/71: Front View Left



3/71: General View Left

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



4/71: Rear View



5/71: Rear View Left



6/71: Rear View Right

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



7/71: General View Right



8/71: Front View Right



9/71: Odometer Reading

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



10/71: General View



11/71: General View



12/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/71: General View



14/71: General View



15/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



16/71: General View



17/71: General View



18/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



19/71: General View




20/71: General View



21/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



22/71: General View



23/71: General View



24/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



25/71: General View



26/71: General View



27/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



28/71: General View



29/71: General View



30/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



31/71: General View



32/71: General View



33/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



34/71: General View



35/71: General View




36/71: General View

FBK4162H [SJV7950C1] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



37/71: General View



38/71: General View



39/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



40/71: General View




41/71: General View



42/71: General View


FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



43/71: General View



44/71: General View



45/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



46/71: General View



47/71: General View



48/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



49/71: **General View**



50/71: **General View**



51/71: **General View**

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



52/71: General View



53/71: General View



54/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



55/71: General View



56/71: General View



57/71: General View

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



58/71: General View



59/71: Chassis Number



60/71: Dismantled Parts

FBK4162H [SJV7950C] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



61/71: Dismantled Parts



62/71: Dismantled Parts



63/71: Dismantled Parts