

ASS. REC. BY:

REF:

ER21

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5508J

Yr Regn:

07, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

523821

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

VF1ABL15AUC 278828

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S / R / Im / STD A / R / Im or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

23/3/19

D.O.I.

27/3/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Red- \$15,885.97 / 80%

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS. \$

Parking

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EGH19005552/Kea3

Date: 04/04/2019

The Motor Claims Department
M/s ERGO INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 5508J

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/03/2019 at the premises of M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio and have the following to report:-

Workshop Estimate Amount	: S\$	19,735.97
Revised Estimate Amount	: S\$	3,850.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	3,850.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5508J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Mar 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001863
Chassis No.:	VF1ABL15AUC278828
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	11 Jul 2014
First Registration Date:	11 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Jul 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	10 Jul 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$53,269.00
COE Rebate Amount:	\$21,912.00
Total Rebate Amount:	\$31,285.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Mar 2019

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5508J**AAD1903-179***Not Authorized
1/10/2019 838501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5508J

VF1ABL15AUC278828

RENAULT

LATITUDE

23.3.2019

EGRO

11/7/2014

LIST

1	1	BUMPER COVER FRT	\$	<i>Bvulm</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75
3	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68
4	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 151.41
5	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
6	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77
7	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21
12	1	BUMPER BEAM FRT	\$	<i>nc</i> 914.08
13	1	TOW COVER FRT	\$	<i>Sn</i> 28.61
14	1	RADIATOR GRILLE	\$	<i>mjom</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>nc</i> 225.36 ✓
16	1	RADIATOR GRILLE FRAME	\$	<i>cm</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>nc</i> 89.79
19	1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43
20	1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43
21	1	HEADLAMP PANEL FRT LH	\$	<i>nc</i> 152.15
22	1	HEADLAMP PANEL FRT RH	\$	<i>nc</i> 152.15

TOTAL	\$	11,148.30
10%	\$	1,114.83
	\$	10,033.47

Trans-cab Auto Services Pte Ltd

AAD1903-179

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5508J

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	✓
2	1SET	BUMPER CLIP FRT	\$	na	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	}
4	1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
7	1	TOW COVER FRT	\$	na	14.50	
8	1SET	RADIATOR GRILLE SCREW	\$	na	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	na	69.00	} X
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
21	1	Windscreen moulding	\$	na	100.00	
22	1SET	Front licence plate with holder	\$	na	80.00	

TOTAL	\$	562.50
TOTAL PARTS	\$	10,595.97

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 3,000.00 ^{400l}

To apply paint protection system (PPS) maintain and enhancement

\$ na 380.00 X

Putty and spray painting of the affected portion.

\$ 3,000.00 ^{220l}

To rust-proofing of the affected areas.

\$ na 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ na 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1903-179**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5508J

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00	X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i> 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	X

TOTAL \$ 9,140.00**Over All Total \$ 19,735.97****(LUMP SUM) Repair Days****10 DAYS**
3 days

L&P Auto Consultants hereby notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during re-survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Nivitha (LKK Auto)

From: Jeannie Cheng <jeannie.cheng@ergo.com.sg>
Sent: Wednesday, 27 March 2019 2:03 PM
To: admin-d@lkkauto.com
Cc: sur@lkkauto.com
Subject: PRS IRO SHC5508J | OI : GBB9603S | DOA: 23/03/2019| ERGO REF: GBB9603S/SL/jc
Attachments: Estimate & GIA.pdf; GBB9603S SAS.PDF

Hi LKK,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and try to finalize with the repairer on the repairs. Their client's vehicle can be surveyed at the location as stated in the email below.

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

(Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.)

Thank you.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five Singapore 038985 jeannie.cheng@ergo.com.sg

www.ergo.com.sg

Kenneth

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

EMAIL DISCLAIMER

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Wednesday, 10 April, 2019 9:18 AM
To: 'Jeannie Cheng'
Cc: CS A Team; Asher Sng (LKKAUTO); Admin A; ERGO Insurance Pte. Ltd. (Claims Department)
Subject: RE: PRS IRO SHC5508J | OI : GBB9603S | DOA: 23/03/2019 | ERGO REF: GBB9603S/SL/jc
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf
Categories: HMK

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

EGI ref: TBA
LKK REF: CC4/EGI19005552/Kea3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SHC 5508J

- TP estimated cost of repair
- Preliminary Advice

We have not authorized repairs.

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)

Sent: Wednesday, 27 March, 2019 2:27 PM

To: 'Jeannie Cheng' <jeannie.cheng@ergo.com.sg>

Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: PRS IRO SHC5508J | OI : GBB9603S | DOA: 23/03/2019 | ERGO REF: GBB9603S/SL/jc

Dear Jeannie,

Thank you for the assignment.

Best Regards,

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment-----Original Message-----

From: Amanda Tay [mailto:amanda.tay@transcab.com.sg]

Sent: Wednesday, March 27, 2019 1:01 PM

To: ERGO Insurance Pte. Ltd. (Claims Department)

Cc: 'Candy Kong'; Jeannie Cheng; Survey Report (ERGO Insurance Pte. Ltd.)

Subject: RE: ARRANGE FOR SURVEY SHC5508J

Dear all,

As for the assessor, we will like to pick

6 LKK LKK Auto Consultants Pte Ltd

Thks & Rdgs

Amanda Tay

Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

-----Original Message-----

From: ERGO Insurance Pte. Ltd. (Claims Department) [mailto:claims@ergo.com.sg]

Sent: Wednesday, March 27, 2019 11:45 AM

To: Amanda Tay <amanda.tay@transcab.com.sg>

Cc: 'Candy Kong' <candy.kong@transcab.com.sg>; Jeannie Cheng <jeannie.cheng@ergo.com.sg>; Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Subject: RE: ARRANGE FOR SURVEY SHC5508J

WITHOUT PREJUDICE

Dear Sir,

GBB9603S - 23.03.2019 at 2107Hrs - SHC5508J

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate

Thks & Rdgs
Amanda Tay
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

This email has been checked for viruses by AVG.
<https://www.avg.com>

Mei Kwan (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 4 September, 2019 10:34 AM
To: Ivy Yong; Jia Le (LKK Auto)
Cc: CS A Team; Admin A
Subject: RE: CDMCG19000550 (GBB9603S) TP Veh : SHC5508J *** LKK REF: CC4/EGI19005552/Kda3

Categories: HMK

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Jia Le,

Please submit survey report.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ivy Yong <ivy.yong@ergo.com.sg>
Sent: Wednesday, 4 September, 2019 10:28 AM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Subject: CDMCG19000550 (GBB9603S) TP Veh : SHC5508J

Can send me your invoice?

Data Classification: Confidential, C3

Warmest Regards,
Ivy Yong
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9197
ivy.yong@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CC4/EGI19005552/Kda3q2		
5 TEMASEK BOULEVARD #04-05 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 10-09-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 9603S	Veh. Inspected	SHC 5508J	
Policy No.	DMCG18001355	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JEANNIE	Assign Date	27/03/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC278828	Colour	METALLIC WHITE / RED	
Odometer	523821	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/03/2019	Inspection Date	27/03/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5508J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER COVER FRT	BUCKLED / CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	MTG CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	CRACKED	1,353.75	1,353.75
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP RH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
LESS 10% DISCOUNT			-1,114.83	-454.63
			10,033.44	4,091.68
<u>SPECIAL NETT ITEMS</u>				
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00

Report Ref No. CC4/EG119005552/Kda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
			562.50	118.00
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,FRAME FULL SUPPORT BRACKET,HEADLAMP PANEL FRT LH AND HEADLAMP PANEL FRT RH .		3,000.00	400.00
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		3,000.00	220.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-

Report Ref No. CC4/EGI19005552/Kda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO VACUUM,REPLACE ,REFIX AND RECHARGE AIR CONDENSER .	NOT NECESSARY	380.00	-
	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM ,REPLACE ,REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			9,140.00	620.00
GRAND TOTAL			19,735.94	4,829.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,850.00

Report Ref No. CC4/EGI19005552/Kda3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.