## **MEGA SWIFT AUTO**

176 Sin Ming Drive #05-11

Sin Ming Autocare Singapore 575721

Tel No.: HP:97511604

Cash

Buss. Reg. No.: 52950829W

Sten (LKK) 8327 8813

29/3/19 12-10 pm

OD - Not Author (Revold)

8 days

EXCESS - \$ 10K

Ry damax pas & AF Spy

L/S

Quotation: WO000137

Date Printed: 27/03/2019 Vehicle Num.: SKM5877E Make/Model : FERRARI

Mileage(Km): P.O/R.O No. : Ref./Remark:

S/N	Quantity	Particular	Unit Price Amount S\$
1. 2. 3. 4.	1 1 1	Complete Front Fender Assembly / DD Front Bumper / DK Wiper Tank ? Wiper Tank Cover ?	27,590.27 27,590.27 16,188.35 16,188.35 463.20 463.20 1,257.00 1,257.00
		Labour Charge" To remove front fender & install panel To checking wireing To respary front fender assembly To respary front bumper	$\begin{array}{ccc} 2600 & 3,500.00 \\ 100 & 150.00 \\ 1000 & 1,500.00 \\ 600 & 750.00 \end{array}$

SingDollars : Fifty-One Thousand Three Hundred Ninety-Eight & Cents Eighty Two Only

Total S\$:

51,398.82

\_\_\_\_\_

Customer's Signature/Co. Stamp

for MEGA SWIFT AUTO

N.B.: Cheque should be crossed and made payable to MEGA SWIFT AUTO

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: