



凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 31/05/2019

Attn: The Motor Claims Department

Your Insured veh no : GBF 5911 H

ERGO Insurance Pte Ltd

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

WITHOUT PREJUDICE

(By Email Only)

Tel : 6829 9199

Fax : 6829 9247

Dear Sir / Madam

ACCIDENT INVOLVING VEHICLE NO GY 6966 J & GBF 5911 H on 22/03/2019 @07:30:00

We have been authorised by M/s Kian Heng Air-Conditioning Svc, the owner of vehicle claim against the party / parties responsible for the damages arising from number GY 6966 J, to the above mentioned accident.

Our records show that you are the insurers of vehicle numbe (GBF 5911 HP) at the material time of the accident with the driver of our client's vehicle, (Mr Woo Chee Kheong).

As a result of the accident caused by your insured driver's negligent driving and/or management of your insured's vehicle number (GBF 5911 H), our client's vehicle was damaged and we have been put to loss and damage as follows:

(1) Cost of repair	\$ 1,658.50
(2) Loss of use X days	\$ 270.00
(3) PIR 2days	\$ 180.00
(4) LTA Search Fee	\$ 7.45
	<u>\$ 2,115.95</u>

A cope of each of the following supporting documents is enclosed:

- (a) Final repair bill
- (b) GIA report with sketch plan of (our client's veh number)
- (c) LTA Search





凱 摩 哆 服 務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 31/05/2019

Attn: The Motor Claims Department

Your Insured veh no : GBF 5911 H

ERGO Insurance Pte Ltd

5 Temasek Boulevard

#04-01 Suntec Tower Five

Singapore 038985

WITHOUT PREJUDICE

(By Email Only)

Tel : 6829 9199

Fax : 6829 9247

Dear Sir / Madam

Final Cost repair Bill To Toyota Dyna NO GY 6966 J & GBF 5911 H on 22/03/2019 @07:30:00

To Supply :-

Total Lumpsum As Of Repair Costs Recommended By Surveyor And

Agreed By Ourselves : \$ 1,550.00

GST 7% \$ 108.50

\$ 1,658.50

