

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO : AXA	DATE : 26/3/2019
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	<i>28/3/19 12:30pm</i>
OWNER PARTICULAR NAME : <i>Steve (LKK) 87778813</i> ADDRESS : <i>Ry AL Ry 11 cly</i> TEL. NO. : VEHICLE DETAILS VEHICLE NO. : SJK6370R MODEL / MAKE : TOYOTA VIOS CHASSIS NO. : MR053HY9305081566	
OWNER INSUANCE : CN TAIPING	ACCIDENT DETAIL
POLICY NO. : DMPCSN3073801800	DATE : 26/3/2019
	TIME : 08:00 HRS
PERSON INCHARGE :	

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOT LID / <i>DD</i>	1	\$ 625.70	\$ 625.70
2	REAR BOOT LID LOGO EMBLEM / <i>NEC</i>	1	\$ 47.20	\$ 47.20
3	REAR BOOT LID E EMBLEM / <i>NEC</i>	1	\$ 36.71	\$ 36.71
4	REAR BOOT LID OUTER GARNISH / <i>CR4</i>	1	\$ 153.80	\$ 153.80
5	REAR BOOT LID OUTER KEY LOCK X <i>NN</i>	1	\$ 95.70	\$ 95.70
6	REAR NUMBER PLATE LAMP LH / RH X <i>NN</i>	2	\$ 45.80	\$ 91.60
7	REAR BOOT LID HINGES LH / RH / <i>RM - LH DD</i>	2	\$ 75.21	\$ 150.42
8	REAR BOOT LID RUBBER GUIDE STOPPER X <i>NN</i>	2	\$ 25.10	\$ 50.20
9	REAR BOOT LID MECHANISM LOCK / <i>DD</i>	1	\$ 119.01	\$ 119.01
10	REAR BOOT LID WEATHERSHIP / <i>CR4</i>	1	\$ 185.30	\$ 185.30
11	REAR TAILLAMP LH / RH / <i>RH - LH</i>	2	\$ 256.10	\$ 512.20
12	REAR TAILLAMP BACK RUBBER GASKET LH / RH / <i>NEC</i>	2	\$ 28.20	\$ 56.40
13	REAR TAILLAMP INNER PANEL LH / RH / <i>RH - LH DD</i>	2	\$ 205.24	\$ 410.48
14	REAR BUMPER / <i>DD</i>	1	\$ 527.15	\$ 527.15
15	REAR BUMPER REFLECTOR LH / RH	2	\$ 98.25	\$ 196.50
16	REAR BUMPER RETAINER LH / RH / <i>LH - RH DD</i>	2	\$ 85.00	\$ 170.00
17	REAR BUMPER CORNER RETAINER LH / RH	2	\$ 85.10	\$ 170.20
18	REAR BUMPER INNER SIDE SHIELD LH / RH	2	\$ 48.60	\$ 97.20
19	REAR END PANEL / <i>DD</i>	1	\$ 617.10	\$ 617.10
20	REAR END PANEL INNER TOP GARNISH / <i>OR</i>	1	\$ 182.50	\$ 182.50
21	REAR END PANEL LOCK STRIKER X <i>NN</i>	1	\$ 36.80	\$ 36.80
22	REAR ENG PANEL BRACKET PLATE LH / RH X <i>R</i>	2	\$ 38.20	\$ 76.40
23	SPARE TYRE PANEL / <i>DD</i>	1	\$ 657.20	\$ 657.20
24	SPRAY TYRE PANEL INNER TOP CARD BOARD / <i>CR4</i>	1	\$ 135.70	\$ 135.70
25	SPARE TYRE PANEL INNER TOP SPONGE	1	\$ 125.60	\$ 125.60
26	SPARE TYRE SIDE PANEL LH / RH X <i>NN</i>	2	\$ 105.70	\$ 211.40
27	SPARE TYRE SIDE PANEL INNER TOP SPONGE LH / RH / <i>CR4 LH 2</i>	2	\$ 95.10	\$ 190.20

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	SPRAY TYRE RETAINER LOCK / CR4	1	\$ 45.60	\$ 45.60
29	REAR FENDER LH / RH LH - RH DD	2	\$ 826.10	\$ 1,652.20
30	REAR FENDER INNER AIR VENT LH	1	\$ 123.50	\$ 123.50
31	REAR FENDER INNER UPHOLSTERY TRIM LH / RH / LH / RH CR4	2	\$ 213.60	\$ 427.20
32	REAR WINDSCREEN GLASS MOULDING / NLC	1	\$ 28.60	\$ 28.60
33	REAR EXHAUST SILENCER BOX ?	1	\$ 298.60	\$ 298.60
34	REAR EXHAUST END CHROME PIPE / DD	1	\$ 125.70	\$ 125.70
35	REAR EXHAUST GASKET / NLC	1	\$ 35.80	\$ 35.80
36	REAR EXHAUST RUBBER MOUNTING / TN	28	\$ 28.90	\$ 86.70
37	REAR EXHAUST ALUMINIUM HEAT SHIELD ?	1	\$ 185.70	\$ 185.70
38	REAR SUB CHAISIS FRAME LH / RH X R	2	\$ 455.80	\$ 911.60
TOTAL PRICE				\$ 9,849.87
LESS -25%				\$ (2,462.47)
SUB TOTAL PRICE				\$ 7,387.40

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BOOTG LID OUTER GARNISH CLIPS SET	1	\$ 30.00	\$ 10 30.00
2	REAR BOOT NUMBER PLATE WITH GARNISH BR /	1	\$ 60.00	\$ 35 60.00
3	REAR TAILLAMP CLIPS SET LH / RH	2	\$ 30.00	\$ 10 60.00
4	REAR TAILLAMP BRAKE BULB LH / RH ?	2	\$ 15.00	\$ 30.00
5	REAR TAILLAMP SIGNAL BULB LH / RH X	2	\$ 15.00	\$ 30.00
6	REAR TAILLAMP REVERSE BULB LH / RH X	2	\$ 15.00	\$ 30.00
7	REAR BUMPER REVERSE SENSOR / BR	1	\$ 280.00	\$ 200 280.00
8	REAR BUMPER CLIPS SET / NLC	1	\$ 60.00	\$ 25 60.00
9	REAR END PANEL INNER TOP GARNISH CLIPS SET	1	\$ 40.00	\$ 10 40.00
10	SPRAY TYRE PANEL INSULATOR MAT X	1	\$ 380.00	\$ 380.00
11	SPRAY TYRE PANEL INNER TOP JACKING TOOL X	1	\$ 180.00	\$ 180.00
12	SPRAY TYRE PANEL INNER TOP BREAK SOWN X	1	\$ 150.00	\$ 150.00
13	REAR FENDER INSULATOR MAT LH/ RH / NLC - RH	2	\$ 180.00	\$ 50 360.00
14	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH / RH NLC	2	\$ 60.00	\$ 20 120.00
15	REAR WINDSCREEN INNER GARNISH CLIPS SET LH / RH / NLC	2	\$ 30.00	\$ 20 60.00
16	REAR WINDSCREEN SEALANT WITH PRIMER / NLC	1	\$ 100.00	\$ 80 100.00

TOTAL

\$ 1,970.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 2,400.00	1540	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 2,000.00	1100	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00	50	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 280.00	X	
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 220.00	7	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	100 30	
TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 150.00	30	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	20	
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 180.00	50	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	50	
TOWING SERVICE ACCIDENT SCENE TOW TO WORKSHOP	\$ 80.00	Bill /	

TOTAL

\$ 6,100.00

QUOTATION SUMMARY

PAGE 04

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	9,357.40
TOTAL LABOUR COST	:	\$	6,100.00
TOTAL REPAIR COST	:	\$	<u>15,457.40</u>

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :