

# AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: AXA INSURANCE

DATE: 28/03/2019  
 VEHICLE NO: SLA2961R  
 MODEL: VOLKSWAGEN JETTA  
 YEAR: 2010  
 ACCIDENT DATE: 27/03/2019  
 CLAIM ADVISOR: LOUIS (97684247)  
 EMAIL:

## ESTIMATION

### DESCRIPTION

### QTY

### LIST PRICE

#### PARTS

BONNET <i>repair</i>	1	\$1,210.20
BONNET LOCK <i>X</i>	1	\$365.10
FRONT EMBLEM <i>CRA</i>	1	\$95.40
FRONT LOGO -TSI <i>X</i>	1	\$92.10
FRONT GRILLE <i>CRA</i>	1	\$967.30
FRONT GRILLE CLIPS <i>new</i>	10	\$50.00
FRONT BUMPER <i>DE</i>	1	\$1,156.30
FRONT BUMPER CLIPS <i>new</i>	10	\$50.00
FRONT BUMPER RETAINER <i>X</i>	2	\$114.60
FRONT BUMPER BRACKET <i>?</i>	2	\$188.40
FRONT BUMPER LOWER CENTRE GRILLE <i>?</i>	1	\$355.20
FRONT BUMPER TOWING COVER <i>X</i>	1	\$98.10
FRONT BUMPER PROTECTOR <i>X</i>	2	\$486.40
FRONT BUMPER LOWER SPOILER <i>cut</i>	1	\$574.10
FRONT NUMBER PLATE GARNISH <i>X</i>	1	\$143.70
AIR DUCT <i>X</i>	1	\$453.10
RADIATOR TOP COVER <i>X</i>	1	\$365.10
RADIATOR TOP COVER CLIPS <i>X</i>	10	\$30.00
FRONT BUMPER SPONGE <i>?</i>	1	\$297.50
FRONT REINFORCEMENT BRACKET <i>?</i>	2	\$188.40
FRONT REINFORCEMENT <i>?</i>	1	\$576.30
SUPPORT PANEL - TOP <i>?</i>	1	\$474.10
SUPPORT PANEL <i>?</i>	1	\$896.30

# AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: AXA INSURANCE

DATE: 28/03/2019  
 VEHICLE NO: SLA2961R  
 MODEL: VOLKSWAGEN JETTA  
 YEAR: 2010  
 ACCIDENT DATE: 27/03/2019  
 CLAIM ADVISOR: LOUIS (97684247)  
 EMAIL:

## ESTIMATION

HEADLAMP ?	2	\$1,978.80
HEADLAMP PANEL ?	2	\$298.40
FOGLAMP X	2	\$598.60
FOGLAMP COVER X	2	\$288.40
INTERCOOLER X	1	\$1,245.60
CONDENSER X	1	\$894.10
CONDENSER AIR GUIDE X	2	\$266.40
RADIATOR X	1	\$911.30
LH FRONT FENDER X	1	RESTORE
RH FRONT FENDER X	1	RESTORE
BOOTLID H - ?	1	\$1,342.10
BOOTLID LAMP ?	2	\$698.40
BOOTLID HINGE X	2	\$324.60
REAR LOGO - JETTA per	1	\$76.40
BOOTLID LOCK cut	1	\$299.50
REAR BUMPER DE	1	\$1,081.30
REAR BUMPER CLIPS per	10	\$50.00
REAR BUMPER DIFFUSER DE	1	\$567.30
REAR BUMPER RETAINER X	2	\$114.60
REAR BUMPER BRACKET X	2	\$188.40
REAR BUMPER REFLECTOR X	2	\$298.60
REAR NUMBER PLATE LAMP X	2	\$366.20
REAR BUMPER SPONGE ?	1	\$197.50

# AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE

#04-142 SINGAPORE 608586

ATTN: AXA INSURANCE

DATE: 28/03/2019  
 VEHICLE NO: SLA2961R  
 MODEL: VOLKSWAGEN JETTA  
 YEAR: 2010  
 ACCIDENT DATE: 27/03/2019  
 CLAIM ADVISOR: LOUIS (97684247)  
 EMAIL:

## ESTIMATION

REAR REINFORCEMENT ?  
 END PANEL repair  
 SPARE TYPE PANEL X  
 END PANEL TOP GARNISH ?  
 REAR WEATHER STRIP new  
 REVERSE SENSOR ?  
 REVERSE SENSOR HOLDER new  
 REAR EXHAUST PIPE X  
 REAR EXHAUST PIPE FINISHER X

1	\$453.10
1	\$569.20
1	RESTORE
1	\$299.60
1	\$287.90
2	<del>\$445.40</del> 200? 3/12
2	\$64.20
1	\$1,654.20
2	\$462.60

TOTAL: \$25,551.40  
 DISCOUNT 10%: \$2,555.14  
\$22,996.26

## S/NET

REAR NUMBER PLATE 35  
 FRONT NUMBER PLATE 35  
 REAR END PANEL SEALANT X  
 COOLANT X  
 ATF OIL X

1	35	<del>\$100.00</del>
1	35	<del>\$100.00</del>
1		\$80.00
1		\$50.00
1		\$150.00

TOTAL: \$480.00

LABOUR

PRICE

# AUTOWHEELS

MOTORWORKS PTE LTD

48 TOH GUAN ROAD EAST ENTERPRISE  
#04-142 SINGAPORE 608586

ATTN: AXA INSURANCE

DATE: 28/03/2019  
VEHICLE NO: SLA2961R  
MODEL: VOLKSWAGEN JETTA  
YEAR: 2010  
ACCIDENT DATE: 27/03/2019  
CLAIM ADVISOR: LOUIS (97684247)  
EMAIL:

## ESTIMATION

LABOUR FOR FACILITATE REPAIR - FRONT PORTION	\$1,800.00	300
LABOUR FOR FACILITATE REPAIR - REAR PORTION	\$1,500.00	
TO RESPRAY AFFECTED AREAS - BONNET	\$300.00	200
TO RESPRAY AFFECTED AREAS - FRONT BUMPER	\$300.00	200
TO RESPRAY AFFECTED AREAS - RH FRONT FENDER	\$250.00	X
TO RESPRAY AFFECTED AREAS - LH FRONT FENDER	\$250.00	X
TO RESPRAY AFFECTED AREAS - BOOTLID	\$300.00	200
TO RESPRAY AFFECTED AREAS - REAR BUMPER	\$300.00	200
TO RESPRAY AFFECTED AREAS - REAR BUMPER DIFFUSER	\$250.00	X
TO RESPRAY AFFECTED AREAS - END PANEL	\$250.00	200
TO RESPRAY AFFECTED AREAS - SPARE TYRE PANEL	\$250.00	X
TO REMOVE AND REFIT AC CONDENSER INCLUDING TOP UP AC GAS	\$150.00	100. X
TO REMOVE AND REFIT RADIATOR INCLUDING WATER PRESSURE TEST	\$150.00	X
TO REMOVE AND REFIT INTERCOOLER	\$250.00	X
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	\$150.00	60
TO REMOVE AND REFIT REAR EXHAUST PIPE FOR FACILITATE REPAIR	\$350.00	X
TO REMOVE AND REFIT REVERSE SENSOR	\$100.00	60
TO CHECK AND RECONNECT ALL NECESSARY WIRING	\$100.00	30
SUNDRIES	\$50.00	20
RUST PROOFING	\$80.00	40

TOTAL: \$7,130.00

TOTAL: \$30,606.26

7% GST: \$2,142.44

\$32,748.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul  
Hp 90010068

7 days

4/5

29/03/19 @ 1550

Resurvey after repair