

Wang Pei Han

CC 3, ASM 1900

5672, K8a3s2

107907

ASSIGNMENT

Surveyor:

KSC

DOI:

28/03/2019

Date / Time:

28/03/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SMG 9494 H

Claim No. :

59M0110V

Name of Insured :

Sarah Leo Beng Wee

Policy No. :

Insured Tel No. :

HP:

Make / Model :

Excess Sec II :SS

D.O.A :

28/03/2019

Place of Accident :

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

Site 5528 B



INSRS:

WSP:

Tel :

Liability :

RMKS:

Trans-Cab




INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handley Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: SS (days) Reduction: % Email Call

FINAL SETTLEMENT Date/Time: Confirm with: Email Call

Final Liability: % (Agreed / Assessed) BOLA S/N No. : If NO or B 28, Ass. Lia :

Repair Cost: SS Loss of Rental (LOR): SS (days) Loss of Use (LOU): SS (\$ x days) Loss of Income (LOI): SS (\$ x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: SS Medical: SS Disbursement: SS (e.g. Tow/ Independent) Legal Cost: SS

Total: SS Global Sum SS: 1) Claim status: Normal/Reject/Private Settle 2) Report Format: 3) Survey fee:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS Name 1: Payee 2: (Strike if N.A.) SS Name 2: Payee 3: (Strike if N.A.) SS Name 3:

COPY SENT 20/11/19

ASS. REC. BY:

REF: ADA /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Tans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S14C 5528B Yr Regn: 08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Pencult Latitude c.c 1995

Colour: M. White / RW A/C: Insured / Std / NI / NA

Sp. Reading: 513199 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: V1-1 AB215AUC - 278889

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Giti

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 27/3/19

Rear

R/Bal. 9 mm

L/Bal. P mm

D.O.I. 28/3/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or 015 Rear body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to Lisy & food

(Recd of 26885.04 80%)

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____

S + RS. \$ _____

Fuels

Others

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5528B**AAD1903-213***NOT Authorized
L/Sing & 67001*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHC 5528B
 VF1ABL15AUC278869
 RENAULT
 LATITUDE
 27.3.2019
AXA
 15/8/2014

	PART		LIST
1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66 ✓
1	DOOR GUIDE REAR RH	\$	<i>S</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>H</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>H</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>S</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>H</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>S</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>S</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>S</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>S</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>S</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>S</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>S</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>S</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>S</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>S</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>S</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>N</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>S</i> 6.91
1	DOOR CASING REAR RH	\$	<i>S</i> 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	<i>S</i> 30.39
1	DOOR CASING CLIP	\$	<i>N</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>S</i> 48.74
1	DOOR FINISHER INNER REAR RH	\$	<i>S</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>H</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>H</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>H</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>H</i> 20.33
1	DOOR GRAB HANDLE REAR RH	\$	<i>S</i> 210.96

X

Trans-cab Auto Services Pte Ltd

AAD1903-213

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5528B

1	DOOR BLIND REAR RH	\$	Sm	741.80	X
1	DOOR WHEATHESTRIIP REAR RH	\$	Sm	410.66	X
1	DOOR SEAL REAR RH	\$	Sm	162.02	X
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Sm	229.31	X
1	DOOR WAIST SEAL OUTER REAR RH	\$	Sm	334.69	X
1	DOOR WAIST SEAL INNER REAR RH	\$	Sm	115.64	X
1	FENDER PANEL REAR RH	\$	R	3,299.13	✓
1	FENDER PANEL INNER TRIM REAR	\$	Sm	671.45	X
1	WHEELARCH REAR RH	\$	R	543.47	X
1	DOOR MIRROR ASSY RH	\$	Sm	1,483.40	X
1	ROCKER PANEL INNER GARNISH RH	\$	Sm	466.51	X
1	ROCKER PANEL INNER RH	\$	R	1,024.79	X
1	ROCKER PANEL CENTER RH	\$	R	990.25	X
1	BUMPER COVER REAR	\$	Bu/R	1,108.46	✓
1	BUMPER LOWER REAR	\$	Sm	768.84	} X
1	BUMPER BRACKET CTR REAR	\$	Sm	113.47	
1	BUMPER BRACKET SIDE RH REAR	\$	Sm	135.97	
1	BUMPER RETAINER RH REAR	\$	Sm	44.99	
1	REAR TAILAMP RH	\$	Sm	552.55	
		\$		23,125.98	
		10% \$		2,312.60	
		\$		20,813.38	

Special Nett

1	REAR DOOR STICKER '6555-3333"	\$	nn	80.00	Gosa
1	DOOR CHECK BOLT	\$	nn	22.69	} X
1	DOOR GUIDE SCREW	\$	nn	10.85	
1	DOOR HINGE BOLT	\$	nn	10.85	
1	DOOR HINGE NUT RH	\$	nn	14.60	
1	DOOR CHECK BOLT	\$	nn	22.69	
1	DOOR CHECK NUT	\$	nn	3.75	
1	DOOR LOCK SCREW L70Y	\$	nn	6.12	
1	DOOR CATCH SCREW L70Y	\$	nn	10.06	
TOTAL		\$		181.63	

Trans-cab Auto Services Pte Ltd

AAD1903-213

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5528B

TOTAL PARTS	\$	20,995.01
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>8001</i>
Putty and spray painting of the affected portion.	\$	4,200.00 <i>6601</i>
To rust-proofing of the affected areas.	\$	170.00 <i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 <i>1001</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>601</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00 <i>201</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>601 X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 <i>601</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 <i>X</i>
Towing Fees.	\$	<i>nn</i> 120.00 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1903-213

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5528B

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *~* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *~* 380.00 X

TOTAL \$ 12,590.00

Over All Total \$ 33,585.01

LUMP SUM (REPAIR DAY)

15 DAYS
5 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5528B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Mar 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001876
Chassis No.:	VF1ABL15AUC278869
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	15 Aug 2014
First Registration Date:	15 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,088.00
COE Rebate Amount:	\$21,172.00
Total Rebate Amount:	\$30,545.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Mar 2019

OK

Hsiao Tong (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 9 September 2019 5:54 PM
To: Hsiao Tong (LKKAuto)
Cc: 'Jasmine Tan'; 'claims'
Subject: FW: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]
Attachments: Statement of SMG9494H.pdf; SHC5528B DOA 27.03.19.wmv

WITHOUT PREJUDICE


Dear Hsiao Tong

Please see the attachment for video footage.

Your insured turning out from the right without checking for the oncoming vehicle and hit onto our taxi.

Circumstances of Accident

On 27.03.2019 at about 1640hours, I was travelling straight on the extreme right lane along Dunearn Road. Su impact. Vehicle B (SMG9494H) which drive out from my right without checking for oncoming vehicle and hit onl side rear portion.



Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Saturday, 7 September, 2019 3:58 PM

To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>;

claims@transcab.com.sg

Subject: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

Your Ref: AAD1903-213 (SHC5528B)

Without Prejudice

Our Ref: CC3/ASM19005672/Kpa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019

We refer to the above matter.

Please be informed that liability is unclear. Our insured reported that your client had cut across the double white line and resulted the accident. Attached is a copy of our insured accident report for your easy reference.

As per AXA instruction, we would like to request for evidences (ie: video footage/ scene photos / PIR) for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Hsiao Tong (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 24 October 2019 5:15 PM
To: Hsiao Tong (LKKAuto)
Cc: jasminetan@transcab.com.sg; 'claims'; Admin A
Subject: RE: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]
Attachments: AAD1903-213 - LOD.pdf; DSCN3168.JPG; DSCN3169.JPG; DSCN3167.JPG

WITHOUT PREJUDICE

Dear Hsiao Tong

Enclosed is our LOD and after paint photos for your action.

Hope you can review and let us have your best offer.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Thursday, 24 October, 2019 10:02 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'claims' <claims@transcab.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

Without Prejudice

Hi Wai Yin,

We refer to the above matter.

Please provide the following for our necessary action: -

- After repair/ after paint photos
- LOD
- Authorisation to Act
- Final Repair Invoice
- Rental

- LTA search fee

Thanks.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Monday, 9 September 2019 5:54 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'claims' <claims@transcab.com.sg>

Subject: FW: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

WITHOUT PREJUDICE


Dear Hsiao Tong

Please see the attachment for video footage.

Your insured turning out from the right without checking for the oncoming vehicle and hit onto our taxi.

Circumstances of Accident

On 27.03.2019 at about 1640hours, I was travelling straight on the extreme right lane along Dunearn Road. Su impact. Vehicle B (SMG9494H) which drive out from my right without checking for oncoming vehicle and hit ont side rear portion.



Thank You

Best Regards,

Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]
Sent: Saturday, 7 September, 2019 3:58 PM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg
Subject: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

Your Ref: **AAD1903-213 (SHC5528B)**
Our Ref: CC3/ASM19005672/Kpa3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019

We refer to the above matter.

Please be informed that liability is unclear. Our insured reported that your client had cut across the double white line and resulted the accident. Attached is a copy of our insured accident report for your easy reference.

As per AXA instruction, we would like to request for evidences (ie: video footage/ scene photos / PIR) for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."


Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com



<TP - Mandate IA> -S9M01IDV [ACCIDENT INVOLVING SMG 9494H(OI) & SHC 5528B(TP) ON 27/03/2019]

Type

📌 Question

Message

Liability: 100%. Insured turned out from minor road and collided with third party who was on main road. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$7,963.23(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 29-Oct-19

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 29/10/2019

Survey Details:

Date of loss	27-Mar-19
Date of appointment	28-Mar-19
Date of survey	28-Mar-19
Location of survey	TRANS-CAB AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SHC 5528B
Make and Model	RENAULT LATITUDE 2.0L DCI - 1995cc
Date of registration	15-Aug-14
Parf Rebate	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	\$ 33,585.01
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 6,587.03
Check items (estimate)	\$ -
Labour	\$ 1,780.00
Total	\$ 8,367.03
Lump Sum(if applicable)	\$ 6,700.00

Number of days for repair	5
---------------------------	---



Remarks:

Both parties show that OID turned out from minor road and collided with third party who was on main road.

Mandate:

Liability(TP)		100%	
Proposed repair cost (w/GST)	\$	7,169.00	
Loss of use		NIL	
Loss of rental	\$	486.78	(6days x \$81.13)
Loss of income	\$	300.00	(6days x 50.00)
LTA search fees	\$	7.45	
Others		NIL	
Proposed Total	\$	7,963.23	

Hsiao Tong (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Tuesday, 29 October 2019 5:09 PM
To: Hsiao Tong (LKKAuto)
Subject: RE: New message for service request 107907, vehicle number SHC5528B

<input type="checkbox"/>	**OI turned out from side road and collided with TP	CHT	18/10/2019 12:17:36 PM
<input type="checkbox"/>	SENT LETTER TO OI VIA EMAIL (100%) **KIV	CHT	18/10/2019 12:17:53 PM
<input type="checkbox"/>	**TP LOD IN VIA EMAIL	CHT	25/10/2019 11:47:49 AM
<input type="checkbox"/>	Message AXA : Liability: 100%. Insured turned out from minor road and collided with third party who was on main road. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$7,963.23(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/Instruction. Hsiao Tong – 29-Oct-19	CHT	29/10/2019 10:14:21 AM
<input type="checkbox"/>	29/10/19 4:59 PM WANG Peter -----Pls proceed DS with quantum as proposed -----LOR is subject to rental agreement.	LSP	29/10/2019 4:56:06 PM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 29 October 2019 5:05 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 107907, vehicle number SHC5528B

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: peter.wang@axa.com.sg <peter.wang@axa.com.sg>
Sent: Tuesday, 29 October, 2019 5:00 PM
To: admin-d@lkkauto.com
Subject: New message for service request 107907, vehicle number SHC5528B

AXA Insurance has sent you a message for claim number S9M01IDV.

Hsiao Tong (LKKAuto)

From: Jasmine Tan <jasminetan@transcab.com.sg>
Sent: Thursday, 14 November 2019 7:40 PM
To: Hsiao Tong (LKKAuto); 'Ng Wai Yin'
Cc: 'claims'; Admin A
Subject: RE: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Thursday, 7 November 2019 9:23 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: jasminetan@transcab.com.sg; 'claims' <claims@transcab.com.sg>; Admin A <admin-a@lkkauto.com>
Subject: RE: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of **\$7,800.00(all-in)**.

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Thursday, 24 October 2019 5:15 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: jasminetan@transcab.com.sg; 'claims' <claims@transcab.com.sg>; Admin A <admin-a@lkkauto.com>

Subject: RE: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

WITHOUT PREJUDICE

Dear Hsiao Tong

Enclosed is our LOD and after paint photos for your action.

Hope you can review and let us have your best offer.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63

Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

Sent: Thursday, 24 October, 2019 10:02 AM

To: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'claims' <claims@transcab.com.sg>; Admin A <admin-a@lkkauto.com>

Subject: RE: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

Without Prejudice

Hi Wai Yin,

We refer to the above matter.

Please provide the following for our necessary action: -

- After repair/ after paint photos
- LOD
- Authorisation to Act
- Final Repair Invoice
- Rental

- LTA search fee

Thanks.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Monday, 9 September 2019 5:54 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'claims' <claims@transcab.com.sg>

Subject: FW: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

WITHOUT PREJUDICE


Dear Hsiao Tong

Please see the attachment for video footage.

Your insured turning out from the right without checking for the oncoming vehicle and hit onto our taxi.

Circumstances of Accident

On 27.03.2019 at about 1640hours, I was travelling straight on the extreme right lane along Dunearn Road. Su impact. Vehicle B (SMG9494H) which drive out from my right without checking for oncoming vehicle and hit onl side rear portion.



Thank You

Best Regards,

Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]
Sent: Saturday, 7 September, 2019 3:58 PM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg
Subject: Your Ref: AAD1903-213 (SHC5528B) *Our Ref: CC3/ASM19005672/Kpa3 [ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019]

Your Ref: **AAD1903-213 (SHC5528B)**
Our Ref: CC3/ASM19005672/Kpa3

Without Prejudice

Dear Sirs/Mdm,

ACCIDENT INVOLVING SMG9494H(AXA) AND SHC5528B ON 27/03/2019

We refer to the above matter.

Please be informed that liability is unclear. Our insured reported that your client had cut across the double white line and resulted the accident. Attached is a copy of our insured accident report for your easy reference.

As per AXA instruction, we would like to request for evidences (ie: video footage/ scene photos / PIR) for our necessary action.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63
Tel No.: 6287 6666 Fax No. 6281 1400
Co./GST Reg. No. 200303878K

LKK

Our Ref : AAD1903-213
Your Ref : SMG9494H
Date : 06.May 2019

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SHC5528B AND SMG9494H ON 27/03/19 04:40 PM ALONG Dunearn Road towards City

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	7,169.00
2.	Loss of Rental for <u>6</u> days @ \$ <u>81.13</u> per day	\$	486.78
3.	Loss of Income for <u>6</u> days @ \$ <u>50</u> per day	\$	300.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	7,963.27

We enclose a copy of the following documents for your consideration :-

- | | |
|---------------------------------|---------------------------------|
| GIA report lodged by our driver | Rental rate and mileage records |
| Certificate of Insurance | Authorization To Act |
| Original final repair bill | LTA Search Fee |

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully
Trans-Cab Services Pte Ltd



Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

Trans-Cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel: 6287 6666

Fax: 6287 7764

Co. Reg. No.: 201019626G

GST Reg. No.: 201019626G

Tax Invoice / Debit Note

TO: AXA INSURANCE PTE LTD 8 SHENTON WAY,#27-01 AXA TOWER 068811 SINGAPORE ATTENTION:	INVOICE NO. : INV1904-174 DATE : 30. April 2019 REFERENCE NO : AAD1903-213 TERMS : DUE DATE : 30. April 2019 PAGE : 1
---	--

NO.	CODE	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1.	6050101	REPAIR-SHC5528B;DOA 27.03.19(LUMP SUM-19)	1	7,169.00	7,169.00

Total SGD Excl. GST : 6,700.00

7% GST : 469.00

**** SEVEN THOUSAND ONE HUNDRED SIXTY NINE SGD ONLY ****

Total SGD Incl. GST : 7,169.00

- 1) All cheques should be crossed and made payable to "Trans-Cab Auto Services Pte Ltd"
- 2) Please quote our Invoice Number during payment.
- 3) We reserve the right to charge interest @ 1.5% per month on overdue invoice.
- 4) Any dispute as to the accuracy, charges etc of this invoice must be communicated within 10 days from the date hereof failing which it shall be deemed to have been unconditionally accepted.

E. & O. E.

THIS IS A COMPUTER GENERATED INVOICE WHICH REQUIRES NO SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC3/ASM19005672/Kpa3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: PETER WANG		Date : 21-11-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMG 9494H	Veh. Inspected	SHC 5528B
Policy No.	P2236537	Coverage (\$)	0.00
Claim No.	S9M01IDV	Excess (\$)	0.00
Assign From		Assign Date	28/03/2019
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC278869	Colour	MEATLLIC WHITE / RED
Odometer	513194	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	7 mm
L/H Front Tyre	215/60 R16	GITI	7 mm
R/H Rear Tyre	215/60 R16	GITI	9 mm
L/H Rear Tyre	215/60 R16	GITI	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/03/2019	Inspection Date	28/03/2019
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5528B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR PANEL REAR RH (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR RH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH (CONSISTENT)	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH (CONSISTENT)	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH / RH L70Y (CONSISTENT)	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR RH (CONSISTENT)	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH (CONSISTENT)	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH (CONSISTENT)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR RH (CONSISTENT)	SERVICEABLE	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH (CONSISTENT)	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUR REAR L70Y (CONSISTENT)	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT)	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y (CONSISTENT)	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT)	SERVICEABLE	6.91	-
1	DOOR CASING REAR RH (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR RH (CONSISTENT)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR RH (CONSISTENT)	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR RH (CONSISTENT)	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH (CONSISTENT)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH (CONSISTENT)	SERVICEABLE	115.64	-
1	FENDER PANEL REAR RH (CONSISTENT)	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR (CONSISTENT)	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	543.47	-
1	DOOR MIRROR ASSY RH (CONSISTENT)	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH RH (CONSISTENT)	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER RH (CONSISTENT)	TO REPAIR SEE LABOUR	990.25	-
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED / DENTED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR (CONSISTENT)	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	REAR TAILLAMP RH (CONSISTENT)	SERVICEABLE	552.55	-
	LESS 10% DISCOUNT		-2,312.58	-725.22
			20,813.40	6,527.03
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER "6555-3333" (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN) (CONSISTENT)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN) (CONSISTENT)	NOT NECESSARY	10.85	-

Report Ref No. CC3/ASM19005672/Kpa3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HINGE NUT RH (SN) (CONSISTENT)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN) (CONSISTENT)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN) (CONSISTENT)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	10.06	-
			181.61	60.00
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK REAR RH, DOOR FINISHER BRACKET INNER REAR RH, WHEELARCH REAR RH, ROCKER PANEL INNER RH AND ROCKER PANEL CENTER RH.		4,500.00	800.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	660.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-

Report Ref No. CC3/ASM19005672/Kpa3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			12,590.00	1,780.00
GRAND TOTAL			33,585.01	8,367.03
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,700.00

Report Ref No. CC3/ASM19005672/Kpa3

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.