



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM)

#04-04 Singapore 757047

Tel: 65 6493 1924

Fax: 65 6493 1928

VEHICLE REPAIR ESTIMATE

Insurance Company: AXA INSURANCE

Address:

Telephone:

Fax:

Email:

Make/ Model : BMW X1

Date: 25-02-19

Chassis No : WBAJG12080EG23842

Vehicle No: SFH8333Z

Date/Time of Accident : 23-01-19 14:50

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	FRONT BUMPER <i>DEF /</i>	1	\$ 1,040.90	10%	\$ 936.81
2	FRONT BUMPER SIDE BRACKET RH <i>rec /</i>	1	\$ 123.50	10%	\$ 111.15
3	FRONT BUMPER FOG LAMP RH <i>nnx</i>	1	\$ 377.80	10%	\$ 340.02
4	FRONT BUMPER FOG LAMP COVER RH <i>nnx</i>	1	\$ 149.55	10%	\$ 134.60
5	FRONT BUMPER PARKING SENSOR RH <i>Shunted /</i>	2	\$ 728.30	10%	\$ 655.47
6	FRONT BUMPER NOZZLE RH <i>nnx</i>	1	\$ 234.90	10%	\$ 211.41
7	FRONT BUMPER NOZZLE COVER RH <i>nnx</i>	1	\$ 71.55	10%	\$ 64.40
8	FRONT BUMPER SPONGE <i>nnx</i>	1	\$ 62.40	10%	\$ 56.16
9	FRONT BUMPER REINFORCEMENT <i>nnx</i>	1	\$ 494.80	10%	\$ 445.32
10	FRONT BUMPER FOG LAMP GRILLE RH <i>nnx</i>	1	\$ 162.55	10%	\$ 146.30
11	FRONT BUMPER LOWER <i>nnx</i>	1	\$ 390.00	10%	\$ 351.00
12	FRONT HEADLAMP RH <i>scr /</i>	1	\$ 3,900.00	10%	\$ 3,510.00
13	FRONT HEADLAMP LOWER BRACKET RH <i>nnx</i>	1	\$ 179.45	10%	\$ 161.51
14	FRONT HEADLAMP PANEL RH <i>nnx</i>	1	\$ 185.90	10%	\$ 167.31
15	FRONT SUPPORT PANEL <i>nnx</i>	1	\$ 390.00	10%	\$ 351.00
16	FRONT FENDER RH <i>nnx</i>	1	\$ 910.10	10%	\$ 819.09
17	FRONT FENDER SHIELD RH <i>nnx</i>	1	\$ 205.45	10%	\$ 184.91
18	FRONT FENDER ARCH GARNISH <i>scr /</i>	1	\$ 208.80	10%	\$ 187.92

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT BUMPER CLIP <i>rec /</i>	10	\$ 50.00	\$ 30 50.00
2	FRONT FENDER SPLASH SHIELD CLIP <i>nnx</i>	10	\$ 40.00	\$ 40.00
Total Special Items Cost				\$ 8,924.36

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 250 600 00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 250 800 00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 20 150.00
TO REMOVE/ REFIT WIRING CHECKS	\$ 30 60.00
TO REMOVE/ REPLACE PARKING SENSORS	\$ 30 100.00
Total Others Cost	\$ 310.00
GRAND TOTAL	\$ 10,634.36

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
Direct Contact: 65 8322 7418
Email: jeslyn@carzauto.com.sg

Three J2-LKK

8/4/19

L/s 3days.

