

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : LONPAC INSURANCE BHD
 100 BEACH ROAD
 #19-00 SHAW TOWERS
 SINGAPORE 189702

TEL: 62507388 FAX: 62962706
 ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST1900083
Date: 29 Mar 2019

Veh Reg No: SKE2541K
Make/Model: TOYOTA VIOS E
 MANUAL
Chasis No: MR053HY9305288484
Reg. Date: 20/02/2012
Your Ref No: SLU3460H

Claim Type: Third Party
Accident Date: 28/03/2019
TP Veh Reg No: SLU3460H

Joy

Estimate Repair Cost to Vehicle No :SKE2541K

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC REAR BUMPER <i>Rebonded</i>	487.50 ✓	
2	1 PC REAR BUMPER BRACKET RH <i>new</i>	69.70 +	
3	1 PC REAR BUMPER SIDE RETAINER <i>new</i>	113.90 ✓	
4	1 PC REAR BUMPER RETAINER (SMALL) RH <i>new</i>	36.20 ✓	
5	1 PC REAR BUMPER REFLECTOR - RH <i>could</i>	94.70 ✓	
6	1 PC REAR PANEL <i>rebed</i>	688.10 ✓	539
7	1 PC TAIL LAMP - RH <i>could</i>	409.90 ✓	289.60
8	1 PC REAR FENDER MUDFLAP <i>new</i>	65.20 +	
9	1 PC BOOT LID RUBBER <i>new</i>	186.50 +	
10	1 PC BOOT LID LOCK <i>new</i>	162.60 +	
		2,314.30	
		Less 25%	578.58 1,735.76
Special Net			
11	1 SET REAR BUMPER STICKER <i>new</i>	195.00 ✓	
12	1 PC REAR FENDER STICKER <i>new</i>	195.00 ✓	
13	2 PCS "L" PLATE BRACKET <i>new</i>	70.00 ✓	
	<i>Rear End Panel Sealant, New</i>	460.00 ✓	460.00
Labour			
14	1 TO CHECK WIRING	50.00 <i>30</i>	
15	1 TO SPRAY UNDERSEAL	80.00 <i>60</i>	
16	1 TO REPLACE STICKER	100.00 <i>70.50</i>	
17	1 (REAR) TO SPRAY PAINTING	1,000.00 <i>600</i>	
18	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 <i>700</i>	
		2,230.00	2,230.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702

TEL: 62507388 FAX: 62962706
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 28/03/2019
TP Veh Reg No: SLU3460H

Estimate No: EST1900083
Date: 29 Mar 2019

Veh Reg No: SKE2541K
Make/Model: TOYOTA VIOS E
MANUAL

Chasis No: MR053HY9305288484
Reg. Date: 20/02/2012
Your Ref No: SLU3460H

Estimate Repair Cost to Vehicle No :SKE2541K

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 4,425.76
		Add GST @ 7%	309.80
		Total Amount Payable	S\$ 4,735.56

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED THIRTY FIVE AND CENTS FIFTY SIX ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
h/s 29/03/19.
05 days. Supplementary: 80
Total: 3210.67
h/s: 2550

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : LONPAC INSURANCE BHD
 100 BEACH ROAD
 #19-00 SHAW TOWERS
 SINGAPORE 189702

TEL: 62507388 FAX: 62962706
 ATTN: Motor Claim Department \ Motor Claim

Estimate No: EST1900083
Date: 30 Mar 2019

Veh Reg No: SKE2541K
Make/Model: TOYOTA VIOS E
 MANUAL

Chasis No: MR053HY9305288484
Reg. Date: 20/02/2012
Your Ref No: SLU3460H

Claim Type: Third Party
Accident Date: 28/03/2019
TP Veh Reg No: SLU3460H

Estimate Repair Cost to Vehicle No :SKE2541K

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Supplementary Parts to Repair		
1	Special Net "L" PLATE <i>Best</i>	80.00 ✓	
		80.00	80.00
	Total		S\$ 80.00
	GST Amount		S\$ 5.60
	Total Amount Payable		S\$ 85.60

For Kang Car Repairers Pte Ltd



 AUTHORISED SIGNATURE

80