

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0411/2019/ GW
Date : 01-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tay Boon Ching
Address : 11 Sembawang Crescent
#10-24
Singapore 757058
Telephone : HP +65 91080747
Type of Claim : Third Party Claims
Policy No. : 10757921
Vehicle No : **SLT 163 R**
Model Code : A4 SEDAN 1.4 TFSI S
Model / Year : 21-06-17
Engine No : CVN 038645
Chassis No : WAUZZZF47HA162545
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Mar-19
Place of Accident : Along Sembawang Alley

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 163 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00 ✓	
2	To dismantle and renew rhs front door and rhs rear door. Re-organise crash management components. Reinstall all parts removed. 500	\$ 1,800.00 1000	
3	To respray rhs front door, rhs rear door and door handle. 550	\$ 1,800.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,352.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 163 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR-RH ✓ DD	\$	2,152.00
2	FRONT OUTER DOOR SEAL-RH ✓ MEC	NEC \$	185.00
3	BONDING AGENT ✓ MEC	NEC \$	45.00
4	CLEANING SOLUTION ✓ MEC	NEC \$	65.00
5	APPLICATOR ✓ MEC	NEC \$	7.00
6	FRONT DOOR ATTACHMENT PARTS-RH ?	\$	488.00
7	FRONT DOOR CATCH-RH ✗	\$	96.00
8	FRONT DOOR TRIM PLATE-RH ✗	\$	80.00
9	FRONT DATA FOR PRESSURE TRYE-RH ✓ MEC	NEC \$	35.00
10	REAR DOOR-RH ✓ DD	\$	2,152.00
11	REAR OUTER DOOR SEAL-RH ✓ MEC	NEC \$	185.00
12	BONDING AGENT ✓ MEC	NEC \$	45.00
13	CLEANING SOLUTION ✓ MEC	NEC \$	65.00
14	APPLICATOR ✓ MEC	NEC \$	7.00
15	REAR DOOR SEALING STRIP-RH ?	\$	15.00
16	REAR DOOR ATTACHMENT PARTS-RH ?	\$	515.00
17	REAR DOOR CATCH-RH ✗	\$	109.00
18	SUNDRIES ?	\$	500.00
TOTAL SPARE PARTS CHARGES		:	\$ 6,746.00
TOTAL LABOUR CHARGES		:	\$ 4,352.00
GRAND TOTAL		:	\$ 11,098.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Steve (LKK) 8322 8813

Surveyed Date

: 8/4/19 1.20 pm

Authorised Date

: with Mr. M. H. C.

Excess Cost

: P/P

Liability

: Rg before spray

Remarks

4 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant