

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKR 6778 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
81	A/C RECEIVER DRIER	\$ 227.00	181.60
82	A/C COMPRESSOR HOSE	\$ 152.00	121.20
83	A/C HOSE AND TUBE ASSEMBLY	\$ 476.00	380.40
84	A/C O-SEAL RING	\$ 8.00	X
85	A/C LINE O-RING	\$ 10.00	X
86	FRONT FENDER PROTECTION FILM-LH	\$ 21.00	X
87	FRONT FENDER TOP LEDGE COVER-LH	\$ 28.00	X
88	FRONT FENDER LEDGE COVER-LH	\$ 56.00	X
89	FRONT WIPER CROWL TRIM	\$ 89.00	X
90	FRONT SECTIONAL PART-PILLAR A/B-LH	\$ 2,443.00	1954.40
91	FRONT A-PILLAR-LH OUTER	\$ 976.00	780.80
92	WEB PLATE FOR SIDE MEMBER-LH	\$ 134.00	107.20
93	REINFORCEMENT FOR LOWER SIDE MEMBER-LH	\$ 329.00	262.80
94	FRONT SENSOR-INNER/ OUTER	\$ 231.00	184.80
95	FROTNT BUMPER WIRING SET	\$ 470.00	376
96	FANFARE- HIGH TONE LH	\$ 37.00	29.20
97	FANFARE MOUNT BRACKET-LH	\$ 26.00	20.80
98	FRONT UNDERTRAY	\$ 520.00	416
99	REAR UNDERTRAY	\$ 358.00	286
100	FRONT UNDERBODY TRIM-LH	\$ 37.00	29.44
SUB FRONT SPARE PARTS		\$ 6,628.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

34322