

Premium Automobiles

①

55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 1 of 3 SKR 6778 A A4 Sedan 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To remove and reinstall dashboard inner frames, wire harness and all attachments. (S/N)	\$ 1,800.00	/ ✓
2	To cut out and weld lhs inner wheel house, floor pan, fire wall lower section and reinforcements.	\$ 5,500.00	1500 ✓
3	To reseal fire wall and floor pan section, respray inner wheel house, floor pans and inner panels.	\$ 2,600.00	1650 ✓
④	To renew gear box assy and carry out adaptation. (S/N)	\$ 1,200.00	960 ✓
TOTAL LABOUR CHARGE		\$ 11,100.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Caro Corp.
 17/4/19.

Premium Automobiles

②

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 2 of 3 SKR 6778 A A4 Sedan 2.0 TFSI
--	---	---

Quantity	Description	Unit Price	Amount
Parts			
1	FRONT FENDER END PLATE-LH / MCL	\$ 32.00	25.04
2	DRAIN HOSE FOR HEADLIGHT WASHER SYSTEM-LH / M's	\$ 29.00	25.36
3	HEADLIGHT COMPESATING ELEMENT-LH	2 \$ 67.00	53.60
4	HEADLIGHT RETAINER PLATE SPACER-LH / MCL	2 \$ 67.00	53.60
5	HEADLIGHT SCREW ASSEMBLY SPACE-LH	2 \$ 74.00	59.20
6	FRONT FENDER TOP COVER-LH / M's	\$ 28.00	22.24
7	FRONT FENDER LEDGE COVER-LH	\$ 52.00	41.52
8	SOCKET - JACK	\$ 5.00	32.40
9	HEXAGON HEAD BOLT	4 \$ 46.00	40.32
10	HEXAGON NUT	4 \$ 2.00	1.60
11	POP RIVET	4 \$ 3.00	2.88
12	HEXAGON BOLT	8 \$ 65.00	49.92
13	RETAINER FOR BRAKE HOSE-LH	\$ 25.00	19.40
14	JOINTED SHAFT-LH	\$ 34.00	26.88
15	REAR VIEW MIRROR / M's	\$ 984.00	786.80
16	FRONT DOOR TRIM-LH / CRA	\$ 1,667.00	1502.40
17	ENGINE MOUNTING-LH / CRA BT	\$ 377.00	301.60
18	ENGINE MOUNTING BRACKET-LH / CRA	\$ 149.00	119.20
19	ENGINE MOUNTING HOLDER SUPPORT / MCL	\$ 63.00	49.76
20	ENGINE AND GEARBOX FIXING PARTS / MCL	\$ 128.00	102.40
SUB-TOTAL SPARE PARTS		\$ 3,897.00	

For Premium Automobiles Pte Ltd



Authorized Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

3

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 3 of 3 SKR 6778 A A4 Sedan 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
Parts				
21	ENGINE OIL SUMP-LOWER PART <i>✓ 4 Mbc.</i>	\$ 311.00	248.40	
22	ENGINE OIL SUMP-UPPER PART <i>✓ 4 Mbc.</i>	\$ 507.00	405.60	
23	HEXAGON SOCKET HEADBOLT <i>x NN</i>	\$ 16.00	x	
24	ENGINE OIL LEVEL SENSOR SEAL RING <i>✓ 2</i>	\$ 21.00	17.60	
25	SILICONE SEALANT <i>✓</i>	\$ 55.00	46.48	
26	SHAFT OIL SEAL <i>✓</i>	\$ 20.00	16.40	
27	HIGH LUBRICITY ENGINE OIL 5.0 LTR <i>✓</i>	\$ 180.00	215.60	
28	CROSS MEMBER FOR WHEEL HOUSING LINER <i>✓</i>	\$ 62.00	49.28	
29	WHEEL HOUSING LINER LENGTH EXTENSION-LH <i>✓ M's</i>	\$ 277.00	221.60	
30	FRONT FENDER REINFORCEMENT-LH <i>✓ 4015</i>	\$ 127.00	101.60	
31	FRONT FENDER LOWER PLATE-LH <i>✓ 4015</i>	\$ 277.00	221.60	
32	7 SPEED DUAL CLUTCH GEARBOX <i>x NN</i>	27,830.00	x	
33	DUAL CLUTCH TRANSMISSION FLUID 1.0 LTR <i>✓ 4015</i>	\$ 122.00	97.60	
34	FRONT A-PILLAR OUTER-LH <i>x Repeat</i>	\$ 976.00	x	
35	STEERING COLUMN CRUISE CONTROL <i>Act</i>	\$ 872.00	752	
36	STEERING GEAR <i>BT</i>	\$ 5,939.00	4751.20	
37	FRONT TIE ROD END-LH <i>BT</i>	\$ 163.00	144	
38	FRONT SPEED SENSOR <i>Act</i>	\$ 90.00	71.84	
39	FRONT RIM -LH (AFTER MARKET RIM) <i>4015</i>	TBC	500	
40	FRONT TYRE-LH (245/40 R18) <i>4015</i>	TBC	272	
GRAND TOTAL		\$ 52,842.00		

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

5

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 27-May-19 CHANG 1 of 1 SKR 6778 A A4 Sedan 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	FRONT REINFORCEMENT BEAM	\$ 733.00	bt / 586
GRAND TOTAL		\$ 733.00	

For Premium Automobiles Pte Ltd

by Taufik.
27/5/19.



Authorized Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0407/2019/DY/GW 12-Apr-19 George 1 of 1 SKR 6778 A A4 Sedan 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	Sealing flange / <i>M.C.</i>	\$ 260.00	\$	214.00
GRAND TOTAL		\$ 260.00	\$	214.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. PA/OD/0407/2019/DY/GW Date 1-Jun-19 Service Advisor jb Pages 2 of 3 Regn No SKR 6778 A Model No A4 Sedan 2.0 TFSI	
Quantity	Description	Unit Price	Amount
Parts			
1	Steering under dash cover - <i>MLC</i>	\$ 230.00	\$ 184.00
2	LHS B pillar lower cover - <i>SCR</i>	\$ 140.00	\$ 112.00
3	LHS sill panel inner reinforcement - <i>GST</i>	\$ 457.00	\$ 365.60
4	LHS A pillare lower inner reinforcement	\$ 203.50	\$ 162.80
5	LHS curtain air bag connector - <i>MLC</i>	\$ 173.50	\$ 138.80
6	LHS front door arm rest trim - <i>cut</i>	\$ 485.00	\$ 388.00
7	LHS front wheel spoiler - <i>Mi's</i>	\$ 96.70	\$ 77.36
8	Dashboard air vent - centre - <i>MLC</i>	\$ 153.00	\$ 122.40
9	LHS rea door hinge - lower - <i>RT</i>	\$ 41.30	\$ 33.04
10	Floorpan rubber plug x 4 - <i>MLC</i>	\$ 76.80	\$ 61.49
11			
		\$ 2,056.80	\$ 1,645.49

6/6 123020

123018

6/6 123019