

COMFORTDELGRO ENGINEERING PTE LTD*
REPAIR ESTIMATE*

China-FZ
 L. Sam

VEHICLE NO : SHC 7562Z

DATE 1/4/2019 11:02

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Reinforcement			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs			\$ 22.00
	Rear Bumper Bracket		\$ 35.60	\$ 71.20
	Rear Bumper Sponge			\$ 103.50
	Rear Bumper Under Cover			\$ 228.00
	SUB TOTAL			\$ 1,566.70
	LESS 20%			\$ 313.34
	DISCOUNTED TOTAL			\$ 1,253.36
	Rear Bumper Reverse Sensor			\$ 135.70
				\$ 135.70
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 810.00
	ESTIMATE TOTAL			\$ 2,199.06

Icek
 P
 P
 /NEC
 P
 P
 /SCR

Nett XSVL

200
 200
 XNW
 30

NAZ LKK
 1/4/19 1620
 LIS
 2 DAYS
 CHACK ITEMS PHOTOS
 AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

Date: <u>30/3/11</u> Time Received: <u>1700</u>		3. Vehicle Type: <input type="checkbox"/> Private <input type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)		4. Type of Towing: <input type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up	
<input type="checkbox"/> New Name of Customer: <u>Low Sin Juan</u> Contact No.: <u>88A 7562 Z</u> Vehicle No.: <u>97311533</u> Make / Model / Colour: Email:		<input type="checkbox"/> SPARK Kakis 5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery		6. Parts Replaced/Remarks:	

7. Location: <u>Hougang S110</u>		8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input checked="" type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi			
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input checked="" type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others:					

10. Odometer Reading: <u>370356</u>		11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested		 #: Cracked X: Dented /: Scatched O: Missing Signature of Customer: <u>[Signature]</u>				
Fuel Level: <table border="1"><tr><td>F</td><td>1/4</td><td>1/2</td><td>3/4</td><td>E</td></tr></table>		F	1/4			1/2	3/4	E
F	1/4	1/2	3/4	E				

Job Attended		12. Tow Truck / Recovery Van: <input type="checkbox"/> VRS <input type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> TZ <input checked="" type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS TOWING	
Name of Driver: <u>Tan Ah Yee</u>		Vehicle No.: <u>CU41409</u>	
Time Dispatch: <u>1705</u>		Time of Arrival: <u>1730</u>	
Time Completed: <u>1805</u>			

Cash Invoice Details (if applicable)	
13. Cash Invoice No.:	

Customer Acknowledgement		
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupon cash cards, spectacles, pen, etc.		
b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.		
c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™		
Date: <u>30/3/11</u>	Time: _____	Signature of Customer: <u>[Signature]</u>

14. WORKSHOP	
Name of Attending Staff/Guard: _____	Date & Time of Arrival: _____
Signature of Attending Staff/Guard: _____	