

SHA 5723P

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,800.00 900/-
	Spray Painting Charge			\$ 1,250.00 900/-
	Wiring Charge			\$ 50.00 22
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 22
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Transfer of Door	\$	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00 } 150/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 5,160.00
	ESTIMATE TOTAL			\$ 18,913.52
<p>02/04/2019 @ 1008hr KKA Antur 2/3mm 8 days yan LKK Auto</p>				
				
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: auto;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				