AND THE R		12 08/11/1900	5819/US	d3 112	notera.	
1.11/2/01	marcus -	ASSIGNME				
Umin.	Gabriel We	e	T	Daid1	14/19 0 1·4	Spm
Estimated Co			Hill to:			1
		LEVATINUTMYTC				
To Inspect V	chiefe He	SKQ43		Insmed	SHB 4262D	- 20
at Werkshop		Euro Success		Tel (1828 9277	
of	1 Icalci 2	whit Ave 6 =	牛 02-03			
Policy No.			Claim No:			
Som braned			Brooss.			
Make of Veh (Client's Recor					2/03/2019	•
$\mathrm{CA} \neq \mathrm{REV}$	/ REP. / REV 24 H	ts		3/1/	aulg Endorsement	
Date/Fine:_		Person Contacted:	Ah H		ихоит.	
Date/Time	Action/Instruction (() Estimate				
	SKQ 4367-					
	SUR 106-	D- NS/INC 18	11/10/201	Klaha	DOA: 8/61	12018
	211D ET 200	7)- 1-0/1/46/10	010-17	Nigeria	1704. 0/01	200
	-					
						.00

260

Nivitha (LKK Auto)

From:

Motor Claim - III < motorclaim@iii.com.sg>

Sent:

Tuesday, 2 April 2019 1:45 PM

To:

Ruby Ong; 'sur@lkkauto.com'; Admin-D (LKKAuto)

Cc:

Sherini Pillai; Zuhaidah Samsuri

Subject:

RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKQ 43G [OUR REF.

TCL.MH.RO.50200.19.ESS]

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKQ43G and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards, Gabriel Wee



64 Cecil Street; #05 - IOB Building Singapore 049711

Tel: 6347 6100, Ext – 248

From: Ruby Ong [mailto:ruby@htapartners.com.sg]

Sent: 02 April, 2019 12:06 PM

To: Motor Claim - III < motorclaim@iii.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SKQ 43G [OUR REF. TCL.MH.RO.50200.19.ESS]

Importance: High

Your ref:

SHB 4262D

WITHOUT PREJUDICE

Our ref:

TCL.MH.ro.50200.19.ess

2 April 2019

India International Insurance Pte Ltd

By Email Only

Motor Claims Department 64 Cecil Street #04-00 IOB Building

Singapore 049711

VERY URGENT

Dear Sirs,

CLAIMANT: LEE TEE CHUANG

ACCIDENT INVOLVING SKQ 43G & SHB 4262D ALONG CLEMENCEAU AVENUE NORTH ON 24 MARCH 2019 @ 2250HRS

We are instructed by Lee Tee Chuang to notify you of a road traffic accident on 24 March 2019 at about 2250 hrs along Clemenceau Avenue North involving our client's vehicle registration number <u>SKQ 436</u> and vehicle registration number SHB 4262D driven by your insured/insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, our client proposes to appoint <u>LKK Auto Consultants Pte Ltd</u> as the single joint expert to carry out the prerepair survey for <u>SKQ 43G</u>.

Please make the necessary arrangements with the contact person. The details are as follows:

Venue

Euro Success Services Pte Ltd

1 Kaki Bukit Avenue 6 #02-03 Autobay Singapore 417883

Contact Person:

Ah Huat (Tel. 9828 9277 / 6742 6231)

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416

Tel: 6533 0212 ext 278 Fax: 6338 3536 / 6533 0313 www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! New 5 Years Renewal Coe Toyota Estima 2.4A



2.88%p.a Low Interest@GV Finance.2 Years Warranty. \$4800 Down Monthly From \$988 GV Credit Pte Ltd StarAd



Browse by Category

Post an Ad

Advertiser Login

Y

Ways of Selling

« Back (1 2 3) Next =

Sort by Date Posted

✓ 20 results/page ✓

57 vehicles

estima

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Make estima

Any

Arry

2009

Anv

Any Available

2.88% Per Annum Lowest Interest At \$988 Monthly For Toyota Estima, Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox

Toyota Estima 2.4A Aeras S (COE till 02/2024)

With STA Evaluation Graded. Add Ons Available.

\$55,800

\$11,490 /yr

10-Feb-2009

2,362 cc

MPV

Advanced Search Submit (

Available

SPEEDING MADE

2.88%p.a Low Interest@GV Finance.2 Years Warranty. \$4800 Down Monthly From \$988

GV Credit Pte Ltd

Posted: 03-Apr-2019

\$7,270 /yr

Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used

2.88% P.A Lowest Interest At \$988 Monthly For Toyota Estima. \$0 Admin Fees For All GV Purchase. 2 Years Warranty For Engine And Gearbox With

27-Mar-2009

2,362 cc

Available

Toyota Estima 2.4A X (New 10-yr COE)

\$72,800

PREMIUM AD

STA Evaluation Graded. Add Ons Available. 2.88%p.a Low Interest@GV Finance.2 Years Warranty. \$4800 Down Monthly From \$988

Posted: 03-Apr-2019

Toyota

Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used

Toyota Estima 2.4A Aeras (COE till 01/2024)

\$50,899

\$10,680 /yr

08-Jan-2009

2,362 cc

109,000 km

Available

PREMIUM ADD

2 Owner Low Mileage. All Black Interior Rare In Market. 2015 Facelift Like Driving A 2015 Estima. New Leather Seats. New Paintwork, Low Mileage. Engine Oil/Mounting/Steering Rack/Balance Shaft/Bearing...

Posted: 03-Apr-2019

Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Toyota



Toyota Estima 2.4A X (New

\$68,000

\$6,790 /yr

17-Jul-2009

2,362 cc

127,898 km

Available

10-yr COE) Major Wear And Tear Parts Restored With Proven Invoice. Very Well Maintain By Careful Owner. Genuine Mileage At 127898. Well Known For Long Distance Stability And Spacious Interior. Good Efficiency Fu..

Posted: 03-Apr-2019

Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Estima 2.4A Aeras Premium Moonroof (New 10yr COE)

\$69,888

\$6,980 /yr

15-Jun-2009

2.362 cc

112,000 km

MPV

Available

Graded B by

Providing Good Service, Free 6 Month Warranty, Loans Available, Having Our Own Workshop, 100% Accident Free, Well Maintained, Bank Loan And In House Loan Available. Low Monthly Installment. Trade In W...

Tags: 2009 Toyota Estima, 2009 toyota estima, Toyota Estima, toyota estima, Toyota, Estima, estima, Used Posted: 03-Apr-2019

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	7963D	
Vehicle No.:	SKQ43G	
Vehicle to be Exported:	No	
Intended Deregistration Date:	05 Apr 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	ESTIMA 2.4G A	
Primary Colour:	White	
Manufacturing Year:	2008	
Engine No.:	2AZF203458	
Chassis No.:	ACR500079666	
Maximum Power Output:	125.0 kW (167 bhp)	
Open Market Value:	\$35,691.00	
Original Registration Date:	22 Jan 2009	
First Registration Date:	22 Jan 2009	
Transfer Count:	2	
Actual ARF Paid: Intended PARF Rebate Details	\$35,691.00	
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:	<u>92</u> 00	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	21 Jan 2029	
COE Category:	B - Car (1601cc & above)	
COE Period(Years):	10	
PQP Paid:	\$31,335.00	
COE Rebate Amount:	\$30,686.00	
Total Rebate Amount:	\$30,686.00	

The information contained herein is correct as at 03 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Pièase report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCI	DENT	STAT	100	ENT
AUU	DEN	OHA!	1.0	- 1

26/03/2019 09:53 Date Of Report 24/03/2019 22:50 Date Of Accident

CLEMENCEAU AVE NORTH Exact Location Of Accident

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKQ43G

Insured/Policyholder

LIM TEE CHUANG Name Of Registered Owner

NRIC No S7127963D NOEMAIL Email Address

(LOCAL) +65-91217272 Mobile Phone No OTHERS-NOPHONE Alternative Phone No.

Vehicle Particulars

TOYOTA Manufacturer

ESTIMA 2.4G A

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

NO Fleet Policy

Policy Number

5107132922

Cover Note Number

Driver

SHAWN LIM TECK JOO Name of Driver

S98179111 NRIC No 27/05/1998 Date Of Birth INDOOR Occupation Date Of Driving Pass 12/03/2019

0 YEAR AND 0 MONTH Driving Experience

MALE Gender

Mobile Number +65-93874143

Fax Number

Contact Number

SLTJSHAWN@GMAIL.COM EMail Address

Address

BLK 107 BUKIT PURMEI ROAD

#09-25

Postcode

090107

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

CHILDREN

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance

NO

Number of Passengers (Including Driver)

4

Passenger 1

NAME:

: LEE LAY YENG

GENDER:

: FEMALE

Passenger 2

NAME:

: AMOS KMEH JAN YU

GENDER:

MALE

Passenger 3

NAME:

: RYKIEL LOW GEK TING

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHB4262D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category Name of Driver

NRIC/Passport Number

IXAT

Contact Number
Address *
Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

MPORTANT NOTICE

- # Please report correctly the details of the accident to speed up the claims process.
- Inis Form must be completed by the Policyholder and/or the Authorised Driver.
- In formation provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Arry false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 8y the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- S. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature 26/03 1020Am (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

Uh

NRIC/FIN No.:


Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE 6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 – 17:00
UEN: \$665500206 / GST Reg. No : M400017718

MPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

		ADDEN	DUM	
(4	PARTICULARS OF PER	SONMAKINGTHEAMENDME		
	Original Report No :	mmov19039276	Vehicle Registration No:	SKQ436
		11m Tee Churing	NRIC/FIN/Passport No :	
		nicle Owner) (*) Please delete as		27
	Address :			Singapore()
	Contact (Tel)		Mobile No.: 9/2/7	272
	Email Address :			
	Date of Accident :	24/03/19	Time of Accident :	22:50
	Place of Accident	Clemenceau Ave N	lorth	
	Insurance Company:	NITUC		
	make the following an * I wint lack at the turn as is I Realised 7	back to the fi sad and I Real a single white hat the distance we ters instand.	set that I'm able time. Also 11 shift 80-100 meters	technician and to make a 1944 Also it was about
	10/04/20/20 management	ر / Driver's	うん / Driver's Signature	TO SEE THE SECTION OF THE COST OF THE PROPERTY



EURO SUCCESS SERV PTE. LTD Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: SKQ43G

Model: TOYOTA ESTIMA

Not Arlloral
LIAL

1/5 = 3800/2

Take the Atterny.

Vehicle No. 3KQ43G	Woden 10	, 011.01.20,111.11.	lafel	She Him
QTY	List Items	25	Price \$	
1	FRONT R/H FENDER	60	Ty 684.80 -	
1	FRONT R/H FENDER INNER SHIELI)	TOM 192.40.	
1	FRONT R/H HEAD LAMP		Cre 1104.00	
1	FRONT BUMPER	165.10 Torr	Deepout 1058.60	
2	FRONT BUMPER L-R RETAINER @	65.90	0/554 131.80	26
1	FRONT BUMPER LOWER KIT		Cu7 656.60	_
1	FRONT BUMPER REFORMENT		A 7 499.30	X
1	FRONT BUMPER BEAM		△ [↑] 307.60	(.)
1	FRONT BUMPER R/H SPORT LIGH	Т	1 298.10	α
1	FRONT R/H LOWER ARM		مر 699.60	×
1	FRONT R/H SHOCK ABSOBER		17 474.20	×
1	FRONT R/H KNUCKLE ARM		A 4 608.40	×
1	FRONT R/H WHEEL BEARING		My L 396.30	
1	FRONT R/H DOOR MIRROR		858.60	X
			7	- 0
		TOTAL	\$7,970.30	3693.90
		LESS 25%	\$1,992.58	252
		TOTAL	\$5,977.72	-2770.42
				2
	SPECIAL NETT ITEMS		1 /	1100
1	FRONT R/H SPORT RIM	1	Berf (D) 1000.00	
1	FRONT BUMPER CLIP		ru 45.00	
1	FRONT FENDER SHIELD CLIP		nn 45.00	V
1	FRONT PDC SENSOR		A 280.00	^
			61 370 00	
			\$1,370.00	
	LABOUR CHARGES			23
	TO CHECK WHEEL ALIGNMENT		100	60
	TO CHECK AND DEELY EDONT LIN	DERCARRIAGE	250.00	Mark Today Control

DADOON CHANGES	/ ^
TO CHECK WHEEL ALIGNMENT	100 60
TO CHECK AND REFIX FRONT UNDERCARRIAGE	250.00 /00
TO RESPRAY UNDERCOATING	200.00 30
TO CHECK ELECTRICAL WIRING	80.00 20
TO RESPRAY PAINTING AND ETC	900.00 750
TO PANEL BEATING, REMOVE AND REPLACING	1000.00 #50
[12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [12] : [

ABOVE PARTS

\$2,530.00 475042

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$9,877.72

Acknowledged by Repairer

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/III19005819/USD3N2

Date:

11/04/2019

REFERENCE

Handling

India International Insurance Pte Ltd

Policy No:

Insurer: Claimant

Claimant Vehicle No :

SKQ43G

Insured Vehicle No:

SHB4262D

Date of Loss:

24/03/2019

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKQ43G

Make & Model:

TOYOTA ESTIMA, 2.4 (A) 22/01/2009 (Man. Year: 2008) Engine No: Chassis No: Odometer: 2AZF203458 ACR500079666

153953 km

Reg. Date: Colour:

White 2362 cc

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Handbrake (Serviceable):

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size:

215/55R17

Rear Tyre Size:

215/55R17

Front Left Side: Front Right Side: Bridgestone 5 mm Bridgestone 5 mm Rear Left Side: Rear Right Side: Bridgestone 5 mm Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items		Repairer's 7,347.72 0.00	Adjuster's 3,340.42 0.00	4,007.30 0.00	Diff % 54.54
Labour Paintwork Labour Towing		2,530.00 0.00 0.00	1,410.00 0.00 0.00	1,120.00 0.00 0.00	44.27
3	Calculated Gross Total (S\$) proved Total (Overridden) (S\$)	9,877.72	4,750.42 3,800.00	5,127.30	51.91
Ap	Nett Amount (S\$)	9,877.72	3,800.00	6,077.72	61.53

INSPECTION

Date of Assignment:

02/04/2019

Date Inspected:

03/04/2019 Inspected At:

Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03

AUTOBAY Singapore 417883

Estimated Period of Repair:

3.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 11 Apr 2019)

Parts:

M1-MPV

TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKQ43G)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recom	mended	Parts
Recon	mienaea	raits

	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT R/H FENDER	Bent	684.80 FL	*613.60 FL
1		*FRONT R/H FENDER INNER SHIELD	Torn	192.40 FL	*192.40 FL
1		*FRONT R/H HEAD LAMP	Cracked	1,104.00 FL	*1,104.00 FL
1		*FRONT BUMPER	Torn/Deep Cut	1,058.60 FL	*665.10 FL
1		*FRONT BUMPER L-R RETAINER	O/s Bent	131.80 FL	*65.90 FL
1		*FRONT BUMPER LOWER KIT	Cut	656.60 FL	*656.60 FL
1		*FRONT BUMPER REFORMENT	Not Necessary	499.30 FL	*- FL
1		*FRONT BUMPER BEAM	Not Necessary	307.60 FL	*-FL
1		*FRONT BUMPER R/H SPORT LIGHT	Not Necessary	298.10 FL	*-FL
1		*FRONT R/H LOWER ARM	Not Necessary	699.60 FL	*-FL
1		*FRONT R/H SHOCK ABSORBER	Not Necessary	474.20 FL	*- FL
1		*FRONT R/H KNUCKLE ARM	Not Necessary	608.40 FL	*-FL
1		*FRONT R/H WHEEL BEARING	Damaged	396.30 FL	*396.30 FL
1		*FRONT R/H DOOR MIRROR	Repair	858.60 FL	*-FL
1		*FRONT R/H SPORT RIM	Bent/Dented	1,000.00 FS	*480.00 FS
1		*FRONT BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
1		*FRONT FENDER SHIELD CLIP	Necessary	45.00 FS	*45.00 FS
1		*FRONT PDC SENSOR	Not Necessary	280.00 FS	*-FS
nchise	part. S=SpcN	lett. L=ListItemDisc.	-		
			Sub Total (S\$)	9,340.30	4,263.90
		- List Item Discount on L Ite	ms 25.00/25.00% (S\$)	1,992.58	923.48
			Total Parts (S\$)	7,347.72	3,340.42
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*FRONT R/H FENDER INNER SHIELD *FRONT R/H HEAD LAMP *FRONT BUMPER *FRONT BUMPER L-R RETAINER *FRONT BUMPER LOWER KIT *FRONT BUMPER REFORMENT *FRONT BUMPER BEAM *FRONT BUMPER R/H SPORT LIGHT *FRONT R/H LOWER ARM *FRONT R/H SHOCK ABSORBER *FRONT R/H KNUCKLE ARM *FRONT R/H WHEEL BEARING *FRONT R/H WHEEL BEARING *FRONT R/H DOOR MIRROR *FRONT R/H SPORT RIM *FRONT BUMPER CLIP *FRONT BUMPER CLIP *FRONT FENDER SHIELD CLIP *FRONT PDC SENSOR	*FRONT R/H FENDER INNER SHIELD Torn *FRONT R/H HEAD LAMP Cracked *FRONT BUMPER Torn/Deep Cut *FRONT BUMPER L-R RETAINER O/s Bent *FRONT BUMPER LOWER KIT Cut *FRONT BUMPER REFORMENT Not Necessary *FRONT BUMPER BEAM Not Necessary *FRONT BUMPER R/H SPORT LIGHT Not Necessary *FRONT R/H LOWER ARM Not Necessary *FRONT R/H SHOCK ABSORBER Not Necessary *FRONT R/H KNUCKLE ARM Not Necessary *FRONT R/H WHEEL BEARING Damaged *FRONT R/H WHEEL BEARING Damaged *FRONT R/H SPORT RIM Bent/Dented *FRONT R/H SPORT RIM Bent/Dented *FRONT BUMPER CLIP Necessary *FRONT PDC SENSOR Not Necessary *FRONT DC SENSOR Not Necessary *FRONT L=ListItemDisc. *Sub Total (S\$)	*FRONT R/H FENDER INNER SHIELD Torn 192.40 FL *FRONT R/H HEAD LAMP Cracked 1,104.00 FL *FRONT BUMPER Torn/Deep Cut 1,058.60 FL *FRONT BUMPER L-R RETAINER O/s Bent 131.80 FL *FRONT BUMPER LOWER KIT Cut 656.60 FL *FRONT BUMPER REFORMENT Not Necessary 499.30 FL *FRONT BUMPER BEAM Not Necessary 307.60 FL *FRONT BUMPER R/H SPORT LIGHT Not Necessary 298.10 FL *FRONT R/H LOWER ARM Not Necessary 699.60 FL *FRONT R/H SHOCK ABSORBER Not Necessary 474.20 FL *FRONT R/H KNUCKLE ARM Not Necessary 608.40 FL *FRONT R/H WHEEL BEARING Damaged 396.30 FL *FRONT R/H WHEEL BEARING Damaged 396.30 FL *FRONT R/H SPORT RIM Bent/Dented 1,000.00 FS *FRONT BUMPER CLIP Necessary 45.00 FS *FRONT PDC SENSOR Not Necessary 45.00 FS *FRONT PDC SENSOR Not Necessary 280.00 FS

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Reco	mm	and	pd	2	DOLLE
Reco	111111	enu	eu	La	Jour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO CHECK WHEEL ALIGNMENT	New	100.00	60.00
2	TO CHECK AND REFIX FRONT UNDERCARRIAGE	New	250.00	100.00
3	TO RESPRAY UNDERCOATING	New	200.00	30.00
4	TO CHECK ELECTRICAL WIRING	New	80.00	20.00
5	TO RESPRAY PAINTING AND ETC	New	900.00	750.00
6	TO PANEL BEATING, REMOVE AND REPLACING ABOVE PARTS	New	1,000.00	450.00
	Gross Labou	r Cost (S\$)	2,530.00	1,410.00

< END OF ESTIMATES >