

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 10 Apr 2019

Preliminary Advice

Insured Vehicle No	: SJW9434H		
TP Vehicle No	: SGD6895R	Accident Date	: 19/03/2019
Make	: VOLKSWAGEN GOLF	Assignment Date	: 03/04/2019
Date of Inspection	: 08/04/2019	Est. Duration of Repair	: 2/DAYS
Inspection At	: VAG SINGAPORE PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ..Rear..... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,340.00
Revised Amount	:S\$	1,620.00
Check Items (Estimated)	:S\$	75.00
Total	:S\$	1,695.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.