zoonood ASS, REELBY		REFE (S/FCL)	9005915/K	S d3 Special Instructions
ะกับพูงเลงา	Konnuth	ASSIGN	MENT (Office)	
From (Person	Sitheren	THE CONTRACT OF THE PARTY OF TH	THE RESERVE AND THE PARTY OF TH	Date/Time: 9.240003/4/10
Estimated Co.	at:		Bill to:	
on (iii) w	S/TP RES/OD R	ES / EVA / INV / MY		
To Inspect Vo	chiele No:	EW669	55 R	Insured: SHC 7223S
at Workshop		Ah Him M	lotor	Tel. 64563637
of	]:	16 Sin Miney	Drive #	05-12
Policy No:		9		DIGCO DEVIMENT
Sum Insured:			Excess	
Make of Veh (Client's Record				D.O.A 21/03/2019
CA / REV	/ REP. / REV 24	HRS		H.O.D. Endograment
			d Mei fi	Vehicle IN (1011)
Date/Fime	EW 66558			•
	SH( 72239	-CS/FC1/900	1961/ bsd :	Bn2 D-04-26/01/2019
12/04/19	@ 16:11	o.m. revise	d pn to	. Sthera via enail.
10/	7 61 Lng &	32 Red	- 46%. 7	Confirm

Site Inap (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Add Fee:

Report Format:

Lump Sum / I.B.J: (\$ 850/- 45

50

10

210

S+RS\_\_SI

) Photos

) Others

TOTAL

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D19002001MFSH

Date: 12 April 2019

Our Ref: CS/FCI19005915/Ksd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


# INITIAL INSPECTION REPORT OF VEHICLE NO. <u>EW 6655R</u>.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/04/2019 at the premises of M/s Ah Lim Motor Company and have the following to report:-

Workshop Estimate Amount	: S\$	1,574.32	
Revised Estimate Amount	: S\$	1,560.80	
"Check" Items Amount	: S\$		
Market Value	: <u>S</u> \$		-
LTA Reimbursement Value	: S\$		
Nett Value	: S\$	6 7 6	

## Description of Damage:


The vehicle sustained damages at the o/s rear portion.



## Comments/ Present Status:

Damages Consistent. Repair days: 2 Days

Yours faithfully, Kenneth Kong Automotive Assessor



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

#### MOTOR SURVEY ASSIGNMENT

Date

22-03-2019

Our Ref No. D19002001MFSH

**Accident Date** 

21-03-2019

Claim Type. Third Party

Insured Vehicle

SHC7223S

Third Party Vehicle. EW6655R

Survey Location

176 SIN MING DRIVE #05-12 SIN MING AUTOCARE

Contact Person.

MEILI TAN

Contact No.

64563637/0

Fax No. 64563686

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

AH LIM MOTOR

COMPANY

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SITHARA

#### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection. This is a computer generated letter, no signature required.

## Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Friday, 12 April 2019 4:11 PM

To:

'Sithara'; 'CWS Motor Claims'

Cc:

assignments; SUR; Admin-D (LKKAuto)

Subject:

RE: SURVEY ASSESSMENT - D19002001MFSH/1

Attachments:

EW 6655R - Preli Advise.pdf

Dear Sithara,

Enclosed preliminary revised of vehicle EW 6655R.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Wednesday, 3 April 2019 10:09 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19002001MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <a href="mailto:assignments@lkkauto.com">assignments@lkkauto.com</a> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Wednesday, 3 April 2019 9:24 AM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19002001MFSH/1

Dear Sir/Mdm,
We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

This email has been checked for viruses by AVG antivirus software.
www.avg.com

# > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	1072Z
Vehicle No.:	EW6655R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	R18A13030575
Chassis No.:	JHMFD16308S214123
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$21,335.00
Original Registration Date:	28 Feb 2008
First Registration Date:	28 Feb 2008
Transfer Count:	1
Actual ARF Paid:	\$23,469.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,289.00
COE Rebate Amount:	\$19,764.00
Total Rebate Amount:	\$19,764.00
Message Please note that the 5-year COE for this vehicle cannot	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Mar 2019

ОК



## CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00002942-01 (Comprehensive - Classic Plan)

Car plate number: EW6655R

Your name (As the policyholder): Poon Hiu Chuin

Coverage start date: 28/02/2019 Coverage end date: 27/02/2020

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

### Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company:no

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 25/02/2019

Shrie


Abhishek Bhatia

Chief Executive Officer FWD Singapore Pte Ltd

Elen. Clare Dept - 682088889

Please immediately inform us at +65-6820-8888 or email us at contact.sg@fwd.com if any details in this Certificate of Insurance need to be changed.

Mary. Auster + Report Services.



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S6841072Z





POON HIU CHUIN

晓 川

CHINESE Date of birth

Sex M

S5841072Z

5206384

22-10-1968 Country/Place of birth

SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive 09 Apr 1987 of the driver; and other motor vehicles =< 2500kg o

NP 428A



NRIC No. S6841072Z



Date of innue 30-07-2013

10 TAO CHING ROAD #16-23 SINGAPORE 618725

NRIC No: \$6841072Z

Date: 11/03/2018

# AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721 TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COP

M/S:

POON HIU CHUIN

10 TAO CHING ROAD

#16-23

SINGAPORE 618725

ATTN:

Your Ref No:

EW6655R

Claim Type: Accident Date:

Third Party 21/03/2019

TP Veh Reg No:

SHC7223S

Estimate No:

MCS1900061

Date:

25 Mar 2019

Policy No:

PNPV2018-00002942-01

Veh Reg No:

EW6655R

Make/Model:

HONDA CIVIC 1.8L

My Notherse 11 Ly 81230/ Runy Athe Pary

Estimate Repair Cost to Vehicle No :EW6655R

	Description	Quantity	List Price	Amount
	1000 A		<u>SS</u>	<u>SS</u>
	SPARE PARTS		10.	
1	REAR BUMPER	1 PC	CP1 730,00	_
2	REAR BUMPER CLIP	15 PC	N 58.50	_
3	REAR BUMPER SIDE RETAINER RH	1 PC	h 16.90	X
			805.40	
		Less 20%	161.08	644.32
	LABOUR			202
4	TO CHECK WIRING AND REINSTALL REVERSE SENSOR	1 PC	30.00	
5	TO DISMANTLE THE DAMAGED REAR BUMPER. TO REPLACE REAR BUMPER & TO KNOCK & REPAIR REAR AFFECTED AREAS	1 PC	400.00	2201
6	TO SPRAY REAR BUMPER & REAR FENDER RG	1 PC	500.00	2001
			930.00	11.5
			Total	S\$ 1,574.32
		Add (	ist @ 7%	110.20
		Total Amou	int Payable	S\$ 1,684.52

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SIX HUNDRED EIGHTY FOUR AND CENTS FIFTY TWO ONLY

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	nationale Des Experts En Auton	nobile
MS	FIRST CAPITAL IN	ISURANCE LTD	Ref : CS/FCI190059	15/Ksd3n2
	OBINSON ROAD 01 CITY HOUSES	INGAPORE 068877	Date: 11-07-2019 Code: FCI2	
1.		Policy Particul	ars :- THIRD PARTY CLA	IM
	Insured Veh.	SHC 7223S	Veh. Inspected	EW 6655R
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19002001MFSH	Excess (\$)	0.00
	Assign From	SITHARA	Assign Date	03/04/2019
2.		Vehicle P	articulars & Condition	
	Make & Model	HONDA CIVIC (A)	c.c	1799
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JHMFD16308S214123	Colour	METALLIC PEARL WHITE
	Odometer	203284	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3.		Cor	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	PIRELLI	7 mm
	L/H Front Tyre	205/55 R16	PIRELLI	7 mm
	R/H Rear Tyre	205/55 R16	PIRELLI	7 mm
	L/H Rear Tyre	205/55 R16	PIRELLI	7 mm
4.		Descr	iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE ETAILS.	O/S REAR PORTION.	
5.			eral Information	
	Accident Date	21/03/2019	Inspection Date	11/04/2019
	Survey held at	AH LIM MOTOR COMPANY	,	
		176 SIN MING DRIVE #05-1 SIN MING AUTOCARE SINGAPORE 575721	12	
5a.			Remarks	
	B)THE INSPECTION	ISISTENT TO ACCIDENT RE ON WAS CONDUCTED ON A CE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BAS	
5b.			ate Days of Repair	Physical Company of the Company
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Day	vs



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EW 6655R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	730.00	730.00
15	REAR BUMPER CLIP	NECESSARY	58.50	58.50
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	16.90	
	LESS 20% DISCOUNT		-161.08	-157.70
			644.32	630.80
	LABOUR			
	TO CHECK WIRING AND REINSTALL REVERSE SENSOR.		30.00	30.00
	TO DISMANTLE THE DAMAGED REAR BUMPER.TO REPLACE REAR BUMPER & TO KNOCK & REPAIR REAR AFFECTED AREAS.		400.00	220.00
	TO SPRAY REAR BUMPER & REAR FENDER RG.		500.00	200.00
			930.00	450.00
	GRAND TOTAL		1,574.32	1,080.80

850.0	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)
	(TO ITS PRE-ACCIDENT CONDITION)

Report Ref No. CS/FCI19005915/Ksd3n2

MARKET VALUE: \$33,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$19,764.00=NETT VALUE: \$13,236.00

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.