

INSURANCE

Guo Qiong

REF CS / INC 19005922 / G003ⁿ²

Special Instruction

ASSIGNMENT (Office)

Event/Person

Annie Koh

at

INC

Date/Time

3/4/19@9.43am

Estimated Cost

Bill to

OD / TP / WS / TP / RES / OF / RES / EVA / INV / MV / CS

To Inspect Vehicle No

SKQ 2664B

Insured

SLM 2152X

at Workshop no

Thiam Heng Hwat

Tel

8263 6295

of

176 Sin Ming Drive #05-14

Policy No

Claim No

MT/1038371 -002

Sum Insured

Excess

Make of Veh

D.O.A

29/3/2019

(Client's Record)

CA / REV / REP / REV 24 HRS

HOV, Equipment

Date/Time

10.17am@3/4/19

Person Contacted

Steven

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SKQ 2664B - X

SLM 2152X

Surveyor

602

REF:

Wc

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Thiam Heng Hunt

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 days

Res.: Yes or No

Lum Sum:

20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKA 2664B

Yr Regn:

17 Nov 2016

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 5 2.0L c.c 1998

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

96197

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

IM6CW1071F0119731

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size:

F: 205/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kap sen

Front

Rear

R/Bal.

5 mm

R/Bal.

5 mm

L/Bal.

5 mm

L/Bal.

5 mm

D.O.A.

D.O.I.

03-04-19

Survey held at

W/S

1.14pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Int o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

03/4 estimate give later.

24/10 Int'liz \$1050 with Steven.
 Cred \$869.32, 89%.

24/10/2019

RECEIVED 25 OCT 2019

Date/Time, File Pass to?

☐

Prel. Report

1) 24/10 Int'liz

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee

Transportation

\$ + RS \$

Photos

Others

TOTAL

250

Report Format :

TP

Lump Sum / I.B.I. (\$

1050

Nivitha.(LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Wednesday, 3 April 2019 9:43 AM
To: Admin-D (LKKAuto); assignments
Cc: SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/04/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 3 April 2019 9:38 AM
To: Annie Koh <annie.koh@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/04/2019

Dear Annie,

Thank you for the assignment.

Please be informed that XE 2773D (LEE KUAN HWA) is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annie Koh [mailto:annie.koh@income.com.sg]
Sent: Wednesday, 3 April 2019 9:32 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 03/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA
1	HELENA TAN	MT/1036593-002	XE2773D	LEE KUAN HWA MOTOR SERVICE	24 SUNGEI KADUT STREET 4 SUNGEI KADUT INDUSTRIAL ESTATE SINGAPORE 729050	Siew Chen / 6269 9192	10:00-12:00	SMF4403J	19/3/19
2	DAVID PHUA	MT/1038186-002	SGF15905	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SGG5105D	30/3/19
3	FIONA SHEN	MT/1038371-002	SKQ2664B	THIAM HENG HUAT PTE LTD	176 SIN MING DRIVE #05-14 SIN MING AUTOCARE	Steven / 82636295		SLM2152X	29/3/19

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T+65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	437N
Vehicle Details	
Vehicle No.:	SKQ2664B
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	PE30679398
Chassis No.:	JM6CW1071F0119731
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$18,126.00
Original Registration Date:	17 Nov 2014
First Registration Date:	17 Nov 2014
Transfer Count:	1
Actual ARF Paid:	\$13,126.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Nov 2024
PARF Rebate Amount:	\$9,844.00
Intended COE Rebate Details	
COE Expiry Date:	16 Nov 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$72,201.00
COE Rebate Amount:	\$36,456.00
Total Rebate Amount:	\$46,300.00

The information contained herein is correct as at 24 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2019 17:25
Date Of Accident	29/03/2019 09:00
Exact Location Of Accident	BLK 625 ANG MO KIO AVE 9 OPEN CAR PARK LOT 380
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ2664B
Insured/Policyholder	
Name Of Registered Owner	GIS MOTORING PTE. LTD
Co Reg No	201803437N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5098097810-01
Cover Note Number	

Driver

Name of Driver	CHOW KEE LUM
NRIC No	S0207480Z
Date Of Birth	14/07/1947
Occupation	OUTDOOR
Date Of Driving Pass	18/07/1967
Driving Experience	51 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90033989
Fax Number	
Contact Number	
EMail Address	FRDCHOW@YAHOO.COM.SG

Address	BLK 625 ANG MO KIO AVE 9 #12-104
Postcode	560625
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer to sketch plan.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM2152X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	STELLA
NRIC/Passport Number	
Contact Number	86919964
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 30-3-2019

[Handwritten Signature]

Driver's Signature

(If driver is not the policyholder)

Date & Time: 30-3-2019



Reporting Centre Personnel's Signature


Name:

NRIC/FIN No.:



Sketch Plan Pg. 2

(Estimate)
 Date of accident: 29-3-2019 Time: 10AM Location: OPEN CAR PARK LOT 380
 BIK 625 ANG MO KIO AVE 9
 SINGAPORE S60625
 Veh A: SKQ 2664B Veh B: SLM 2152X No of pax: 1 Weather: Clear/dry Rain/Wet
 SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 29-3-2019 (PM) ABOUT LATE MORNING, I WENT
 TO MY OPEN CARPARK AT BIK 625 ANG MO KIO AVE 9 TO DRIVE
 MY VEHICLE SKQ 2664B (A)
 WHEN I REACHED MY CARPARK, I REALISED MY
 FRONT RIGHT HEADLIGHT & ITS SURROUNDING AREA
 OF MY VEHICLE WAS DAMAGED
 → THERE WAS A WRITTEN NOTE MESSAGE PLACED AT
 MY VEHICLE'S WINDSCREEN BY DRIVER/OWNER
 OF SLM 2152X (B) INFORMING ME TO CALL HER
 AS SHE HAD SCRATCHED MY CAR SIDE.
 3RD PARTY = MS STELLA @ 86919964 (HP)
 SLM 2152X

☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: thiamhaighuat@gmail.com

Email address:

& myself: frdchow@yahoo.com.sg

Email address: HP. 90033989

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

30-3-2019

GAAPOL Sketch Plan Page 2/2

Driver's Signature

(If driver is not the policyholder)

Date & Time: 30-3-2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Thiam Heng Huat

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Vehicle model: MAZDA 5

Number plate: SKQ2664B

List items			
No.	Description	Unit	Amount
1	Bonnet	1	\$ 583.60
2	Bonnet lock	1	\$ 139.80
3	Bonnet bottom lock assy	1	\$ 59.80
4	Bonnet lock sensor	1	\$ 159.30
5	Front fender o/s	1	\$ 307.00
6	Front fender inner cowling o/s	1	\$ 200.40
7	Headlamp assy o/s	1	\$ 1,411.40
8	Headlamp lower bracket o/s	1	\$ 42.20
9	Front bumper	1	\$ 1,055.40
10	Front bumper top panel "MAZDA" emblem	1	\$ 45.30
11	Front bumper side retainer L+R@\$20.50	2	\$ 41.00
12	Front bumper bracket L+R@\$40.20	2	\$ 80.40
13	Front bumper top grille	1	\$ 546.80
14	Front bumper lower grille	1	\$ 668.80
15	Front bumper lower splash cowling	1	\$ 189.90
16	Front fog lamp o/s	1	\$ 389.90
17	Front fog lamp cover o/s	1	\$ 74.40
18	Front bumper tow cover	1	\$ 88.50
19	Front bumper foam	1	\$ 75.40
20	Front bumper reinforcement	1	\$ 338.00
21	Front support panel	1	\$ 429.70
22	Front support panel top garnish	1	\$ 256.85
23	Wiper washer tank	1	\$ 217.80
24	Wiper washer tank motor	1	\$ 187.00
		Subtotal	\$ 8,361.65
		Discount	20%
		Total	\$ 6,689.32

X NP

/ DE
/ AC

X NP

1100.7

880.56

7588.65

Special nett items			
No.	Description	Unit	Amount
1	Sundries	1	\$ 50.00
2	Front fender inner cowling clips o/s	1 set	\$ 60.00
3	Front support panel top garnish clips	1 set	\$ 60.00
4	Front bumper clips	1 set	\$ 60.00
5	Front bumper lower splash cowling clips	1 set	\$ 60.00
6	Bonnet insulator clips	1 set	\$ 60.00
Total			\$ 350.00

{ x ~~10~~
 30 / etc.
 { x

Labour			
No.	Description	Unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.	1	\$ 1,000.00
2	Supply spray paint material and necessary items to respray bonnet, front bumper, front fender o/s, front support panel and other affected areas / panels.	1	\$ 1,000.00
3	Check wiring after repair for proper function.	1	\$ 80.00
4	To rust proof affected areas.	1	\$ 100.00
Total			\$ 2,180.00

200
 200
 { x

Grand Total			\$ 9,219.32
-------------	--	--	-------------

860092

1310.56
 20%: 1050
 2 Days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19005927/Gqd3n2

73 BRAS BASAH ROAD

Date: 25-10-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: FIONA SHEN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 2152X	Veh. Inspected	SKQ 2664B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1038371-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	03/04/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 5 2.0L	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JM6CW1071F0119731	Colour	GREY
Odometer	96197 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	KAPSEN	5 mm
L/H Front Tyre	205/55 R16	KAPSEN	5 mm
R/H Rear Tyre	205/55 R16	KAPSEN	5 mm
L/H Rear Tyre	205/55 R16	KAPSEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/03/2019	Inspect Date / Time	03/04/2019 (01:14 PM)
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 2664B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	NOT NECESSARY	583.60	-
1	BONNET LOCK	NOT NECESSARY	139.80	-
1	BONNET BOTTOM LOCK ASSY	NOT NECESSARY	59.80	-
1	BONNET LOCK SENSOR	NOT NECESSARY	159.30	-
1	FRONT FENDER O/S	NOT NECESSARY	307.00	-
1	FRONT FENDER INNER COWLING O/S	NOT NECESSARY	200.40	-
1	HEADLAMP ASSY O/S	NOT NECESSARY	1,411.40	-
1	HEADLAMP LOWER BRACKET O/S	NOT NECESSARY	42.20	-
1	FRONT BUMPER	DEFORMED	1,055.40	1,055.40
1	FRONT BUMPER TOP ;PANEL "MAZDA" EMBLEM	NECESSARY	45.30	45.30
2	FRONT BUMPER SIDE RETAINER L+R @\$20.50	NOT NECESSARY	41.00	-
2	FRONT BUMPER BRACKET L+R @\$40.20	NOT NECESSARY	80.40	-
1	FRONT BUMPER TOP GRILLE	NOT NECESSARY	546.80	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	668.80	-
1	FRONT BUMPER LOWER SPLASH COWLING	NOT NECESSARY	189.90	-
1	FRONT FOG LAMP COVER O/S	NOT NECESSARY	74.40	-
1	FRONT BUMPER TOW COVER	NOT NECESSARY	88.50	-
1	FRONT BUMPER FOAM	NOT NECESSARY	75.40	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	338.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	429.70	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	256.85	-
1	WIPER WASHER TANK	NOT NECESSARY	217.80	-
1	WIPER WASHER TANK MOTOR	NOT NECESSARY	187.00	-
1	FRONT FOG LAMP O/S	NOT NECESSARY	389.90	-
	LESS 20% DISCOUNT		-1,517.73	-220.14
			6,070.92	880.56
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	SET FRONT FENDER INNER COWLING CLIPS O/S (SN)	NOT NECESSARY	60.00	-
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	60.00	-

Report Ref No. CS/INC19005927/Gqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRONT BUMPER LOWER SPLASH COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	60.00	-
			350.00	30.00
	LABOUR			
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEATING,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.		1,000.00	200.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY BONNET,FRONT BUMPER,FRONT FENDER O/S,FRONT SUPPORT PANEL AND OTHER AFFECTED AREAS/PANELS.		1,000.00	200.00
	CHECK WIRING AFTER REPAIR FOR PROPER FUNCTION.	NOT NECESSARY	80.00	-
	TO RUST PROOF AFFECTED AREAS.	NOT NECESSARY	100.00	-
			2,180.00	400.00
GRAND TOTAL			8,600.92	1,310.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,050.00

Report Ref No. CS/INC19005927/Gqd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.