

Asher Sng (LKKAUTO)

From: Varun C360 <varun@corporate360.us>
Sent: Wednesday, 10 April 2019 12:31 PM
To: Asher Sng (LKKAUTO)
Subject: Accident Notice - SKQ 1126U & SLK 8428Y

Ref: CC4/ASM19005940/ea3//S9M01IZG

Accident Date - 02.04.2019

Location: Exit gantry gate at Kallang Leisure Mall Car Park

Incident - The driver of SLK 8428Y exited the gantry gate at the car park and suddenly stopped the car. I, the driver of SKQ 1126U exited when the gantry gate opened but due to the sudden stopping of the other car in front of me, I slowly hit the back bumper. There were minor scratches on the rear bumper of SLK 8428Y and my car. It was discussed that both cars can be repaired at a minimal cost at a painting workshop for which I will pay the fee. However, the other car driver insisted to report to Volkswagen and fix a new bumper. This is totally inappropriate and an expensive process hence I requested the driver to consider fixing the minor repair work elsewhere. I fixed my car bumper for less than \$150 at a good Paint work shop. I showed the photos of the other car and it was approximately quoted for less than \$200. For such a minor repair work and with less expensive options available, it is inappropriate for the other driver to opt for replacement with a new bumper that costs \$4000. This is an inappropriate claim and I do not want my NCD to be affected.

Thanks,

Varun
84449824