

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

INSURER: **FWD Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	19/FWD/OD-181 (04)
Policy No:	PNPV2018-00007629	Date of Loss:	01/04/2019
Vehicle Reg. No.:	SLP6734A	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GAIFIL HAIRI BIN ABDULLAH		
Driver:	GAIFIL HAIRI BIN ABDULLAH		

Make/Model:	VOLVO V40, 2.0 T2 CROSS COUNTRY (A)	Vehicle Reg. Date:	13/01/2015
Vehicle Colour:	GREY	Chassis No:	YV1MZ845BF2066212
Engine No:	D4162T3051035		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Not return
Take job. Return party.
3 day excess \$1000
5/4/19

Remarks: VEHICLE NOT IN
 Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS	Amount
Parts	3,400.00
Miscellaneous Items	0.00
Labour	730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	4,130.00
+ GST 7.00% (\$)	289.10
Nett Amount (\$)	4,419.10

4480

This claim is handled by: **CHIA PEI YING**

Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS	
Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2019)
Parts: 144	VOLVO V40 2.0 T2 CROSS COUNTRY (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: SME Motor Pte Ltd/SLP6734A/03/04/2019 16:06	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER (TOP) <i>Dis/Torn</i>	0.00	0.00	*1,480.00 F ✓
2	1		*REAR BUMPER RETAINER RH <i>crn</i>	0.00	0.00	*100.00 F ✓
3	10		*REAR BUMPER CLIP <i>rec</i>	0.00	0.00	*50.00 F ✓
4	1		*REAR BUMPER (LOWER) <i>De/Torn</i>	0.00	0.00	*750.00 F ✓
5	1		*REAR BUMPER SPOILER <i>Torn</i>	0.00	0.00	*750.00 F ✓
6	1		*REAR RH FENDER INNER COWLING <i>Torn</i>	0.00	0.00	*230.00 F ✓
7	8		*REAR RH FENDER INNER COWLING CLIP <i>rec</i>	0.00	0.00	*40.00 F ✓
Total Parts (S\$)						3,400.00

F=Franchise part.

SME Motor Pte Ltd/SLP6734A/03/04/2019 16:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items
 There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 <i>20</i>
2	LABOUR CHARGE	New	350.00 ✓
3	SPRAY PAINTING	New	350.00 <i>300</i>
Gross Labour Cost (S\$)			730.00

SME Motor Pte Ltd/SLP6734A/03/04/2019 16:06. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

9-3550
1260-770

4320.