

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19005951/Avd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 08-04-2020 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 7172E	Veh. Inspected	SJE 2148A
	Policy No.		Coverage (\$)	0.00
	Claim No.	D19002218MFSH	Excess (\$)	0.00
	Assign From	SITHARA	Assign Date	03/04/2019
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FIT	c.c	1339
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	GE61057884	Colour	WHITE
	Odometer	195196	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	MICHELIN	6 mm
	L/H Front Tyre	195/55 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/55 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/55 R15	MICHELIN	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	01/04/2019	Inspection Date	04/04/2019
	Survey held at	ACE AUTOLUTION PTE LTD		
		13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a.	ı. Remarks			
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			