

SINGAPORE 417807.

**BILLING****BILL to -**

Vehicle NO SJF 2148 A

Repair Type : LUMPSUM

Repair As Per Surveyor Report S 3,100.00

Material Cost :

Less Repair Items Adjustment

Special Net Items :

Total Repair Cost : S 3,100.00

Final Repair Cost : S 3,100.00

**Others**

Search Fee (LTA) S

Surveyor Fees S

Loss of Rental S

Loss Of Use S 1,800.00 15 days (include Sat,Sun.Waiting PRI&amp;public holidays)

**Total Amount Bill : S 4,900.00**