22/03/2002 ASS. REC, BY:	REF: CS/ F(11900	5953 RI+d30	Pecial Instruction:
Surveyor: Rasu	ASSIGNMI	ENT (Office)	
From (Person): SITH			Date/Time: 3.4.19 5.39p.m
Estimated Cost:		Bill to:	
To Inspect Vehicle No:	SKP L731U	CS	ed: SH (0205 R
at Workshop m/s Juz	z Performance	Т	el: 63850303
of 8 Kati Buki	it Ave 4 # 03-51/	5) primiar	
Policy No:		Claim No: D1900	2255 MFSH
Sum Insured:		Excess:	
Make of Veh:			D.O.A. 01.04.2019
(Client's Record) CA / REV / REP. /] Date/Time: 4.4.1	REV 24 HRS "WP" 10.319.m Person Contacted:		HOD Endorsement
Date/Time Action/In	estruction (V) Estimate 31 V - X 0205 R - X		
	rensed to sathema	by ensist.	
Conf	rm lump sum s	\$19007- CREC	l: 7513.30; 71%)

.



MS First Capital Insurance Limited Co Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

03-04-2019

Our Ref No. D19002255MFSH

Accident Date

01-04-2019

Claim Type. Third Party

Insured Vehicle

SHC0205R

Third Party Vehicle. SKP6731U

Survey Location

8 KAKI BUKIT AVE 4 #03-51/52 PREMIER @ KAKI BUKIT

Contact Person.

FIRA

Contact No.

63850303/0

Fax No. 63857038

Survey Type

WITHOUT PREJUDICE:

10.31a.m

V . 04+

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

5. /\ D. C

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

JUZZ PERFORMANCE

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SITHARA

PTE LTD

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 9 April 2019 4:03 PM

To:

'CWS Motor Claims'; assignments

Cc:

'Sithara'; SUR

Subject:

RE: SURVEY ASSESSMENT - D19002255MFSH/1

Attachments:

CSFCI19005953R1td3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SKP 6731U.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 4 April 2019 10:37 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19002255MFSH/1

Dear Sir / Mdm.

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Wednesday, 3 April, 2019 5:39 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Sithara < Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19002255MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Your Ref: D19002255MFSH

Date: 09 April 2019

Our Ref: CS/FCI19005953/R1td3

The Motor Claims Department MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKP 6731U .

Please be informed that we had conducted the inspection of the abovementioned vehicle on $\underline{08/04/2019}$ at the premises of M/s $\underline{JUZZ\ PERFORMANCE}$. and have the following to report:-

Workshop Estimate Amount	: <u>S</u> \$	24,513.30	
Revised Estimate Amount	: <u>S</u> \$	15,192.30	
"Check" Items Amount	: <u>S\$</u>	-	
Market Value	: <u>S</u> \$		
LTA Reimbursement Value	: <u>S\$</u>	-	
Nett Value	: <u>S\$</u>	1-	

Description of Damage:

<u>The vehicle sustained damages</u>
<u>at the rear n/s portion.</u>



Yours faithfully

Rasul Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, yo aforesaid.	u hereby consent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	02/04/2019 08:47
Date Of Accident	01/04/2019 16:00
Exact Location Of Accident	NORTH BRIDGE ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKP6731U
Insured/Policyholder	
Name Of Registered Owner	NOORJANNAH BTE ABOOBAKER
NRIC No	S7138886G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90061610

OFFICE-90061610

Alternative Phone No Vehicle Particulars

Manufacturer **BMW**

X3 XDRIVE20I ABS 4WD HID DSC SR NAV Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY PRIVATE CAR Vehicle Category

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy

Policy Number 9VPCP1853510 (COMP)

Cover Note Number

Driver

NOORJANNAH BTE ABOOBAKER Name of Driver

NRIC No S7138886G Date Of Birth 10/11/1971 Occupation **INDOOR** Date Of Driving Pass 01/01/1999

20 YEARS AND 3 MONTHS **Driving Experience**

Gender **FEMALE**

Mobile Number (LOCAL) +65-90061610

Fax Number

Contact Number OFFICE-90061610

EMail Address NOEMAIL Address 544 EAST COAST ROAD

Postcode 458972

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

YES NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC205R

Vehicle Make/Model/Colour HYUNDAI I40 1.7L CRDI

Details Of Properties

Vehicle Category TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLW7610E

. Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

BMW 318I

PRIVATE CAR

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKM707X

Vehicle Make/Model/Colour

TOYOTA VELLFIRE 2.4Z

Details Of Properties

Vehicle Category

PRIVATE HIRE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

- 2 APR 2019

Policyholder's Signature Driver's
Date & Time: (If drive

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC) 23 Kaki Bukit Ave 4 Singapore 415933

Tel: 67416697 Fax: 67492305

Name: NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN		
SKETCHTEAN		8 -> Traffic light &
		1
5KP6731	u < A	I waspstationary position when taxi of hit me. But it was & not his fault as
SHC 205 R &	- A 4 []	has a tappened only camera's # often a few
SLW 7610 E -	÷ B ← □	witness & Seconds-
SKM 707X CPTE CAR HIRE DRIVER)	= C 4 L	4
DESCRIBE CIRCUMSTANCES OF	THE ACCIDENT	
On 1 Apral J was dravai accordance	2019 at 4pm of in a norm To the region.	along North Bridge Red, I way and in ed speed limed.
When approach and my co	hing a traffic on came to by left lan	light, I slowed down a complete stopas I
J wish to w jam my brak due to the	e. My con case. troffic lights.	me to a complete stop
Whilst my a tami histourt, I saw tami drave taxi plate n	there were 7	
me about	S seconds AFTER	Lationary but it hit
1 1/2	APR 2019	23 Kaki Bukit Ave 4 Singapore 415933 Tel: 67416697 Fax: 67492305 Email: vackb@singnet.com.sg
Policytolder's Signature Date & Time;	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Describe Circumstances of the Accident
WAS
it caused by the impact from the other cans
hitting the taxi from behind him. Hence, Mr him
was not directly the party that hit my car.
Mr hiam the faxi driver has a camera in
his can and it would show the segmence of what happened.
The con immediately behind Mr Liam is
Ms Rosie's vehicle Her licence plate no is SLW 76/0E
The car behind Ms Rosie is kevin Tan Song & Kevin is a private hire car driver
V

Declaration

I/We declare the foregoing particulars are true in every respect.

- 2 APR 2019

& Time

IDAC KAKI BUKIT (VAC) 23 Kaki Bukit Ave 4 Singapore 415933 Tel: 67416697 Fax: 67492305 Email: vackb@singnet_com.sg Witnessed by Reporting Centre

Driver's Signature (If driver is not the policyholder) / Date

Personnel

Policyholder's Signature / Date &

JUZZPERFGRMANCE

Co Reg No: 201534963C 8 Kaki Bukit Avenue 4 #03-51/52 Premier@Kaki Bukit

Singapore 415875

Email: admin@juzzperformance.com.sg /

TO

: First Capital Insurance Ltd

DATE

: 8-Apr-19

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

ESTIMATE REPORT :

OWNER'S PARTICULAR

VEHICLE DETAILS

NAME

: NOORJANNAH BTE **ABOOBAKER**

VEHICLE NO : SKP6731U

ADDRESS

: 544 EAST COAST ROAD

MODEL

: BMW X3

TEL. NO.

Singapore 458972 : 90061610

CHASSIS NO : OB27910

OWNER'S INSURANCE:

ACCIDENT DETAILS

DATE: 1-Apr-19

TIME : 16:00

THIRD PARTY REQUESTOR / CONTACT :

QUOTATION SUMMARY

CLAIM DETAIL: PARTS

S/N	DESCRIPTION	QTY UNIT LIST PRICE		DESCRIPTION		PRICE	
1	TAILGATE M	1	\$	3,125.80	\$	3,125.80	176
2	TAILGATE UPPER LOCK 🗡 🗥	1	\$	321.00	\$	321.00	
3	TAILGATE LOGO NE	1	\$	112.00	\$	112.00	68
4	TAIL GATE EMBLEM 'X3'	1	\$	98.00	\$	98.00	61
5	TAILGATE WEATHER STRIP W	1	\$	298.00	\$	298.00	1
6	TAILGATE INNER TRIM X 1/1/1	1	\$	398.00	\$	398.00	
7	TAILGATE LOWER LOCK 🗡 🕠	2	\$	268.00	\$	536.00	
8	REAR BUMPER 7	1	\$	1,989.00	\$	1,989.00	140
9	REAR BUMPER (LOWER)	1	\$	689.00	\$	1,378.00	23
10	REAR BUMPER CENTER BRACKET (PA)	1	\$	298.50	\$	298.50	110
11	REAR BUMPER SIDE BRACKET CA / IAC	1	\$	154.00	\$	308.00	12
12	REAR BUMPER REINFORCEMENT 84/	1	\$	768.00	\$	768.00	68
13	REAR BUMPER SIDE REATINER ✓ 🗥	2	\$	215.00	\$	430.00	
14	REAR BUMPER TOWING COVER ✓ 🔨 🔨	2	\$	52.00	\$	104.00	
15	REAR BUMPER REFLECTOR (LEFT HAND)	1	\$	48.00	\$	48.00	/
16	TAILLAMP (LEFT HAND) YN	1	\$	589.00	\$	589.00	
17	TAILLAMP SIDE GARNISH (LEFT HAND)	1	\$	120.00	\$	120.00	

4804

1	TAILLAMP LOWER BRACKET X NN	2	\$	185.00	\$ 370.00	
19	REAR FENDER INNER COWLING X VIV	2	\$	190.00	\$ 380.00	
20	REAR FENDER INNER TRIM 🗡 🗚	2	\$	750.00	\$ 1,500.00	
21	REAR FENDER OUTER WHEEL ARC (LEFT HAND)	NNZ	\$	321.00	\$ 642.00	
	REAR END PANEL (OUTER) 64/	1	\$	1,135.00	\$ 1,135.00	497
23	REAR END PANEL TOP GARNISH 🗡 🗚	1	\$	298.00	\$ 298.00	
24	REAR END PANEL FEXIBLE GARNISH (TOP)	1	\$	398.00	\$ 398.00	
25	REAR EXHAUST MOUNTING #	p	\$	48.00	\$ 96.00	48
26	REAR EXHAUST GARNISH ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓	1	\$	62.00	\$ 124.00	
27	REAR EXHAUST HEAT SHIELD 14/	2	\$	324.00	\$ 648.00	155
28	REAR EXHAUST PIPE 44/	1	\$	2,948.00	\$ 2,948.00	1482
	6989	TOTAL	PRIC	Œ	\$19,460.30	
	5 %	LESS 0	%		\$ -	
	1639.55	SUB T	OTAL	PRICE	\$19,460.30	

	00			
S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE ✓ ✓ ✓	1	\$50.00	\$50.00
2	REAR BUMPER CLIPS W	8	\$6.50	\$52.00
3	TAILGATE UPPER SEALANT 🗴 🔨	1	\$80.00	\$80.00
4	TAILGATE LOWER SEALANT / 1	1	\$60.00	\$60.00
5	TAILGATE LOWER INNER TRIM CLIPS	8	\$6.50	\$52.00
6	REAR FENDER INNER TRIM CLIPS X AA	20	\$6.50	\$130.00
7	REAR FENDER INNER COWLING CLIP 🗡 🗥	18	\$6.50	\$117.00
8	REAR FENDER WHEEL ARC CLIPS × 111	12	\$6.50	\$78.00
9	REAR END PANEL TOP GARNISH CLIPS	4	\$8.50	\$34.00
10	REAR END PANEL SEALANT	1	\$150.00	\$150.00
11	REAR REVERSE SENSOR	1	\$350.00	\$350.00

TOTAL

\$1,153.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

TO PANEL BEAT, REMOVE AND 1 REPLACE PARTS	\$1,000.00 200 800
2 TO SPRAY PAINT AFFECTED AREA	\$1,200.00 600 700
3 TUFF COAT	\$250.00 40
4 WIRING AND BULB CHECK	\$80.00 × NA
REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY TO FACILIATE 5 REPAIR	\$300.00

60

345

REMOVE AND REFIX REVERSE 6 SENSOR AND DISTANCE SETTING	\$60.00	60	
TRANFER TAILGATE MECHANISM 7 (UPPER AND LOWER)	\$190.00	60	
8 CONDUCT WATER LEAKAGE TEST	\$80.00	×	
REMOVE AND REFIX REAR EXHAUST 9 PIPE	\$150.00	60	

TOTAL

\$3,900.00

1800

ESTIMATE REPORT

TOTAL PARTS COST

\$20,613.30

TOTAL LABOUR COST :

\$3,900.00

TOTAL REPAIR COST :

\$24,513.30

APPROVED DETAILS

EXCESS

NO. OF WORKING DAYS: 6 Joy

RE-SURVEY

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

08/04/18 @1450

90000068

Rematte repriv

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

6639.55 1800.00 8784.55

20% 7027.64 4s-7000 6 days



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19	99607198R GST Reg. No. 19-96	0/198-R		
	Affiliated to Federation Interna	tionale Des Experts En Automo	bile		
MS FIRST CAPITAL IN	ISURANCE LTD	Ref : CS/FCI1900595	3/R1td3e2		
36 ROBINSON ROAD #16-01 CITY HOUSES	INGAPORE 068877	Date: 07-05-2019 Code: FCI2			
1.	Policy Particular	s :- (THIRD PARTY CLAIM	1)		
Insured Veh.	SHC 205R	Veh. Inspected	SKP 6731U		
Policy No.		Coverage (\$)	0.00		
Claim No.	D19002255MFSH	Excess (\$)	0.00		
Assign From	SITHARA	Assign Date	03/04/2019		
2.	Vehicle Pa	rticulars & Condition			
Make & Model	B.M.W. X3 XDRIVE20I	c.c	1997		
Engine No.	HIDDEN	Year of Reg.	2014		
Chassis No.	WBAWX320800B27910	Colour	WHITE		
Odometer	51778	Steering	IN ORDER		
Brakes	IN ORDER	Modification	SPORTS RIM		
General	FAIR				
3.	Cond	ditions of Tyres			
	Size	Make	Balance		
R/H Front Tyre	245/50 R18	PIRELLI	6 mm		
L/H Front Tyre	245/50 R18	PIRELLI	6 mm		
R/H Rear Tyre	245/50 R18	PIRELLI	6 mm		
L/H Rear Tyre	245/50 R18	PIRELLI	6 mm		
4.		otion of Damages			
TOTAL DESIGN SERVE SERVE	STAINED DAMAGES AT THE	REAR N/S PORTION.			
DAMAGES SEE D		eral Information			
5. Accident Date	01/04/2019	Inspection Date	08/04/2019		
Survey held at			00/04/2010		
8 KAKI BUKIT AVENUE 4 #03-51/52 PREMIER @ KAKI BUKIT SINGAPORE 415875					
5a.		Remarks			
B)THE INSPECTION	NSISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A"\ CE TO YOUR INSTRUCTIONS	MITHOUT PREJUDICE" BASI	S. ED REPAIRS.		

Estimate Days of Repair

6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 6731U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	BENT	3,125.80	1,765.00
1	TAILGATE UPPER LOCK	NOT NECESSARY	321.00	-
1	TAILGATE LOGO	NECESSARY	112.00	68.00
1	TAIL GATE EMBLEM 'X3'	NECESSARY	98.00	61.00
1	TAILGATE WEATHER STRIP	сит	298.00	298.00
1	TAILGATE INNER TRIM	NOT NECESSARY	398.00	-
2	TAILGATE LOWER LOCK @\$268.00	NOT NECESSARY	536.00	:=
1	REAR BUMPER	DEFORMED	1,989.00	1,400.00
2	REAR BUMPER (LOWER) @\$689.00	CUT-1PC ONLY	1,378.00	239.00
1	REAR BUMPER CENTER BRACKET	CRACKED	298.50	110.00
2	REAR BUMPER SIDE BRACKET @\$154.00	CRACKED-1PC ONLY	308.00	126.00
1	REAR BUMPER REINFORCEMENT	BENT	768.00	689.00
2	REAR BUMPER SIDE REATINER @\$215.00	NOT NECESSARY	430.00	-
2	REAR BUMPER TOWING COVER @\$52.00	NOT NECESSARY	104.00	-
1	REAR BUMPER REFLECTOR (LEFT HAND)	CRACKED	48.00	48.00
1	TAILLAMP (LEFT HAND)	NOT NECESSARY	589.00	-
1	TAILLAMP SIDE GARNISH (LEFT HAND)	NOT NECESSARY	120.00	-
2	TAILLAMP LOWER BRACKET @\$185.00	NOT NECESSARY	370.00	-
2	REAR FENDER INNER COWLING @\$190.00	NOT NECESSARY	380.00	-
2	REAR FENDER INNER TRIM @\$750.00	NOT NECESSARY	1,500.00	-
2	REAR FENDER OUTER WHEEL ARC (LEFT HAND) @\$321.00	NOT NECESSARY	642.00	-
1	REAR END PANEL (OUTER)	BENT	1,135.00	497.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	298.00	-
1	REAR END PANEL FEXIBLE GARNISH (TOP)	NOT NECESSARY	398.00	-
2	REAR EXHAUST MOUNTING @\$48.00	CUT-1PC ONLY	96.00	48.00
1	REAR EXHAUST GARNISH	NOT NECESSARY	124.00	-
2	REAR EXHAUST HEAT SHIELD @\$324.00	BENT	648.00	155.00
1	REAR EXHAUST PIPE	BENT	2,948.00	1,485.00

Report Ref No. CS/FCI19005953/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LESS 5% DISCOUNT			-349.45
			19,460.30	6,639.55
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
8	REAR BUMPER CLIPS @\$6.50 (SN)	NECESSARY	52.00	52.00
1	TAILGATE UPPER SEALANT (SN)	NOT NECESSARY	80.00	-
1	TAILGATE LOWER SEALANT (SN)	NOT NECESSARY	60.00	
8	TAILGATE LOWER INNER TRIM CLIPS @\$6.50 (SN)	NOT NECESSARY	52.00	
20	REAR FENDER INNER TRIM CLIPS @\$6.50 (SN)	NOT NECESSARY	130.00	:-
18	REAR FENDER INNER COWLING CLIP @\$6.50 (SN)	NOT NECESSARY	117.00	a -
12	REAR FENDER WHEEL ARC CLIPS @\$6.50 (SN)	NOT NECESSARY	78.00	1.0
4	REAR END PANEL TOP GARNISH CLIPS @\$8.50 (SN)	NECESSARY	34.00	34.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	150.00	60.00
1	REAR REVERSE SENSOR (SN)	NOT WORKING	350.00	250.00
			1,153.00	396.00
	LABOUR			
	TO PANEL BEAT, REMOVE AND REPLACE PARTS.		1,600.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	700.00
	TUFF COAT.		250.00	40.00
	WIRING AND BULB CHECK.	NOT NECESSARY	80.00	9-
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY TO FACILIATE REPAIR.		300.00	80.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	60.00
	TRANFER TAILGATE MECHANISM (UPPER AND LOWER)		160.00	60.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	80.00	
	REMOVE AND REFIX REAR EXHAUST PIPE.		150.00	60.00
			-	
			-	
			3,900.00	1,800.00
	GRAND TOTAL		24,513.30	8,835.55

Report Ref No. CS/FCI19005953/R1td3e2



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS 7,000.00
(TO ITS PRE-ACCIDENT CONDITION)

Report Ref No. CS/FCI19005953/R1td3e2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.