



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 04.04.2019

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2737D PRIUS HYBRID 1.8L A (2012)

To Supply

1) 1pc	Rear bumper <i>de</i>	\$	1,218.00
2) 1set	Rear bumper clips <i>na</i>	\$	30.00
Sub total parts		\$	1,248.00
Less: 25% discount		\$	(312.00)
		\$	936.00

To supply S.Nett Parts

1) 1set	Reverse sensor <i>?</i>	\$ <i>200</i>	250.00
Sub total S.Nett parts		\$	250.00

L/charge

1) To remove & replace reverse sensor. Check wiring.	\$	50.00
2) To knock / repair rear end panel. Remove rear bumper. Replace the above parts. Align & adjust rear bumper.	\$	200 300.00
3) To putty, respray painting rear bumper & rear end panel. To polish.	\$	200 300.00
Sub total L/charges		\$ 650.00
Estimated Grand Total		\$ 1,836.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Resue
4p 90000068
2 days
43
05/04/19 @ 1730
Resue after repair