



Co. Reg. No.: 201416720C
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
 Tel : 6636 9100 Fax : 6636 9113

Date : 03/04/2019

TO: AXA Insurance Singapore Pte Ltd
 8 Shenton Way
 #27-01 AXA Tower
 Singapore 068811

Poh Kin.

Our Customer : Ou Yaocan
 Vehicle No : SLL3609U
 Model : Volkswagen Jetta 1.4
 Manufacture Year : 2015 (Reg:22/2/2017)
 Date of Accident : 25/2/2019
 Total Estimate Repair Days : 7
 Total Pages : 2

Attn : Motor Claims Department
 Email : motor.survey@axa.com.sg

Re: Repair Estimate For Third Party Claim against FBF2656P

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A. Spare Parts					
1	Boot lid <i>Revised</i>	1	\$1,290.00	\$1,290.00	✓
2	Boot lid weatherstrip <i>seen</i>	1	\$295.00	\$295.00	✗
3	Boot lid reflector RH <i>cut</i>	1	\$399.00	\$399.00	✓
4	Boot lid "Volkswagen" logo <i>see</i>	1	\$80.00	\$80.00	✓
5	Boot lid "Jetta" emblem <i>see</i>	1	\$80.00	\$80.00	✓
6	Boot lid "TSI" emblem <i>see</i>	1	\$70.00	\$70.00	✓
7	Tail lamp RH <i>cut</i>	1	\$380.00	\$380.00	✓
8	Rear bumper <i>Revised</i>	1	\$1,050.00	\$1,050.00	✗
9	Rear bumper foam <i>seen</i>	1	\$220.00	\$220.00	✗
10	Reverse sensor <i>Revised 1 piece</i>	2	\$290.00	\$580.00	<i>200 (SN)</i>
11	Rear bumper reflector RH <i>cut</i>	1	\$140.00	\$140.00	✓
				Total	\$4,584.00
				Less 10%	\$458.40
				Sub Total 1	\$4,125.60
<i>2438 2195.10 SN: 200</i>					
B. Spare Parts (S/Nett)					
1	Rear number plate w/casing <i>seen</i>	1	\$70.00	\$70.00	✓
2	Rear bumper clip <i>seen</i>	10	\$9.00	\$90.00	✗
				Sub-Total 2	\$160.00
				Total for Parts	\$4,285.60
C. Labour					
1	To check wiring.			\$80.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00	<i>300</i>
3	Spray painting all affected parts & areas.			\$600.00	<i>400</i>
4	To spray anti-rust undercoat.			\$60.00	<i>✗</i>
				Total Labour	\$1,540.00
				Total Repair Cost	\$5,825.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*total 3125.10 Admin Lj
 1/2: 25K. 1/2: 08/04/19.
 03 pags.*