

Su Brothers' Motor Workshop

Blk 5034 Ang Mo Kio Industrial Park 2

#01-341/343

Singapore 569537

Tel : 64824355 Fax : 64824788 Email : su_bros@singnet.com.sg

Co. Reg. No : 26584500M GST Reg No : M9-0008282-A

Date : 03/04/2019

Pg 1/2

Our Ref : SB/MC/0131/04/19 TD

Longpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Attention : Motor Claims Department

Vehicle No : SKT 2924 K

Make/Model : Subaru XV

DOA : 02/04/2019

Your insured Vehicle reg no: GBB 1600 C

List Items:-

1 pc	Rear bumper	\$	894.00
1 pc	Rear bumper side retainer	\$	16.00
10 pcs	Rear bumper clip @ \$3.50	\$	35.00
1 pc	Rear bumper n/s side reflector	\$	24.00
1 pc	Rear bumper reinforcement	\$	187.24
1 pc	Rear bumper n/s bracket	\$	28.80
1 pc	Rear bumper centre reflector	\$	102.00
1 pc	n/s tail lamp assy	\$	377.40
1 pc	Rear end panel	\$	388.00
1 pc	Rear end panel upper garnish	\$	100.00
1 pc	Rear end panel upper garnish chrome plate	\$	210.00
1 pc	Boot gate	\$	910.80
1 pc	Boot gate rubber	\$	119.00
1 pc	Boot gate emblem " Subaru "	\$	68.00
1 pc	Boot gate emblem " XV "	\$	40.80
1 pc	Boot gate emblem " Synmetrial AWD "	\$	69.00
1 pc	Rear w/s moulding	\$	98.00
1 pc	Rear camera head	\$	560.00
1 pc	Rear n/s fender inner shield	\$	64.80
1 pc	Rear n/s fender curve outer garnish	\$	180.50
1 pc	Rear n/s fender lower air vent garnish	\$	64.00
1 pc	Rear boot inner trim	\$	252.00
		\$	4,789.34
Less 10%		\$	478.93
Bal c/d		\$	4,310.41

Our Ref : SB/MC/0131/04/19 TD
Vehicle No : SKT 2924 K

Bal b/f \$ 4,310.41

Special Nett Item:-

1 pc Rear w/s gum \$ 50.00

Labour Charges:-

To check & reconnect harness wiring. \$ 35.00

To spray on anti rust proofing. \$ 100.00

To putty & spray painting. \$ 880.00

To remove/refit rear w/s glass. \$ 120.00

To transfer rear wiper motor, blade, 3rd brake light, rear spoiler etc to new boot gate. \$ 80.00

To cut/weld rear end panel, knock & reshape rear spare tyre panel, n/s tail lamp panel, rear n/s fender, to renew above parts etc. \$ 860.00

\$ 6,435.41

