

# AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153  
Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aacls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M

TO:

Lonpac Insurance - Claims Dept  
300 Beach Road,  
#17-04/07 The Concourse,  
Singapore 199555

## Quotation

DATE: 12-Apr-19

TERMS: 30 Days

PAGE NO.: Page 1 of 1

S/N	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (\$)
<b>Accident Repair of YP602H</b>				
DOA : 23/02/2019 @ ALONG BT BATOK WEST AVE 2 (GBG9160B)				
1	To jet, pull and adjust the box structure with welding Add 4pcs of angle bar with welding support on rear corner pillars To supply part and labour			800 \$ 1,050.00
2	To supply and replace 1pc spring lock at RHS sliding door			\$ 80.00
3	To supply and replace 2pcs aluminium composite panel at rear swing door	2	600 \$800.00	\$ 1,600.00
4	To spray painting			\$ 600.00
				500
				1200
				500
<b>LKK Auto Consultants hence notify the Repairer of the following:</b> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul>				
Acknowledged by Repairer Signature: Date:				
E. & O. E.				
SGD: THREE THOUSAND FIVE HUNDRED SIXTY-THREE AND CENTS TEN ONLY.			SUB-TOTAL	\$3,330.00
			7% GST	\$233.10
			TOTAL	\$3,563.10

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd.".

AAK LOGISTICS SERVICES PTE LTD



Authorised Signature