

CITYCAB PTE LTD

kenneth.ding@dingauto.sg 92313123
kelly.ding@dingauto.sg 9688323

DING AUTOMOTIVE PTE LTD
Blk 10 Sin Ming Industrial Estate Sector C
#01-20
Singapore 575645
Tel: 6452 1208 Fax: 6452 0814

TO :
ESTIMATE REPORT 1ST Quotation
FAX NO:
05/04/2019 9:03
JOB-NO: 60111541
OWNER'S PARTICULARS
NAME: CityCab PTE LTD (Fleet) CONTACT: 85533880 Page 1 of 1
ADDRESS: 383 SIN MING DRIVE 64739522
SINGAPORE 575717 0

VEHICLE DETAILS
LICENSE NO: SHA9982G TRANS: AUTO CHASSIS: KMHLB41UMFU089271
MAKE / MODEL: HYUNDAI / i40 ENGINE: D4FDEU449437
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REPAIR REAR LH DOOR . STRAIGHTEN AND PANEL BEAT ON ACCIDENT AFFECTED AREAS	1.00	500.00	0.00	500.00		Y	250
2 RUST PROOFING ON ACCIDENT AFFECTED AREAR	1.00	80.00	0.00	80.00		Y	20
3 RESPRAY SIDE SKIRT RH	1.00	230.00	0.00	230.00		Y	x
4 RESPRAY REAR FENDER RH	1.00	230.00	0.00	230.00		Y	x
5 RESPRAY REAR DOOR RH	1.00	230.00	0.00	230.00		Y	200
TOTAL:		1,270.00	0.00	1,270.00			

MATERIALS							
1 REAR DOOR ADS STICKER RH	1.00	180.00	0.00	180.00	S	Y	cut
2 REAR FENDER ADS STICKER RH	1.00	180.00	0.00	180.00	S	Y	cut
3 SIDE SKIRT ADS STICKER RH	1.00	180.00	0.00	180.00	S	Y	cut
4 SUNDRIES	1.00	50.00	0.00	50.00	S	Y	20
TOTAL:		590.00	0.00	590.00			

Supplementary Rear Door Sticker - 6552 1111 SM 80.00 (17) nec
TOTAL PARTS & LABOUR : 1,860.00 0.00 1,860.00

EXCESS/LOADING:\$ 0.00

No. Of Day: 02

RE-SURVEY: BEFORE/AFTER PAINTING PART-BY-PART OR LUMP SUM: \$ \$ Resurvey photo of new sticker

DATE OF SURVEY: 5, 4, 19

SURVEYED BY: Tanph

CONTACT NO: 94495744 FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001
Ding Auto User 1

ESTIMATOR
STA AUTOCENTRE
TEL: FAX:

Labour \$ 470
SN \$ 640

16.35 hrs

Total \$ 1110.00