

Kw

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

SKF 7054L

AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 CHARTIS BUILDING SINGAPORE 079120

Estimate : TP19/036

Attention : Motor Claim Department

Contact : 64191000 Fax No. : 64193727 Claims Dept

Date : 08/07/2019
 Vehicle Num. : SMH 91R
 Make/Model : SUBARU LEGACY 2.0-2006
 Chassis/Eng# : BP5137363/EJ20D006306
 Accident Date : 22/11/2018
 Claim No. :
 Reference : LYB/SMH91R(SKF7054L)/AIG/tp/sl
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		<i>Not Notarised</i>		
		<i>Resurvey After Paint 2 days</i>		
		<i>85441/5</i>		
		<i>6201</i>		
1.	1	NETT ITEMS : FRONT BUMPER RETAINER/RH		<i>nn</i> 86.90 <i>X</i>
		Nett Total S\$:		86.90
		10.00% Discount S\$:		8.69
				78.21
		LABOUR :		
		TO FOCUS HEADLAMP & CHECK WIRING FUNCTION		<i>nn</i> 55.00 <i>X</i>
		TO REPAIR, ALIGN & LABOUR TO REPLACE ABOVE PARTS		300.00 <i>1201</i>
		TO SPRAY PAINT ON FRT BUMPER USING 2K PAINT		400.00 <i>2501</i>
		TO RE-WRAP FRONT ANTI-STONECHIP STICKER		<i>5.14</i> 280.00 <i>2501</i>
		Labour Total S\$:		1,035.00

E. & O.E.

Total S\$: 1,113.21


 for LIM YEW BOO SPRAY PAINT CO.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

33 DECAL HUB
BLK 3024 UBI RD 3
#01-69 SC(08852)
9189 5083

Date 03.08.2019

M/S.

Cash

SMH91R

總計
Total

250.00

經手人 / Issue by