



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : SKR5419T
ACCIDENT DATE : 05-04-2019 08:30
THIRD PARTY REF. : GBE3819K

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SKR5419T HONDA VEZEL

QTY PARTS DESCRIPTION

1	1	FRONT FENDER RH
2	1	FRONT FENDER WHEEL ARCH GARNISH RH
3	1	FRONT BUMPER
4	10	FRONT BUMPER CLIP@S\$1.50
5	1	FRONT HEADLAMP RH

LESS 20 %
TOTAL (A)

DATE : 05-04-2019

*not Authorized
Kale works
9/4/19
The photo before painting
3 day.*

AMOUNT (SG\$)

<i>Body work</i>	580.00	—
<i>paint</i>	153.00	—
<i>De</i>	459.80	—
<i>men</i>	15.00	—
<i>17</i>	1820.00	X

3,027.80

605.56

2,422.24

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS
3	1	SPRAYPAINTING CHARGES

30.00 *20*

520.00 *300*

620.00 *400*

TOTAL (D)

1,170.00

ESTIMATE TOTAL

3,592.24

LKK Auto Consultants hence notify the Repairer of the following:

- To repair the damaged or spray painting
- To repair the damaged parts during resurvey
- To repair the damaged parts during confirmation
- To repair the damaged parts on a "without Prejudice" basis
- To repair the damaged parts on a "without Prejudice" basis
- To repair the damaged parts on a "without Prejudice" basis
- To repair the damaged parts on a "without Prejudice" basis

Acknowledged by Repairer
Signature: _____
Date: _____

*vehicle hasn't send in for repair
Submit p/p 61686-24*