



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TIMOTHY HIA YI LIANG
9 SHELFORD ROAD #03-05
SINGAPORE 288352

Attention : THE OWNER
Contact : 98287114

*Not Withheld
Clay 8?
Rear After Paint*

Estimate : ES006636

Date : 04/04/2019
Vehicle Num. : SKU5172M
Make/Model : VOLKSWAGEN SHARAN 2.0-2015
Chassis/Eng# : WVWZZZ7NZFV034627/CCZ481842
Accident Date : 30/03/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS :		
2.	1	REAR BUMPER	Bu	1,284.38 ✓
3.	1	REAR BUMPER SPONGE		199.60 ?
4.	1	REAR BUMPER REINFORCEMENT		862.90 ?
5.	6	REAR BUMPER CLIP	15.00	90.00 ✓
6.	1	REAR BUMPER SIDE RETAINER R/H	Di	84.73 ✓
7.	1	REAR BUMPER LOWER LIP		328.35 ✓
8.	1	REVERSE SENSOR	255.82	1,023.28 ?
		REAR END PANEL	R	866.10 X
Nett Total S\$:				4,739.34
10.00% Discount S\$:				473.93
				4,265.41
LABOUR :				
RUST PROOFING TREATMENT			rn	100.00 X
SPRAY PAINT DAMAGED AREA AFFECTED			300l	900.00
TO CUT OFF REAR END PANEL, KNOCK AND STRAIGHTEN REAR				
CHASSIS FRAME AND CHANGE ALL NECESSARY PARTS			400l	900.00
Labour Total S\$:				1,900.00

SingDollars : Six Thousand One Hundred Sixty-Five & Cents Forty-One Only

Total S\$: 6,165.41

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: