



# 簡福星摩多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6743 5344 Fax: (65) 6748 1006, 6281 8428

Branch: 1 Kaki Bukit Avenue 6 #01-13 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

E-mail: ryan@kanfs.net/ patricia@kanfs.net

AXA INSURANCE SINGAPORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

DATE: 5/9/2019

VEHICLE NO. : FBN4912U  
ACCIDENT DATE : 04-04-2019 07:50  
THIRD PARTY REF. : SHD501E

Supplementary.

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE FBN4912U HONDA AFS125MSF

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	AIR CLEANER COVER	CRA 55.00 ✓
2	1	REAR SIDE COWLING LH	DAM 90.00 ✓
3	1	BASKET	DAM 32.00 ✓
4	1	FRONT FENDER (BLACK)	CRA 50.00 ✓
			227.00
			LESS 10%
			22.70
			TOTAL (A)
			204.30
SPECIAL NETT ITEMS			
1	1	FRONT NUMBER PLATE	NN 15.00 X
			TOTAL (B)
			15.00
			SUPPLEMENTARY TOTAL
			219.30



# 簡福星摩多工廠

## KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 06-04-2019

VEHICLE NO. : FBN4912U

ACCIDENT DATE : 04-04-2019 07:50

THIRD PARTY REF. : SHD501E

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE FBN4912U HONDA AFS125MSF

*Not Allowed*  
*hla*  
*Elmer's Attorney*  
*3 dr.*  
*8/4/19*

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)	
1	1 — HORN COVER	CNE 68.00	
2	1 — FRONT FENDER	CNE 68.00	
3	2 — FRONT SIGNAL LAMP @\$48.00	BU 96.00	✓
4	2 — SIDE COWLING @\$85.00 LH	CNE 170.00	85
5	1 — HEAD LAMP	17 108.00	X
6	2 — FOOTREST BAR RUBBER \$10.00	2/5 20.00	P C SVC
7	1 — BRAKE LEVER	CUT 30.00	
8	1 — SIDE MIRROR	CUT 48.00	SVC
9	1 — FRONT FORK ASSY	DAM 250.00	✓
10	1 — UNDER BRACKET	CRA 260.00	✓
11	1 — STEERING CONE BEARING	DAM 65.00	✓
12	1 — FRONT FOOTREST BAR	30/ 78.00	X SVC
13	1 — FRONT BRAKE DISC	DAM 115.00	✓
14	1 — FRONT RIM ASSY	DD/ 240.00	
15	1 — FRONT RIM SHAFT	DAM 30.00	✓
16	1 — HEAD LAMP COVER	17 80.00	X SVC
17	1 — HANDLE END (RH)	CUT 30.00	✓
18	1 — BODY BRACKET	CRA 62.00	✓
		1,818.00	1399
	LESS 10 %	181.80	139.90
	TOTAL (A)	1,636.20	1259.10

### SPECIAL NETT ITEMS

1 1 TYRE *su* 180.00 ?



# 簡福星摩王廠

## KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : FBN4912U  
ACCIDENT DATE : 04-04-2019 07:50  
THIRD PARTY REF. : SHD501E

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
TOTAL ( C )			180.00
LABOUR CHARGES			
1	1	TO PRESS FORK ASSY	250.00 60
2	1	REMOVE ALL NECESSRAY AFFECTED PARTS FOR REPAIRS, WELD/CUT, PANEL BE- ATING & RENEW PARTS	250.00 200
3	1	SPRAY PAINTING	200.00 120
TOTAL ( D )			700.00
ESTIMATE TOTAL			2,516.20