

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: \$0/-
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: 92K.
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 05 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
 Person Contacted: _____

Veh No: SLT2015Y. Yr Regn: 2017 1 Oct.
 Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or

Make: Audi A3 Sedan. cc 999.
 Colour: Silver. A/C: Insured / Std / NI / NA
 Sp. Reading: 27729. T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: WAU228V7J1015248.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 205/55R16.

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. 06 mm		R/Bal. 06 mm	
L/Bal. 06 mm		L/Bal. 06 mm	
D.O.A.		D.O.I. 08/04/18 19	

Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front o/s.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

07 AIG

SLT 2015Y - CC3/A1G19006141/fn3

D.O.A. - 03/14/2019

08/04/19 @ 5.21 p.m. advised PA to AIG via messenger

08/04/19 @ 15.26 p.m. mandate request requested authorisation repair to AIG via messenger.

MV:

PV:

Nett:

RECEIVED 07 JUN 2019

02/06/19 Confirmed P/P \$10,607.52 @ 5 days with Adrian
 (\$12,422.48 Red - 54%)
 Resurvey No. of T/p - 1

Date/Time, File Pass to? Date/Time, File Return to?

1) 07.06/19

2) Typ 4

3) .

4)

5)

6)

7)

8)

9)

10)

11)

12)

13)

14)

15)

16)

17)

18)

19)

20)

21)

22)

23)

24)

25)

26)

27)

28)

29)

30)

31)

32)

33)

34)

35)

36)

37)

38)

39)

40)

41)

42)

43)

44)

45)

46)

47)

48)

49)

50)

51)

52)

53)

54)

55)

56)

57)

58)

59)

60)

61)

62)

63)

64)

65)

66)

67)

68)

69)

70)

71)

72)

73)

74)

75)

76)

77)

78)

79)

80)

81)

82)

83)

84)

85)

86)

87)

88)

89)

90)

91)

92)

93)

94)

95)

96)

97)

98)

99)

100)

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

700

11

211

Prel. Report:

Final Report: \$10,607.52 P/P

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	96271
Vehicle Details	
Vehicle No.:	SLT2015Y
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Apr 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	CHZ549608
Chassis No.:	WAUZZZ8V7J1015248
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,479.00
Original Registration Date:	21 Oct 2017
First Registration Date:	21 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$16,271.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Oct 2027
PARF Rebate Amount:	\$12,203.00
Intended COE Rebate Details	
COE Expiry Date:	20 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,761.00
COE Rebate Amount:	\$35,631.00
Total Rebate Amount:	\$47,834.00

The information contained herein is correct as at 08 Apr 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 7 June 2019 10:43 AM
To: 'Boo seng yak'
Cc: 'Adrian Ling'; 'SUR'; 'Carrine Leong'; 'jiayee.yap@premiumauto.com.sg'; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLT2015Y - OD AIG - SURVEYED 8 APR 19

Dear Mr Boo,

Confirmed final fig \$ 10,607.52 @ 5 days of repairs before excess \$ 0/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Monday, 13 May 2019 2:28 PM

To: Adrian Ling <adrianling@lkkauto.com>; shirleyHiew@lkkauto.com; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLT2015Y - OD AIG - SURVEYED 8 APR 19

Hi Adrian and all,

Revised estimate and photographs of damaged parts is attached

Please confirm repair cost of \$10,607.52 @ 5 days.

Your early closure is well appreciated.

Best regards - jib

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 18 April 2019 1:13 PM
To: glory.tan@premiumauto.com.sg; SUR
Cc: allan.wu@premiumauto.com.sg; 'Claims'; claims@premiumautocare.com.sg
Subject: RE: Supplementary item photos for SLT 2015 Y
Attachments: SUPPLEMENTARY.pdf

Hi Glory,

Supplementary approved by insurance.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: glory.tan@premiumauto.com.sg [mailto:glory.tan@premiumauto.com.sg]
Sent: Monday, 15 April 2019 3:40 PM
To: SUR <sur@lkkauto.com>
Cc: allan.wu@premiumauto.com.sg; 'Claims' <claims@premiumauto.com.sg>; claims@premiumautocare.com.sg
Subject: Supplementary item photos for SLT 2015 Y

Dear all,

Please refer to the attached for check items, supplementary item photos for SLT 2015 Y. Please revise and get it back to us.

Supplementary item,

1. Front bumper closing element-lower centre. (SGD 488)

Check Item number in marked estimate,

13. Wheel housing liner – RH. (SGD 158)
24. Bonnet lift cylinder – RH. (SGD 128)

Thank you.

Best Regard,

Glory Tan

Bodyworks Department

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 f. +65 6841 1183

e. glory.tan@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 10 April 2019 10:47 AM
To: 'Claims'
Cc: SUR
Subject: RE: OD CLAIM FOR SLT 2015 Y

Hi Sheila,

Excess update to \$ 0/-.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 10 April 2019 9:37 AM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>
Cc: 'SUR' <sur@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SLT 2015 Y

Hi Shirley ,

With regards to excess , the driver have provided additional details to prove she have more than 2 years driving license,

Please see attached document.

Kindly advise.

Thank you.

Best Regards,

Sheila M Ismail
Claims Advisor

Premium Automobiles Pte Ltd (Reg No: 199602271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 9 April 2019 2:56 PM
To: 'Claims Dept'
Cc: SUR
Subject: RE: OD CLAIM FOR SLT 2015 Y

Dear Kelvin,

As instructed by our client, please proceed to repair the insured vehicle **SLT 2015Y (Excess \$ 3,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Monday, 8 April 2019 1:59 PM
To: 'SUR' <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: OD CLAIM FOR SLT 2015 Y

Dear All,

Survey was done today by Adrian, Kindly assist to update repair approval.

Thank You.

Best Regards,

Kelvin Khoo
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SLT2015Y (32571787915G)**

OD

Apr 5 2019 12:00PM

[WEE CONGYOU]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 18/04/2019 11:20 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$12129.00) - SLT2015Y - Claim Handler: Mohd Zawaye, Norsazani

Approved:12129.00:Submit survey report in merimen. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLT2015Y (3257178791SG)**

OD

Apr 5 2019 12:00PM

[WEE CONGYOU]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 09/04/2019 14:36 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$11641.00) - SLT2015Y - Claim Handler: Mohd Zawaye, Norsazani

Approved:11641.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 16 Apr 2019

Preliminary Advice

Vehicle No	: SLT2015Y	Accident Date	: 05/04/2019
Make	: AUDI A3 SB	Policy No.	: 1700067995
Assignment Date	: 08/04/2019	Excess	: S\$0.00
Date of Inspection	: 08/04/2019	Est. Duration of Repair	: 5 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,030.00
Revised Amount	:S\$	12,129.00
Check Items (Estimated)	:S\$	1,035.00
Total	:S\$	13,164.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	47,834.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,166.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplementary amount is \$ 488.00.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 08 Apr 2019

Preliminary Advice

Vehicle No	: SLT2015Y	Accident Date	: 05/04/2019
Make	: AUDI A3 SB	Policy No.	: 1700067995
Assignment Date	: 08/04/2019	Excess	: S\$0.00
Date of Inspection	: 08/04/2019	Est. Duration of Repair	: 5 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,542.00
Revised Amount	:S\$	11,641.00
Check Items (Estimated)	:S\$	1,035.00
Total	:S\$	12,676.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	47,834.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,166.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/04/2019 21:13
 Date Of Accident 05/04/2019 12:50
 Exact Location Of Accident 315 OUTRAM ROAD05 S(169074) CARPARK
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLT2015Y
Insured/Policyholder
 Name Of Registered Owner WEE CONGYOU
 NRIC No S8109627I
 Email Address CONGYOU@HOTMAIL.COM
 Mobile Phone No (LOCAL) +65-97885930
 Alternative Phone No OTHERS-97885930

Vehicle Particulars

Manufacturer AUDI
 Model A3 SEDAN 1.0 TFSI S TRONIC
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? YES
 If No, Please state action to be taken
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 1700067995-01
 Cover Note Number

Driver

Name of Driver CHEONG SU MEI, DAWN
 NRIC No S8606446D
 Date Of Birth 12/02/1986
 Occupation INDOOR
 Date Of Driving Pass 12/05/2017
 Driving Experience 1 YEAR AND 10 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-85877175
 Fax Number
 Contact Number
 EMail Address DAWN.CHEONG@HOTMAIL.COM

Address	29 FLORA ROAD #06-02
Postcode	509742
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - FIANCEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

1)1B INDICATES ROUGHLY WHERE CAR WAS PARKED/1: MYCAR / 2: OTHER PARTY 2)QUICK HEADCHECK TO RIGHT, AS I WAS EXITING CARPARK LOT AND NEARING THE BROKEN YELLOW LINES AND DID NOT SEE ANY APPROACHING CARS. 3)DID NOT NOTICE ANY CAR TURNING FROM LANE A. 4)APPROX 5M BETWEEN LANE A AND B, BUT VIEW IS AT AN ANGLE 5)DID NOT EXPECT ANY CAR TO TURN FROM OPPOSITE SIDE LANES C/D/E AS THAT IS AGAINST TRAFFIC 6)OTHER DRIVER APPROACHED VERY FAST SPEED IN CARPARK AT ABOUT 20KM/H, TOO LATE TO STOP. -ONLY VIDEO RECORDING WAS A TRUNCATED COPY FROM OTHER DRIVER'S DASHBOARD CAM. -I REQUESTED EARLIER VIEW OF THE ONLY RECORDING BUT OTHER DRIVER HAS REFUSED TO PROVIDE. -OTHER DRIVER HAS ALSO REFUSED TO PROVIDE POST-COLLISION PHOTOS C DESPITE HAVING AGREED PRIOR TO MOVING THE CARS TO AN UNOBSTRUCTIVE LOCATION. 7)SUSPECT OTHER PARTY TURNED FROM LANE C AS THIS LANE I CANT REALLY SEE INTO, AND ALSO GIVEN THE TRAJECTORY OF HIS CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJE800M
Vehicle Make/Model/Colour	AUDI A4 SEDAN DARK GREY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MICHAEL WONG MING KWONG
NRIC/Passport Number	S7663985Z
Contact Number	91769996
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (A) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time

5/4/19, 1:30 PM
5/4/19


Driver's Signature
(If driver is not the policyholder)
Date & Time

5/4/19, 5:00 PM


Reporter's Signature
Name: Siti Maslita
NRIC/FIN No: S 891-2802

100

A hand-drawn diagram of a car's internal structure, specifically focusing on the engine compartment area. The diagram is labeled with various components and their locations. On the left side, there is a label 'Battery' with an arrow pointing to a rectangular box. To the right of the battery, there is a label 'Alternator' with an arrow pointing to a circular component. Above the alternator, there is a label 'Generator' with an arrow pointing to a component. The diagram also shows the 'Engine' and 'Radiator' area. The entire diagram is drawn on a grid background.

- 1) 2nd witness (pumpy) stated he saw people / a crowd / 25 people early
- 2) 2nd handback to admit no 1 with a gun, 13 and entering the border within 100m. And did not see approaching cars
- 3) Did not notice any car leaving Kings Lane A
- 4) Approx the 200 between Lane A and B, just used 10 or 15 or 20 people
- 5) Did not recall any car to turn a right opposite onto Lane C/D/E - no that it might happen
- 6) 2nd Officer drove off towards east side speed in context of about - 10km/h, no idea to stop
- 7) 2nd Officer was remaining was in front of the 1st Officer when 1st Officer challenged him
- 8) 1st Officer's evidence was of the only recording but after that was not a 1st Officer
- 9) 2nd Officer was also referred to provide post - follow Officer C despite having agreed prior to entering the area to not be involved in the case
- 10) 2nd Officer's evidence was that he saw a car with a gun, 13 and entering the border within 100m. And did not see approaching cars

After reviewing the foregoing information, we have determined that:

Signature	Printed Name	Printed Title
	David A. Hays	Director
	John D. Hays	Assistant Director
	John D. Hays	Assistant Director

Accident Photo



REPUBLIC OF SINGAPORE

License Number **S81096271**

Name

WEE CONGYOU
(HUANG CONGYOU)

Birth Date: **31 Mar 1981**

Valid Date: **02 Jan 2004**

001070636E




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S81096271**

Name

WEE CONGYOU
(HUANG CONGYOU)

黄琮右

Race
CHINESE

Date of birth **31-03-1981** Sex **M**

Country of birth
SINGAPORE




owner

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE **25 Mar 2002**

NP 426A

License No: **S81096271**



3484000

S81096271

NRIC No: **S81096271**

Date of issue
10-01-2004

35 AMBER ROAD #14-16
SINGAPORE 439945

NRIC No: **S81096271** Date: **09/08/2008** No: **6966379**




REPUBLIC OF SINGAPORE

License Number: **S8606446D**

Name: **CHEONG SU MEI, DAWN**
(ZHANG SHUMEI)

Birth Date: **12 Feb 1986**

Issue Date: **12 May 2017**

002683144J

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S8606446D**

Name: **CHEONG SU MEI, DAWN**
(ZHANG SHUMEI)
張 屬 美

Race: **CHINESE**

Date of birth: **12-02-1986**

Country/Place of birth: **SINGAPORE**

Sex: **F**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) with unladen weight $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of driver; and other motor vehicles without clutch pedals with unladen weight $\leq$ 2500kg 12 May 2017

NP 428A



5670209

5670209

S8606446D

Date of issue: **10-11-2016**

Address: **29 FLORA ROAD**
#06-02
SINGAPORE 509742



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : WEE CONGYOU (HUANG CONGYOU)
Period of Insurance : 21 Oct 2018 To 20 Oct 2019
Engine No. : CHZ549608
Chassis No. : WAUZZZ8V7J1015248

Vehicle No. : SLT2015Y
Policy No. : 1700067995-01
Endorsement No. :
Issued Date : 13 Sep 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$0 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

WEE CONGYOU (HUANG CONGYOU)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189) Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125264

PREMIUM LEASING -QKT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Janik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Daniel Lee

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0449/2019/KK
Date	:	7-Apr-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Wee Cong You
Address	:	29 Flora Road #06-02 Singapore 509742
Telephone	:	HP +65 97885930
Type of Claim	:	Own Damage Claims
Policy No.	:	1700067995-01
Vehicle No	:	SLT 2015 Y
Model Code	:	Audi A3 SEDAN 1.0 TFSI
Model / Year	:	Oct-17
Engine No	:	CHZ 549608
Chassis No	:	WAUZZZ8V7J1015248
Mileage	:	-
Date In	:	5-Apr-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	5-Apr-19
Place of Accident	:	315 OUTRAM ROAD 05(169074) CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 2015 Y

S/N	Nature of Jobs	Estimated Charges
1	To remove , check and reinstall front wire harness for headlight , horns , outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper , rhs front bumper , rhs front fender , bonnet and rhs headlight. Reorganize crash management components. Reinstall all parts removed.	\$ 2,700.00 1250.
3	To respray front bumper , bonnet and rhs front fender. ✓	\$ 2,500.00 1100.
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: <u>\$ 6,032.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 2015 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rehnd</i>	\$ 1,830.00	✓ 1464
2	FRONT BUMPER FIXING PARTS <i>21 m</i>	\$ 170.00	+
3	FRONT BUMPER GUIDE SECTION - RH <i>21 m</i>	\$ 35.00	✓ 27.52
4	FRONT BUMPER CLOSING ELEMENT - RH <i>21 m</i>	\$ 270.00	+
5	FRONT BUMPER TRIM COVER - RH <i>21 m</i>	\$ 148.00	+
6	WHEEL HOUSING LINER ADAPTER - RH <i>21 m</i>	\$ 34.00	+
7	AIR GUIDE GRILLE - RH <i>21 m</i>	\$ 171.00	+
8	FRONT FENDER - RH <i>Rehnd</i>	\$ 776.00	✓ 622
9	FRONT FENDER ATTACHMENT PARTS <i>21 m</i>	\$ 65.00	?
10	FRONT FENDER BRACKET - RH <i>21 m</i>	\$ 35.00	✓ 27.76
11	FRONT FENDER BRACE <i>21 m</i>	\$ 88.00	✓ 69.84
12	WHEEL HOUSING LINER SEAL - RH <i>21 m</i>	\$ 31.00	7 X
13	WHEEL HOUSING LINER - RH <i>21 m</i>	\$ 158.00	✓ 126
14	WHEEL HOUSING LINER ATTACHMENT PARTS <i>21 m</i>	\$ 81.00	? X
15	BONNET	\$ 2,898.00	+
16	BONNET ATTACHMENT PARTS	\$ 149.00	+
17	BONNET EDGE PROTECTION	\$ 25.00	+
18	BONNET STRIKER - RH	\$ 100.00	+
19	BONNET STRICKER - LH	\$ 100.00	+
20	FRONT LED HEADLIGHT - RH <i>cut</i>	\$ 5,029.00	✓ 4023.20
SUB TOTAL SPARE PARTS		\$ 12,193.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 2015 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	ELECTRONICS POWER MODULE	\$ 693.00	X
22	FRONT LED HEAT SINK - RH	\$ 666.00	X
23	LIGHT CONTROL UNIT	\$ 508.00	X
24	BONNET LIFT CYLINDER-LH/RH	\$ 128.00	X ✓ 102
25	FRONT BUMPER REINFORCEMENT BEAM	\$ 660.00	X
26	FOAM FILLER PIECE	\$ 172.00	X
27	FRONT BUMPER COVER	\$ 111.00	X
28	ALUMINIUM RIM	\$ 666.00	✓ 532.40
29	RUBBER VALVE	4 \$ 13.00	X
30	SUNDRIES	\$ 700.00	✓ 40.80
TOTAL SPARE PARTS		\$ 16,510.00	
TOTAL LABOUR CHARGES		\$ 6,032.00	
GRAND TOTAL		\$ 22,542.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

23030

22972

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 08/09/19. ✓
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorised, 0.5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/DD/0449/2019/KK 15-Apr-19 Kee Siang 1 of 1 SLT 2015 Y Audi A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	Front bumper Closing Element - Lower Centre <i>combined</i>	\$ 488.00	<i>✓ 390</i>
GRAND TOTAL		\$ 488.00	

For Premium Automobiles Pte Ltd

Adrian Ling
R.S.



Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0449/2019/KK
Date : 7-Apr-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
5 days - ok - jb - 13 MAY 19

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Wee Cong You
Address : 29 Flora Road
#06-02
Singapore 509742
Telephone : HP +65 97885930
Type of Claim : Own Damage Claims
Policy No. : 1700067995-01
Vehicle No : **SLT 2015 Y**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Oct-17
Engine No : CHZ 549608
Chassis No : WAUZZZ8V7J1015248
Mileage : -
Date In : 5-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Apr-19
Place of Accident : 315 OUTRAM ROAD 05(169074) CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 2015 Y

S/N	Nature of Jobs	Estimated Charges			
1	To remove , check and reinstall front wire harness for headlight , horns , outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00
2	To dismantle and renew front bumper , rhs front bumper , rhs front fender , bonnet and rhs headlight. Reorganize crash management components. Reinstall all parts removed.		\$ 2,700.00	\$	1,250.00
3	To respray front bumper , bonnet and rhs front fender.		\$ 2,500.00	\$	1,100.00
4	To renew rhs front rim and carry out wheel alignment.	S/N	\$ 280.00	\$	280.00
5	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,032.00	\$	3,182.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 2015 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - RH	\$ 35.00	\$ 27.52
4	FRONT BUMPER CLOSING ELEMENT - RH	\$ 270.00	
5	FRONT BUMPER TRIM COVER - RH	\$ 148.00	
6	WHEEL HOUSING LINER ADAPTER - RH	\$ 34.00	
7	AIR GUIDE GRILLE - RH	\$ 171.00	
8	FRONT FENDER - RH	\$ 776.00	\$ 622.00
9	FRONT FENDER ATTACHMENT PARTS	\$ 65.00	
10	FRONT FENDER BRACKET - RH	\$ 35.00	\$ 27.76
11	FRONT FENDER BRACE	\$ 88.00	\$ 69.84
12	WHEEL HOUSING LINER SEAL - RH	\$ 31.00	
13	WHEEL HOUSING LINER - RH	\$ 158.00	\$ 126.00
14	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 81.00	
15	BONNET	\$ 2,898.00	
16	BONNET ATTACHMENT PARTS	\$ 149.00	
17	BONNET EDGE PROTECTION	\$ 25.00	
18	BONNET STRIKER - RH	\$ 100.00	
19	BONNET STRICKER - LH	\$ 100.00	
20	FRONT LED HEADLIGHT - RH	\$ 5,029.00	\$ 4,023.20
	SUB TOTAL SPARE PARTS	\$ 12,193.00	\$ 6,360.32

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 2015 Y

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	6,360.32
21	ELECTRONICS POWER MODULE		\$ 693.00	
22	FRONT LED HEAT SINK - RH		\$ 666.00	
23	LIGHT CONTROL UNIT		\$ 508.00	
24	BONNET LIFT CYLINDER-LH/RH		\$ 128.00	\$ 102.00
25	FRONT BUMPER REINFORCEMENT BEAM		\$ 660.00	
26	FOAM FILLER PIECE		\$ 172.00	
27	FRONT BUMPER COVER		\$ 111.00	
28	ALUMINIUM RIM		\$ 666.00	\$ 532.40
29	RUBBER VALVE	4	\$ 13.00	
30	<i>Added parts - see attached</i>		\$ 488.00	\$ 390.00
31	SUNDRIES		\$ 700.00	\$ 40.80
TOTAL SPARE PARTS		:	\$ 16,510.00	\$ 7,425.52
TOTAL LABOUR CHARGES		:	\$ 6,032.00	\$ 3,182.00
GRAND TOTAL		:	\$ 22,542.00	\$ 10,607.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-VV

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0449/2019/KK

15-Apr-19

Kee Siang

1 of 1

SLT 2015 Y

Audi A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Front bumper Closing Element - Lower Centre	\$ 488.00	\$ 390.00
GRAND TOTAL		\$ 488.00	\$ 390.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLT 2015 Y

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0449/2019/MAS

7 June 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLT 2015 Y, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SLT 2015 Y**, claimant, **Mr. Wee Congyou**, please find the related document per attached.

1. A copy of the Original invoice no. 85013853 – S\$11,350.05
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLT 2015 Y

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119998
Main Telephone: 6836 2223
Main Telefax: 6475 3123

Alexandra Service Centre
281 Alexandra Road
Singapore 119998
Telephone: 6886 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408723

Customer Service
Service Appointment
Service Appointment
Service Appointment
Service Appointment
Service Appointment

6366 2223
6828 1233
customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 11:10

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013853 Date : 07/06/2019 Order : SLT2015Y Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLT2015Y (V 35443)	Regn Date: 21/10/2017	Mileage: 27734	WIP No.: 49120
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V7J1015240	Engine: CHZ 549608	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (137)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V0941774D	HEADLIGHT Less 020%	1.00	5029.00	4,023.20
X	A8V5821106A	(A)SK)FENDER 9/4/19 Less 020%	1.00	777.50	622.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6366 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6366 2223
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408791
Telephone: 6366 2127
Telefax: 6471 3733

Customer Service
Service Appointment
6366 2223
6366 2233
Your Breakdown Service
customers.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 11:10

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013853
Date : 07/06/2019
Order : SLT2015Y
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLT2015Y (V 35443)

Regn Date: 21/10/2017

Mileage: 27734

WIP No.: 49120

Model: A3 SEDAN 1.0 TFSI 8VMANG

Chassis: WAUZZZ8V7J1015248

Engine: CHZ 549608

Dept: U

USB No.:

You have been assisted by :- UB-Jiayee

(137)

		Details		Qty	Unit Price	Amount
X	A0V5821172	(SK)WHEEL HOUS	Less 020%	1.00	157.50	126.00
X	A0V58072338	PLATE	Less 020%	1.00	487.50	390.00
X	A0V5807065R GRU	COVER	Less 020%	1.00	1830.00	1,464.00
X	A0V0601025DC	(GER)RIM 16" CAE	Less 020%	1.00	665.50	532.40
X	A0V0821136A	SUPPORT	Less 020%	1.00	87.30	69.84
X	A0V5821468B	BRACKET	Less 020%	1.00	34.70	27.76
X	A0V5807184	GUIDE	Less 020%	1.00	34.40	27.52
X	A0V0955102B	CYLINDER	Less 020%	1.00	127.50	102.00
X	AN 0161857	POP-RIVET	Less 020%	5.00	3.00	12.00
X	AN 0161857	POP-RIVET	Less 020%	5.00	3.00	12.00
X	AN 0385012	RIVET	Less 020%	10.00	1.50	12.00
X	AN 91022001	NUT	Less 020%	4.00	1.50	4.80

Parts 7,425.52
Labour 0.00
Sublet 3,182.00
Menus 0.00
Lubricant 0.00

Sub-Total 10,607.52

7% GST 742.53

Grand Total 11,350.05



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLT 2015 Y

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0449/2019/K
18th April 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI 8V
Vehicle Chassis No. : WAUZZZ8V7J1015248
Vehicle Regn No. : **SLT 2015 Y**
Vehicle Mileage : 27729 KM
Vehicle Owner : Mr. Wee Congyou
Certificate No : 1700067995-01
Own Damage Excess : Waiver
Accident Date : 05/04/2019
Place : 315 Outram Road 05 (169074) Carpark
Repair Cost : \$ 11,350.05
WIP No. : 49120
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :

*final confirmation of
Pending repair case that was
not started
18/4/19*

CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : WEE CONGYOU (HUANG CONGYOU)
Period of Insurance : 21 Oct 2018 To 20 Oct 2019
Engine No. : CHZ549608
Chassis No. : WAUZZZ8V7J1015248

Vehicle No. : SLT2015Y
Policy No. : 1700067995-01
Endorsement No. :
Issued Date : 13 Sep 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$0 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

WEE CONGYOU (HUANG CONGYOU)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy in which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125264

PREMIUM LEASING -QKT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Darus Loo

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Apr 2019		08 Apr 2019 14:36 Edit Adj Rpt	\$10,607.52 Edit Estimates	\$10,607.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	WEE CONGYOU , ID: S81096271, Tel: +6599999999								
Vehicle Reg. No.:	SLT2015Y	Date of Loss:	05/04/2019 12:00 - :59 [17 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 3257178791SG	Policy/Cover Note No.:	1700067995 (Comprehensive)						
		Excess:	\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Lim, Sheng Yang] ShengYang.Lim@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/04/2019]								
Driver/Custodian:	CHEONG SU MEI, DAWN (33 / Female), NRIC: S8606446D, Tel: +6585877175 Email: DAWN.CHEONG@HOTMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (18/04/2019): Alert - Adj Mandate Approved (\$12129.00) - SLT2015Y - Claim Handler: Mohd Zaway... - AIG_SG (10/04/2019): SLT2015Y / OD / 05/04/2019 / Coverage & Excess update - AIG_SG (09/04/2019): Alert - Adj Mandate Approved (\$11641.00) - SLT2015Y - Claim Handler: Mohd Zaway... - AIG_SG (09/04/2019): SLT2015Y / OD / 05/04/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT2015Y (3257178791SG)
 OD
 Apr 5 2019 12:00PM
 [WEE CONGYOU]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		v	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)												Thumbnail		Print		
1	06/04/19 08:57	Video - Accident [Linked Accident Report Documents]												1	Load MP4			
Assessment Reports															1 per page		v	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	08/04/19 15:21	Adjuster Immediate Advice												1	Load HTM			
2	16/04/19 17:19	Adjuster Immediate Advice												1	Load HTM			
Photos/Images															3 per page		v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	08/04/19 15:25	General View												1	Load JPG	☒		
2	08/04/19 15:25	Chassis Number												1	Load JPG	☒		
3	08/04/19 15:25	General View												1	Load JPG	☒		
4	08/04/19 15:25	General View												1	Load JPG	☒		
5	08/04/19 15:25	General View												1	Load JPG	☒		
6	08/04/19 15:25	General View												1	Load JPG	☒		
7	08/04/19 15:25	General View												1	Load JPG	☒		
8	08/04/19 15:25	General View												1	Load JPG	☒		
9	08/04/19 15:25	General View												1	Load JPG	☒		
10	08/04/19 15:25	General View												1	Load JPG	☒		
11	08/04/19 15:25	General View												1	Load JPG	☒		
12	08/04/19 15:25	General View												1	Load JPG	☒		
13	08/04/19 15:25	General View												1	Load JPG	☒		
14	08/04/19 15:25	General View												1	Load JPG	☒		
15	08/04/19 15:25	General View												1	Load JPG	☒		
16	08/04/19 15:25	General View												1	Load JPG	☒		
17	08/04/19 15:25	General View												1	Load JPG	☒		
18	08/04/19 15:25	General View												1	Load JPG	☒		
19	08/04/19 15:25	General View												1	Load JPG	☒		
20	08/04/19 15:25	General View												1	Load JPG	☒		
21	08/04/19 15:25	General View												1	Load JPG	☒		
22	08/04/19 15:25	General View												1	Load JPG	☒		
23	16/04/19 17:20	Reinspection Photo												1	Load JPG	☒		
24	16/04/19 17:20	Reinspection Photo												1	Load JPG	☒		
25	16/04/19 17:20	Reinspection Photo												1	Load JPG	☒		
26	16/04/19 17:20	Reinspection Photo												1	Load JPG	☒		
27	16/04/19 17:20	Reinspection Photo												1	Load JPG	☒		
28	16/04/19 17:20	Reinspection Photo												1	Load JPG	☒		
Documentation															1 per page		v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	08/04/19 15:24	SLT 2015Y GIA.pdf	 Load PDF	
2	08/04/19 15:24	DRIVING & CI.pdf	 Load PDF	
3	08/04/19 15:24	ESTIMATE .pdf	 Load PDF	
4	10/04/19 13:34	SLT 2015 Y Dawn Cheong_VicRoads - Driver Licence Details.pdf	 Load PDF	
5	16/04/19 17:19	SUPPLEMENTARY.pdf	 Load PDF	
6	07/06/19 10:58	ESTIMATE & SUPP MARKED.pdf	 Load PDF	
7	27/06/19 17:35	Workshop Invoice	 Load PDF	
8	27/06/19 17:35	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/04/19 08:57	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/04/19 09:12	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	06/04/19 08:55	Accident Photo	 Load JPG	☒
2	06/04/19 08:55	Accident Photo	 Load JPG	☒
3	06/04/19 08:55	Accident Photo	 Load JPG	☒
4	06/04/19 08:55	Accident Photo	 Load JPG	☒
5	06/04/19 08:55	Accident Photo	 Load JPG	☒
6	06/04/19 08:55	Accident Photo	 Load JPG	☒
7	06/04/19 08:55	Accident Photo	 Load JPG	☒
8	06/04/19 08:55	Accident Photo	 Load JPG	☒
9	06/04/19 08:55	Accident Photo	 Load JPG	☒
10	06/04/19 08:55	Accident Photo	 Load JPG	☒
11	06/04/19 08:55	Accident Photo	 Load JPG	☒
12	06/04/19 08:55	Accident Photo	 Load JPG	☒
13	06/04/19 08:55	Accident Photo	 Load JPG	☒
14	06/04/19 08:55	Accident Photo	 Load JPG	☒
15	06/04/19 08:55	Accident Photo	 Load JPG	☒
16	06/04/19 08:55	Accident Photo	 Load JPG	☒
17	06/04/19 08:57	Accident Photo	 Load JPG	☒
18	06/04/19 08:57	Accident Photo	 Load JPG	☒
19	06/04/19 08:57	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/04/19 22:06	Sketch Plan	 Load JPG	☒
2	05/04/19 22:06	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19006141/ASD3E2

Date: 28/06/2019

REFERENCE

Insured/Claimant: WEE CONGYOU Policy No: 1700067995
Date of Loss: 05/04/2019 Nature of Claim: OD Claim No: 3257178791SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT2015Y
Make & Model: AUDI A3 SB, 1.4 (A) Engine No: CHZ549608
Reg. Date: 21/10/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V7J1015248
Colour: Silver Odometer: 27729 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$92,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,900.00	7,425.52	9,474.48	56.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,032.00	3,182.00	2,850.00	47.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	22,932.00	10,607.52	12,324.48	53.74
+ GST 7.00/7.00% (S\$)	1,605.24	742.53	862.71	53.74
Nett Amount (S\$)	24,537.24	11,350.05	13,187.19	53.74

INSPECTION

Date of Assignment: 08/04/2019
Date Inspected: 08/04/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1	*FRONT BUMPER GUIDE SECTION - RH	Damaged	35.00 FS	*27.52 FS
4	1	*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	270.00 FS	*- FS
5	1	*FRONT BUMPER TRIM COVER - RH	Not Necessary	148.00 FS	*- FS
6	1	*WHEEL HOUSING LINER ADAPTER - RH	Not Necessary	34.00 FS	*- FS
7	1	*AIR GUIDE GRILLE - RH	Not Necessary	171.00 FS	*- FS
8	1	*FRONT FENDER - RH	Distorted	776.00 FS	*622.00 FS
9	1	*FRONT FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
10	1	*FRONT FENDER BRACKET - RH	Bent	35.00 FS	*27.76 FS
11	1	*FRONT FENDER BRACE	Bent	88.00 FS	*69.84 FS
12	1	*WHEEL HOUSING LINER SEAL - RH	Not Necessary	31.00 FS	*- FS
13	1	*WHEEL HOUSING LINER - RH	Torn	158.00 FS	*126.00 FS
14	1	*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
15	1	*BONNET	Not Necessary	2,898.00 FS	*- FS
16	1	*BONNET ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
17	1	*BONNET EDGE PROTECTION	Not Necessary	25.00 FS	*- FS
18	1	*BONNET STRIKER - RH	Not Necessary	100.00 FS	*- FS
19	1	*BONNET STRICKER - LH	Not Necessary	100.00 FS	*- FS
20	1	*FRONT LED HEADLIGHT - RH	Cut	5,029.00 FS	*4,023.20 FS
21	1	*ELECTRONICS POWER MODULE	Not Necessary	693.00 FS	*- FS
22	1	*FRONT LED HEAT SINK - RH	Not Necessary	666.00 FS	*- FS
23	1	*LIGHT CONTROL UNIT	Not Necessary	508.00 FS	*- FS
24	1	*BONNET LIFT CYLINDER - LH / RH	Damaged	128.00 FS	*102.00 FS
25	1	*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	660.00 FS	*- FS
26	1	*FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
27	1	*FRONT BUMPER COVER	Not Necessary	111.00 FS	*- FS
28	1	*ALUMINIUM RIM	Cut	666.00 FS	*532.40 FS
29	4	*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
30	1	*SUNDRIES	Necessary	700.00 FS	*40.80 FS
31	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Cracked	390.00 FS	*390.00 FS
Total Parts (\$\$)				16,900.00	7,425.52

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. REORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	1,250.00
3	TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER	New	2,500.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,032.00	3,182.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >